							Lead Serv	vice Line Inver	itory Temp	late								
*Please enter information in the empty box next to each section	Water	System Nai	me		Stickne	ey .	System	ID Number:	IL03	13000	Current Inven	ntory Date:	4/15,	/2025				
*Please enter totals in the empty box next to each category	Total Servic	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722	Website link Inver		https://lead-service	e-line-inventory-1-novotn	y.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	t Line was	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	, , Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P)	EXAMPLES: Lead (L) Galvanized Requiring Replacemnt (GRR) Unknown (U) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.	
4112 RIDGELAND AVENUE	N/A	N	N	1925	1925	Visual Inspection	Unknown Not Lead (UNL)	Unknown (U) Unknown Not Lead (UNL) U	Unknown (U) Unknown Not Lead (UNL) L	L	column(s).	9/27/2024	N		Service Line was replaced.	2		100028
4034 SCOVILLE AVENUE 3933 SCOVILLE AVENUE	N/A N/A	N N	N N	1953 1955	1953 1955	Visual Inspection Visual Inspection	U U	U	L	L		9/27/2024	N N					100248 100325
3919 SCOVILLE AVENUE	N/A	N	N	1952	1952	Visual Inspection	U	U	L	L		9/27/2024	N					100329
4016 WESLEY AVENUE	N/A	N	N	1953	1953	Visual Inspection	U	U	L	L		9/27/2024	N					100487
4131 GROVE AVENUE	N/A	N	N	1953	1953	Visual Inspection	U	U	L	L		9/27/2024	N					100826
7133 40TH STREET	N/A	N	N	1956	1956	Visual Inspection	U	U	L	L		9/27/2024	N					101023
3942 GROVE AVENUE 7101 PERSHING ROAD	N/A N/A	N N	Y	1930 1909	1930 1909	Visual Inspection Visual Inspection	U U	U	L	L		9/27/2024	N N					101079 101170
7101 PERSHING ROAD 7105 PERSHING ROAD	N/A	N	N N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					101171
3920 WISCONSIN AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					101179
3924 WISCONSIN AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					101180
7101 LORRAINE TERRACE	N/A	N	N	1949	1949	Visual Inspection	U	U	L	L		9/27/2024	N					101183
7033 LORRAINE TERRACE 7029 LORRAINE TERRACE	N/A	N N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N N					101189
3916 WENONAH AVENUE	N/A N/A	N N	N N	1948 1948	1948 1948	Visual Inspection Visual Inspection	U	U	L L	L		9/27/2024 9/27/2024	N N					101190 101203
3912 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					101204
7032 LORRAINE TERRACE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					101218
4228 HOME AVENUE	N/A	N	N	1925	1925	Visual Inspection	U	U	L	L		9/27/2024	N					101315
4228 CLINTON AVENUE 4207 CLINTON AVENUE	N/A N/A	N N	Y	1954 1954	1954 1954	Visual Inspection	U	U	L	L		9/27/2024	N N					101346 101358
4336 WENONAH AVENUE	N/A N/A	N N	N N	1954	1954	Visual Inspection Visual Inspection	U	U	L	L		9/27/2024	N N					101358
6927 43RD STREET	N/A	N	N	1955	1955	Visual Inspection	U	U	L	L		9/27/2024	N					101516
4440 OAK PARK AVENUE	N/A	N	Υ	1959	1959	Visual Inspection	U	U	L	L		9/27/2024	N					101603
4440 CLINTON AVENUE	LA1C092	N	N	1951	1951	Visual Inspection	U	U	L	L		9/27/2024	N 					101686
4200 GUNDERSON AVENUE	N/A N/A	N N	N N	1953 1948	1953 1948	Visual Inspection	U	U	L	L		9/27/2024 9/27/2024	N N					101990
3909 WENONAH AVENUE 7028 LORRAINE TERRACE	N/A N/A	N N	N N	1948 1950	1948 1950	Visual Inspection Visual Inspection	U	U	L	L		9/27/2024	N N					102345 102370
7033 40TH PLACE	N/A	N	N	1916	1916	Visual Inspection	U	U	L	L		9/27/2024	N					102488
7036 LORRAINE TERRACE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					102517
7049 LORRAINE TERRACE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					102733
3933 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					102754
4346 GROVE AVENUE	N/A	N	N	1946	1946	Visual Inspection	U	U	L	L		9/27/2024	N 					103009
7029 PERSHING ROAD	N/A	N N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N N					103138
4338 GROVE AVENUE 3928 WISCONSIN AVENUE	N/A N/A	N N	N N	1947 1948	1947 1948	Visual Inspection Visual Inspection	U	U	L I	L		9/27/2024	N N					103199 103233

							Load Cor	vice Line Inve	aton, Tomp	lato								
*Please enter information in the empty				1				vice Line Inve				_						
box next to each section	Water	System Nar	me 		Stickne	ey	System	ID Number:		13000	Current Inver	ntory Date:	4/15	/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Gal Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.		Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Solder (C)	(C)	Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds,					Copper - Lead Solde (CLS)	r Copper - Lead Solder (CLS	Copper - Lead Solde (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If				Copper - No Lead Solder (C)		IF customer refused access to property,	
	Lead and Copper Sample site number is the 7 digit	Special Care Facilities, Hospitals,	,	What year was the	What year was the	How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		date waiver obtained by PWS or date PWS	
	number starting with "LP" or " LA". / If address is not a lead and	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	customer side service line	EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N).	notified of Lead Service Line. /	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		If Yes, that section of service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite		Leave blank if	
	,						Plastic - PVC, HDPE,	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in the appropriate	,			(0)		customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (F	Plastic - PVC, HDPE, PEX (P)		immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown (U)	Unknown (U) Unknown Not Lead						service Line was replaced.			
3925 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	Unknown Not Lead (UNL)	(UNL)			9/27/2024	N					103244
3909 WISCONSIN AVENUE	N/A	N	N	1949	1949	Visual Inspection	U	U	L	L		9/27/2024	N					103257
4406 WENONAH AVENUE	N/A	N	N	1954	1954	Visual Inspection	U	U	L	L		9/27/2024	N					103273
4137 GROVE AVENUE 3920 WENONAH AVENUE	N/A N/A	N N	N N	1930 1948	1930 1948	Visual Inspection Visual Inspection	U	U	L	L		9/27/2024 9/27/2024	N N					103280 103296
3913 WENONAH AVENUE	N/A	N	N	1949	1949	Visual Inspection	U	U	L	L		9/27/2024	N					103325
7109 PERSHING ROAD	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					103382
4031 HARLEM AVENUE 3917 WENONAH AVENUE	N/A N/A	N N	N N	1948 1948	1948	Visual Inspection Visual Inspection	U	U	L	L		9/27/2024 9/27/2024	N N					103404 103517
3925 WISCONSIN AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					103517
7021 LORRAINE TERRACE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					103538
4120 GUNDERSON AVENUE 7053 LORRAINE TERRACE	N/A N/A	N N	N N	1919 1948	1919 1948	Visual Inspection Visual Inspection	U	U	L	L		9/27/2024 9/27/2024	N N					103554 103562
3916 WISCONSIN AVENUE	N/A N/A	N N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					103562
7025 LORRAINE TERRACE	N/A	N	N	1954	1954	Visual Inspection	U	U	L	L		9/27/2024	N					103679
3905 WENONAH AVENUE	N/A	N N	N N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N N					103690
7041 LORRAINE TERRACE 7037 PERSHING ROAD	N/A N/A	N N	N N	1948 1948	1948 1948	Visual Inspection Visual Inspection	U	U	L	L		9/27/2024 9/27/2024	N N					103741 103743
3921 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					103961
3900 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					103974
3929 WENONAH AVENUE 3932 WISCONSIN AVENUE	N/A N/A	N N	N N	1948 1948	1948 1948	Visual Inspection Visual Inspection	U	U	L	L		9/27/2024 9/27/2024	N N					103980 103988
3901 WENONAH AVENUE	N/A	N	N	1949	1948	Visual Inspection	U	U	L	L		9/27/2024	N					104058
7041 PERSHING ROAD	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					104071
3936 EAST AVENUE 3913 WISCONSIN AVENUE	N/A N/A	N N	N N	1953 1948	1953 1948	Visual Inspection Visual Inspection	U	U	L	L		9/27/2024 9/27/2024	N N					104098 104224
3901 WISCONSIN AVENUE	N/A N/A	N N	N N	1948	1948	Visual Inspection Visual Inspection	U	U	L	L		9/27/2024	N					104224
3908 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					104304
7033 PERSHING ROAD	N/A	N N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N N					104373
3912 WISCONSIN AVENUE 7040 LORRAINE TERRACE	N/A N/A	N N	N N	1948 1949	1948 1949	Visual Inspection Visual Inspection	U	U	L	L		9/27/2024 9/27/2024	N N					104374 104398
3917 WISCONSIN AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					104424
7045 LORRAINE TERRACE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					104467
7037 LORRAINE TERRACE	N/A	N N	N N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N N					104469
3904 HOME AVENUE 4205 ELMWOOD AVENUE	N/A N/A	N N	N N	1947 1997	1947 1997	Visual Inspection Visual Inspection	C	C	C	L NL		9/27/2024 N/R	N N					104485 100052

							Lead Serv	vice Line Inver	ntory Temp	late								
*Please enter information in the empty box next to each section	Water	System Nai	me		Stickne	ey .		ID Number:		13000	Current Inven	ntory Date:	4/15/	/2025				
*Please enter totals in the empty box next to each category	Total Servic	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722	Website link Inver		https://lead-service	e-line-inventory-1-novotn	y.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	t Line was	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	Group Homes, Parks, Playgrounds Special Care Facilities, Hospitals Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead	EXAMPLES: Lead (L) Galvanized Requiring Replacemnt (GRR) Unknown (U) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4131 SCOVILLE AVENUE	N/A	N	N	1997	1997	Visual Inspection	С	Unknown Not Lead (UNL)	(UNL)	NL		N/R	N					100166
4133 SCOVILLE AVENUE	N/A	N	N	1996	1996	Visual Inspection	С	С	С	NL		N/R	N					100167
4114 EAST AVENUE	N/A	N	N	1992	1992	Visual Inspection	С	С	С	NL		N/R	N					100208
4201 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	С	С	С	NL		N/R	N					100209
4203 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	С	С	С	NL		N/R	N					100210
4205 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	С	С	С	NL		N/R	N					100211
4209 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	С	С	С	NL		N/R	N					100213
4211 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	С	С	С	NL		N/R	N					100214
4215 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	С	С	NL 		N/R	N					100216
4221 EAST AVENUE	N/A	N N	N	1956	1956	Visual Inspection	С	С	С	NL NI		N/R	N N					100219
4227 EAST AVENUE 4229 EAST AVENUE	N/A N/A	N N	N N	1956 1956	1956 1956	Visual Inspection	C C	C C	С	NL NL		N/R N/R	N N					100222
4229 EAST AVENUE	N/A N/A	N N	N N	1956	1956	Visual Inspection Visual Inspection	C	C	C	NI NI		N/R	N N					100223
4231 EAST AVENUE	N/A	N	N	1930	1930	Visual Inspection	C	C	C	NL NL		N/R	N N					100227
4004 GUNDERSON AVENUE	N/A	N	N	2023	2023	Installation Record	С	С	С	NL NL		N/R	N N					100289
4024 ELMWOOD AVENUE	N/A	N	N	1997	1997	Visual Inspection	С	С	С	NL NL		N/R	N					100349
4103 MAPLE AVENUE	N/A	N	N	1995	1995	Visual Inspection	С	С	С	NL		N/R	N					100656
7132 40TH PLACE	N/A	N	N	1990	1990	Visual Inspection	С	С	С	NL		N/R	N					101021
7117 40TH STREET	N/A	N	N	1993	1993	Visual Inspection	С	С	С	NL		N/R	N					101029
4207 1/2 WISCONSIN AVENUE	N/A	N	N	1993	1993	Visual Inspection	С	С	С	NL		N/R	N					101267
4229 HOME AVENUE	N/A	N	N	1994	1994	Visual Inspection	С	С	С	NL		N/R	N					101335
4300 KENILWORTH AVENUE.	N/A	N	N	1993	1993	Visual Inspection	С	С	С	NL 		N/R	N					101540
4428 CLINTON AVENUE	N/A	N	N N	1990	1990	Visual Inspection	С	С	С	NL NI		N/R	N N					101682
4411 MAPLE AVENUE 4422 MAPLE AVENUE	N/A N/A	N	N N	2006 1956	2006 1956	Visual Inspection Visual Inspection	С	С	С	NL NI		N/R N/R	N N					101751 101760
4222 MAPLE AVENUE 4208 SCOVILLE AVENUE	N/A N/A	N N	N N	2000	2000	Visual Inspection Visual Inspection	C	C	C	NL NL		N/R	N N					102036
4034 CLINTON AVENUE	N/A N/A	N	N N	2000	2000	Visual Inspection	С	C	С	NL NL		N/R	N N					102036
4100 EAST AVENUE	N/A	N	N	1994	1994	Visual Inspection	С	C	С	NL NL		N/R	N N					102202
4228 RIDGELAND AVENUE	N/A	N	N	1999	1999	Visual Inspection	С	С	С	NL NL		N/R	N					102292
4129 1/2 WISCONSIN AVENUE	N/A	N	N	2002	2002	Visual Inspection	C	С	С	NL		N/R	N					102300
4325 HOME AVENUE	N/A	N	N	1993	1993	Visual Inspection	С	С	С	NL		N/R	N					102336
4207 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	С	С	С	NL		N/R	N					102482
4217 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	С	С	С	NL		N/R	N					102581
4213 GUNDERSON AVENUE	N/A	N	N	2003	2003	Visual Inspection	С	С	С	NL		N/R	N					102628
4411 WISCONSIN AVENUE	N/A	N	N	2006	2006	Visual Inspection	С	С	С	NL		N/R	N					102685
4209 GUNDERSON AVENUE	N/A	N	N	2005	2005	Visual Inspection	С	С	С	NL		N/R	N					102693

*Please enter information in the empty box next to each section *Please enter totals in the empty box next to each category	Water S	System Nar	me						tory Temp	iate								
• •	Total Service				Stickne	ey	System	ID Number:	IL03:	13000	Current Inven	itory Date:	4/15/	/2025				
		e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722	Website link Inven		https://lead-service	e-line-inventory-1-novotny	v.hub.arcgis.com/	
Service Address	ad and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	t Line was	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
sit nu or If a	ead and Copper Sample ite number is the 7 digit umber starting with "LP" or" LA". / address is not a lead and copper sample site mark "N/A"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized (Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacemnt (GRR) Unknown (U) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4036 OAK PARK AVENUE	N/A	N	N	1998	1998	Visual Inspection	С	С	С	NL		N/R	N					102722
4223 ELMWOOD AVENUE	N/A	N	N	1994	1994	Visual Inspection	С	С	С	NL		N/R	N					102732
4018 OAK PARK AVENUE	N/A	N N	N N	1993	1993	Visual Inspection	С	С	С	NL NL		N/R N/R	N N					102734
7015 40TH STREET 4439 WENONAH	N/A N/A	N N	N N	2005 1995	2005 1995	Visual Inspection Visual Inspection	C	С	C	NL NL		N/R N/R	N N					102797 102822
4431 WISCONSIN AVENUE	N/A N/A	N N	N N	2007	2007	Visual Inspection	C	C	C	NL NL		N/R	N N					102822
4033 OAK PARK AVENUE	N/A	N	N	2002	2002	Visual Inspection	C	C	C	NL NL		N/R	N					102899
4243 ELMWOOD AVENUE	N/A	N	N	2006	2006	Visual Inspection	C	C	C	NL NL		N/R	N N					102907
4018 CLINTON AVENUE	N/A	N	N	2006	2006	Visual Inspection	С	С	С	NL		N/R	N					102945
4232 RIDGELAND AVENUE.	N/A	N	N	2006	2006	Visual Inspection	С	С	С	NL		N/R	N					102974
4234 S RIDGELAND AVENUE	N/A	N	N	2005	2005	Visual Inspection	С	С	С	NL		N/R	N					103013
4327 WENONAH AVENUE	N/A	N	N	2002	2002	Visual Inspection	С	С	С	NL		N/R	N					103025
4223 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	С	С	С	NL		N/R	N					103108
4213 EAST AVENUE	N/A	N	N	1957	1957	Visual Inspection	С	С	С	NL		N/R	N					103163
4022 OAK PARK AVENUE	N/A	N	N	1997	1997	Visual Inspection	С	С	С	NL		N/R	N					103206
4024 OAK PARK AVENUE	N/A	N	N	1997	1997	Visual Inspection	С	С	С	NL		N/R	N					103214
4225 EAST AVENUE	N/A	N	N 	1956	1956	Visual Inspection	С	C	С	NL		N/R	N 					103307
6915 43RD STREET	N/A	N	N N	2007	2007	Visual Inspection	С	С	С	NL NI		N/R	N N					103320
4029 EUCLID AVENUE 7132 41ST STREET	LA1CO51; LA1CO47 N/A	N N	N N	2011 1994	2011 1994	Visual Inspection Visual Inspection	С	C C	C C	NL NL		N/R N/R	N N					103330 103332
4233 EAST AVENUE	N/A	N	N N	1956	1956	Visual Inspection	С	С	С	NL NL		N/R	N					103332
4037 HOME AVENUE	N/A	N	N	1997	1997	Visual Inspection	С	С	С	NL NL		N/R	N					103355
6518 41ST STREET	N/A	N	N	2000	2000	Visual Inspection	С	С	С	NL		N/R	N					103369
7008 40TH PLACE	N/A	N	N	1993	1993	Visual Inspection	С	С	С	NL		N/R	N					103425
4104 EAST AVENUE	N/A	N	N			Visual Inspection	С	С	С	NL		N/R	N					103431
4028 EAST AVENUE.	N/A	N	N	1990	1990	Visual Inspection	С	С	С	NL		N/R	N					103454
4220 RIDGELAND AVENUE	N/A	N	N	2009	2009	Visual Inspection	С	С	С	NL		N/R	N					103464
4031 OAK PARK AVENUE	N/A	N	N	2002	2002	Visual Inspection	С	С	С	NL		N/R	N					103539
4026 S OAK PARK AVENUE	N/A	N	N	2000	2000	Visual Inspection	С	С	С	NL		N/R	N					103541
4235 EAST AVENUE	N/A	N	N	1961	1961	Visual Inspection	С	С	С	NL		N/R	N					103583
4108 EAST AVENUE	N/A	N	N	1993	1993	Visual Inspection	C	C	C	NL		N/R	N					103593
4205 HARLEM AVENUE	N/A	N	N N	1996	1996	Visual Inspection	С	С	С	NL NI		N/R	N N					103603
4215 CLINTON AVENUE	N/A	N N	N N	2009	2009	Visual Inspection	С	С	С	NL NI		N/R	N N					103650
4022 EAST AVENUE 4029 OAK PARK AVENUE	N/A N/A	IN N	N N	2005	2005	Visual Inspection Visual Inspection	С	С	C	NL NL		N/R N/R	N N					103665 103676
7134 41ST STREET	N/A N/A	N	N N	2002	2002	Visual Inspection Visual Inspection	C	C	C	NL NL		N/R N/R	N N					103676

							Lead Ser	vice Line Inver	ntory Temp	late								
*Please enter information in the empty box next to each section	Water	System Na	me		Stickne	ξ λ		ID Number:		13000	Current Inven	ntory Date:	4/15,	/2025				
*Please enter totals in the empty box next to each category	Total Servic	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		c to Material ntory:	https://lead-service	e-line-inventory-1-novotn	y.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	: Is this a high-risk Facility or Area?	Identified Since Last	t Line was	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". / If address is not a lead and copper sample site mark "N/A"	Group Homes, Parks, Playgrounds Special Care Facilities, Hospitals Clinics, Child Care Facilities	5, 5, Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead	EXAMPLES: Lead (L) Galvanized Requiring Replacemnt (GRR) Unknown (U) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
7110 40TH PLACE	N/A	N	N	1999	1999	Visual Inspection	С	Unknown Not Lead (UNL)	(UNL)	NL		N/R	N					103711
7134 W 43RD STREET	N/A	N	N	2009	2009	Visual Inspection	С	С	С	NL		N/R	N					103725
6436 41ST STREET	N/A	N	N	2005	2005	Visual Inspection	С	С	С	NL		N/R	N					103734
4030 OAK PARK AVENUE	N/A	N	N	2000	2000	Visual Inspection	С	С	С	NL		N/R	N					103778
4421 WISCONSIN AVENUE	N/A	N N	N N	2017	2017	Visual Inspection	С	С	C	NL		N/R	N N					103795
4237 ELMWOOD AVENUE 4020 EAST AVENUE	N/A N/A	N N	N N	1990 2014	1990 2014	Visual Inspection Visual Inspection	C	С	С	NL NL		N/R N/R	N N					103813 103843
4019 CLINTON AVENUE	N/A N/A	N	N	1999	1999	Visual Inspection Visual Inspection	C	C	C	NL NL		N/R	N N					103845
4323 HOME AVENUE	N/A	N	N	1993	1993	Visual Inspection	С	С	С	NL		N/R	N					103962
4352 GROVE AVENUE	N/A	N	N	2005	2005	Visual Inspection	С	С	С	NL		N/R	N					103981
4116 GUNDERSON AVENUE	N/A	N	N			Visual Inspection	С	С	С	NL		N/R	N					104039
6439 41ST STREET	N/A	N	N	1997	1997	Visual Inspection	С	С	С	NL		N/R	N					104070
4400 WISCONSIN AVENUE	N/A	N	N	2017	2017	Visual Inspection	С	С	С	NL		N/R	N					104092
4206 S GUNDERSON AVENUE	N/A N/A	N N	N N	2017	2017	Visual Inspection	С	С	С	NL NL		N/R N/R	N N					104107
4208 S GUNDERSON AVENUE 4040 CLINTON AVENUE	N/A N/A	N N	N N	2017	2017	Visual Inspection Visual Inspection	C	C	C	NL NL		N/R N/R	N N					104126 104160
4035 CLARENCE AVENUE	N/A	N	N	2016	2018	Visual Inspection	С	С	С	NL NL		N/R	N					104178
4122 MAPLE AVENUE	N/A	N	N	2006	2006	Visual Inspection	С	С	С	NL		N/R	N					104188
4133 HOME AVENUE	N/A	N	N	2022	2022	Visual Inspection	С	С	С	NL		N/R	N					104209
4325 WENONAH AVENUE	N/A	N	N	2004	2004	Visual Inspection	С	С	С	NL		N/R	N					104277
4211 CLINTON AVENUE	N/A N/A	N N	N N	2020	2020	Visual Inspection	С	С	С	NL NI		N/R N/R	N N					104278
4403 WISCONSIN AVENUE 4401 WISCONSIN AVENUE	N/A N/A	N N	N N	2022	2022	Visual Inspection Visual Inspection	C	C	C	NL NL		N/R N/R	N N					104319 104330
4018 EAST AVENUE	N/A	N	N	2010	2010	Visual Inspection	С	С	С	NL		N/R	N					104334
4219 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	С	С	С	NL		N/R	N					104340
4111 1/2 ELMWOOD AVE	N/A	N	N	1990	1990	Visual Inspection	С	С	С	NL		N/R	N					104341
4038 CLINTON AVENUE	N/A	N	N	2000	2000	Visual Inspection	С	С	С	NL		N/R	N					104353
3921 CLARENCE AVENUE	N/A	N	N N	2008	2008	Visual Inspection	С	С	С	NL NL		N/R	N N					104369
4203 CLINTON AVENUE 4207 HARLEM AVENUE.	N/A N/A	N N	N N	2023 1997	2023 1997	Visual Inspection Visual Inspection	C	С	C	NL NL		N/R N/R	N N					104389 104413
4237 GROVE AVENUE	N/A	N	N	2017	2017	Visual Inspection	С	С	С	NL NL		N/R	N					104441
4131 S HOME AVENUE	N/A	N	N	2020	2020	Visual Inspection	С	С	С	NL		N/R	N					104446
6609 41ST STREET	LP1A014	N	N	1993	1993	Visual Inspection	С	С	С	NL		N/R	N					104452
4103 S WISCONSIN AVENUE.	N/A	N	N	2015	2015	Visual Inspection	С	С	С	NL		N/R	N					104453
4110 EAST AVENUE	N/A	N	N	1992	1992	Visual Inspection	С	С	С	NL		N/R	N					104462
3930 GROVE AVENUE	N/A	N	N	2008	2008	Visual Inspection	С	С	C	NL		N/R	N				1	104481

Lea site num or "	Total Service		1904 Service Line Newly	Year PWS-Owned Service Line was Installed What year was the PWS-Owned Service line		Total Non-Lead: Source of Information Used for Service Line Identification	System 111 Gooseneck/	PWS-Owned Service Line Material EXAMPLES: Copper - No Lead Solder (C)	IL03 vanized	Classification for Entire Serivice Line EXAMPLES: Lead (L)	Current Inven Total Unknown: Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	4/15/ Website link Inver Was a Lead Service Line Previously Replaced at this Location?	to Material	https://lead-service Material of Service Line Replacement EXAMPLES:	Has the customer refused access to the property?	hub.arcgis.com/ Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
*Please enter totals in the empty box next to each category Service Address Lead site num or "	and Copper Sample is site number.	Is this a high-risk Facility or Area? EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care	1904 Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Total Non-Lead:	Gooseneck/ Pigtail EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder	Total Galv Requiring rep PWS-Owned Service Line Material EXAMPLES: Copper- No Lead Solder	Customer Side Service Line Material EXAMPLES: Copper - No Lead	Classification for Entire Serivice Line	Total Unknown: Was Galvanized Service Line Material ever downstream of	1722 Date Customer Notified of Lead	Website link Inver	to Material atory:	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access	. Water Account Number
Service Address Lead Lead site num or "	ead and Copper Sample Is site number. Fraction of the starting with "LP" to LA". / didress is not a lead and opper sample site mark	Is this a high-risk Facility or Area? EXAMPLES: Group Homes, Parks, Playgrounds, Special Care acilities, Hospitals, Clinics, Child Care	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used	Gooseneck/ Pigtail EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder	PWS-Owned Service Line Material EXAMPLES: Copper - No Lead Solder	Customer Side Service Line Material EXAMPLES: Copper - No Lead	Classification for Entire Serivice Line EXAMPLES:	Unknown: Was Galvanized Service Line Material ever downstream of	Date Customer Notified of Lead	Inver	Date Lead Service Line	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access	Water Account Number
Lea site num or "	ead and Copper Sample the number is the 7 digit mber starting with "LP" " LA". / widdress is not a lead and topper sample site mark	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care	Identified Since Last Submitted Inventory	Owned Service Line was Installed What year was the PWS-Owned service line	Side Service Line was Installed		EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder	Line Material EXAMPLES: Copper - No Lead Solder	Service Line Material EXAMPLES: Copper - No Lead	Entire Serivice Line EXAMPLES:	Service Line Material ever downstream of	Notified of Lead	Previously Replaced at		Replacement	refused access to the	or IDPH notification, if customer refused access	Water Account Number
Lea site num or "	ead and Copper Sample the number is the 7 digit mber starting with "LP" " LA". / widdress is not a lead and topper sample site mark	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care	Identified Since Last Submitted Inventory	Owned Service Line was Installed What year was the PWS-Owned service line	Side Service Line was Installed		EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder	Line Material EXAMPLES: Copper - No Lead Solder	Service Line Material EXAMPLES: Copper - No Lead	Entire Serivice Line EXAMPLES:	Service Line Material ever downstream of	Notified of Lead	Previously Replaced at		Replacement	refused access to the	or IDPH notification, if customer refused access	Water Account Number
site num or "	ead and Copper Sample te number is the 7 digit mber starting with "LP" " LA". / Iddress is not a lead and opper sample site mark	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care	Yes (Y) or No (N)	PWS-Owned service line			Copper - No Lead Solder (C)	Copper - No Lead Solder	Copper - No Lead						EXAMPLES:			
site num or "	ead and Copper Sample te number is the 7 digit mber starting with "LP" " LA". / Iddress is not a lead and opper sample site mark	Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care	Yes (Y) or No (N)	PWS-Owned service line			Copper - Lead Solder	(C)	Solder (C)									
site num or "	ead and Copper Sample te number is the 7 digit mber starting with "LP" " LA". / Iddress is not a lead and opper sample site mark	Special Care Facilities, Hospitals, Clinics, Child Care	Yes (Y) or No (N)	PWS-Owned service line			(CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder	Galvanized Requiring	If any galvanized service line material was ever downstream of a Lead				Copper - No Lead Solder (C)			
num or "	mber starting with "LP" " LA". / Iddress is not a lead and opper sample site mark	Clinics, Child Care	Yes (Y) or No (N)	PWS-Owned service line		How was the Material of this	Galvanized (G)	Galvanized (G)	(CLS) Galvanized (G)	Replacemnt (GRR) Unknown (U)	section, mark Yes (Y). If the galvanized service line material was never	Enter date		If previous column was	Galvanized (G)		IF customer refused access to property, date waiver obtained	
If ad-	opper sample site mark				customer side service line	Service Line Identified? EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring	Non-Lead (NL)	downstream of any Lead section, mark No (N).	customer was notified of Lead Service Line.	Yes (Y) or No (N)	marked (Y), provide date the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver.	
				installed, if known?		Survey Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Replacemnt (GRR) Lead (L)		If Yes, that section of service line should be marked as Galvanized	/ If Service Line is not Lead put N/R		/ Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		/ Leave blank if	
							Plastic - PVC, HDPE, PEX (P) Unknown (U)	Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P	Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE,		Requiring Replacement in the appropriate immediately preceding						customer has not refused access.	
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	PEX (P) Unknown (U)		column(s).				Leave blank if no Lead Service Line was replaced.			
							(One)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4035 HOME AVENUE	N/A	N	N	2023	2023	Visual Inspection	С	С	С	NL		N/R	N					104483
4236 SCOVILLE AVENUE 4238 RIDGELAND AVENUE	N/A N/A	N N	N N	2023 1971	2023 1971	Visual Inspection	C	C U	C	NL U		N/R	N N					104489 100001
4222 RIDGELAND AVENUE	N/A	N N	N N	1940	1940		U	U	U	U			N N					100001
4214 RIDGELAND AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					100012
4206 RIDGELAND AVENUE	N/A	N	N	1942	1942		U	U	U	U			N					100015
4132 RIDGELAND AVENUE 4114 RIDGELAND AVENUE	N/A N/A	N N	N N	1955 1931	1955 1931		U	U	U	U			N N					100022 100027
6407 41ST STREET	N/A	N	N	1953	1953		U	U	U	U			N					100027
6417 41ST STREET	N/A	N	N	1953	1953		U	U	U	U			N					100036
4121 ELMWOOD AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					100041
4125 ELMWOOD AVENUE 4129 ELMWOOD AVENUE	N/A N/A	N N	N N	1953 1953	1953 1953		U	U	U II	U			N N					100042
4133 ELMWOOD AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					100044
4213 ELMWOOD AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					100054
4217 ELMWOOD AVENUE	N/A	N	N	1951	1951		U	U	U	U			N N					100055
4235 ELMWOOD AVENUE 4236 ELMWOOD AVENUE	N/A N/A	N N	N N	1935	1935		U	U	U	U			N N					100061 100067
4220 ELMWOOD AVENUE	N/A	N	N	1950	1950		U	U	U	U			N					100073
4216 ELMWOOD AVENUE	N/A	N	N	1970	1970		U	U	U	U			N					100075
4214 ELMWOOD AVENUE 4210 ELMWOOD AVENUE	N/A N/A	N N	N N	1920 1957	1920 1957		U	U	U	U			N N					100076 100077
4210 ELMWOOD AVENUE 4204 ELMWOOD AVENUE	N/A N/A	N N	N N	1957	1957		U	U	U	U			N N					100077
4202 ELMWOOD AVENUE	N/A	N	N	1914	1914		U	U	U	U			N					100080
4134 ELMWOOD AVENUE	N/A	N	N	1960	1960		U	U	U	U			N					100086
4132 ELMWOOD AVENUE 4112 ELMWOOD AVENUE	N/A N/A	N N	N N	1977 1953	1977 1953		U	U	U	U			N N					100087 100093
4133 GUNDERSON AVENUE	N/A N/A	N	N	1952	1953		U	U	U	U			N					100093
4205 GUNDERSON AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					100114
4225 GUNDERSON AVENUE	N/A	N	N 	1953	1953		U	U	U	U			N					100118
4231 GUNDERSON AVENUE 4241 GUNDERSON AVENUE	N/A N/A	N N	N N	1955 1952	1955 1952		U	U	U	U			N N					100120 100123
4238 GUNDERSON AVENUE	N/A N/A	N	N	1958	1958		U	U	U	U			N					100123
4236 GUNDERSON AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					100129
4234 GUNDERSON AVENUE 4230 GUNDERSON AVENUE	N/A N/A	N N	N N	1950 1962	1950 1962		U	U	U	U			N N					100130 100131

							Load Cor	vice Line Inves	tory Tomp	lata								
*Please enter information in the empty								vice Line Inver										
box next to each section	Water	System Nar	ne		Stickne	ey .	System	ID Number:	IL03	13000	Current Inver	ntory Date:	4/15	/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	/.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Solder (C)	(C)	Solder (C)	Lead (L)	If any galvanized service line material was ever				Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds,					Copper - Lead Solde (CLS)	Copper - Lead Solder (CLS	Copper - Lead Solde (CLS)	r Galvanized Requiring Replacemnt (GRR)	downstream of a Lead section, mark Yes (Y). If						IF customer refused access to property,	
	Lead and Copper Sample site number is the 7 digit	Special Care Facilities, Hospitals, Clinics, Child Care		What year was the	What year was the	How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never downstream of any Lead	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		date waiver obtained by PWS or date PWS	
	number starting with "LP" or " LA". / If address is not a lead and	Facilities	Yes (Y) or No (N)	PWS-Owned service line	customer side service line	EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	section, mark No (N). /	notified of Lead Service Line. /	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		If Yes, that section of service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if	
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in the appropriate				(3)		customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (P	Plastic - PVC, HDPE, PEX (P)		immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown (U) Unknown Not Lead (UNL)	Unknown (U) Unknown Not Lead									
4226 GUNDERSON AVENUE	N/A	N	N	1930	1930		U	U	(UNL) U	U			N					100133
4204 GUNDERSON AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					100139
4140 GUNDERSON AVENUE 4118 1/2 GUNDERSON AVE	N/A N/A	N N	N N	1956 1964	1956 1964		U	U	U	U			N N					100145 100151
6519 41ST STREET	N/A	N	N	1924	1924		U	U	U	U			N					100159
4215 SCOVILLE AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					100177
4217 SCOVILLE AVENUE 4223 SCOVILLE AVENUE	N/A N/A	N N	N N	1956 1963	1956 1963		U	U	U	U			N N					100178 100180
4227 SCOVILLE AVENUE	N/A	N	N	1926	1926		U	U	U	U			N					100182
4229 SCOVILLE AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					100183
4218 SCOVILLE AVENUE 4214 SCOVILLE AVENUE	N/A N/A	N N	N N	1974 1964	1974 1964		U	U	U	U			N N					100198 100200
4200 SCOVILLE AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					100203
3916 SCOVILLE AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					100230
3926 SCOVILLE AVENUE 4000 SCOVILLE AVENUE	N/A N/A	N N	N N	1952 1974	1952 1974		U	U	U	U			N N					100232 100238
4000 SCOVILLE AVENUE	N/A N/A	N N	N N	1974	1974		U	U	U	U			N N					100238
4022 SCOVILLE AVENUE	N/A	N	N	1925	1925		U	U	U	U			N					100245
4024 SCOVILLE AVENUE	N/A	N N	N	1950	1950		U	U	U	U			N N					100246
6522 41ST STREET 6528 41ST STREET	N/A N/A	N N	N N	1955 1955	1955 1955		U	U	U	U			N N					100249 100252
6532 41ST STREET	N/A	N	N	1955	1955		U	U	U	U			N					100253
6540 41ST STREET	N/A	N	N	1954	1954		U	U	U	U			N					100255
4025 EAST AVENUE 3943 EAST AVENUE	N/A N/A	N N	N N	1926 1926	1926 1926		U	U	U	U			N N					100258 100267
3925 EAST AVENUE	N/A	N	N	1940	1940		U	U	U	U			N					100277
3919 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	U	U	С	U			N					100274
3913 EAST AVENUE 3912 GUNDERSON AVENUE	N/A N/A	N N	N N	1962 1931	1962 1931		U	U	U	U			N N					100277 100278
3920 GUNDERSON AVENUE	N/A N/A	N N	N N	1931	1931		U	U	U	U			N N					100278
3930 GUNDERSON AVENUE	N/A	N	N	1945	1945		U	U	U	U			N					100283
3942 GUNDERSON AVENUE	N/A	N	N	1929	1929		U	U	U	U			N					100286
4000 GUNDERSON AVENUE 4024 GUNDERSON AVENUE	N/A N/A	N N	N N	1959 1953	1959 1953		U	U	U	U			N N					100288 100296
6508 41ST STREET	LP1A012	N	N	1989	1989		U	U	U	U			N					100302
6514 41ST STREET	N/A	N	N	1916	1916		U	U	U	U			N					100304

							Load Cor	vice Line Inve	atom. Tomo	lata								
*Please enter information in the empty								vice Line Inve										
box next to each section	Water	System Nar	me		Stickne	² y	System	ID Number:	IL03	13000	Current Inver	ntory Date:	4/15	/2025				
*Please enter totals in the empty box next to each category	t Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Gal Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	v.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Solder (C)	(C)	Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds,					Copper - Lead Solde (CLS)	r Copper - Lead Solder (CLS	Copper - Lead Solde (CLS)	r Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If				Copper - No Lead Solder (C)		IF customer refused access to property,	
	Lead and Copper Sample site number is the 7 digit	Special Care Facilities, Hospitals,	,	What year was the	What year was the	How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		date waiver obtained by PWS or date PWS	
	number starting with "LP" or " LA". / If address is not a lead and	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	customer side service line	EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. /	Yes (Y) or No (N)	the Lead Service Line was replaced. /	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite		Leave blank if	
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in the appropriate				, co		customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (F	Plastic - PVC, HDPE, PEX (P)	•	immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown (U)	Unknown (U) Unknown Not Lead						Service Line was replaced.			
6516 41ST STREET	N/A	N	N	1960	1960		U	Unknown Not Lead (UNL)	(UNL)	U			N					100305
4035 SCOVILLE AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					100303
4029 SCOVILLE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					100310
4003 SCOVILLE AVENUE 3915 SCOVILLE AVENUE	N/A N/A	N N	N N	1953 1958	1953 1958		U	U	U	U			N N					100320 100331
3911 SCOVILLE AVENUE	N/A	N	N	1959	1959		U	U	U	U			N					100331
3912 ELMWOOD AVENUE	N/A	N	N	1962	1962		U	U	U	U			N					100333
3916 ELMWOOD AVENUE	N/A	N	N	1952	1952	Visual Inspection	U	U	С	U			N					100335
3928 ELMWOOD AVENUE 3932 ELMWOOD AVENUE	N/A N/A	N N	N N	1929 1953	1929 1953		U	U	U	U			N N					100338 100339
6430 41ST STREET	N/A	N	N	1956	1956		U	U	U	U			N					100354
4029 GUNDERSON AVENUE	N/A	N	N	1937	1937		U	U	U	U			N					100359
4009 GUNDERSON AVENUE	N/A	N 	N	1919	1919		U	U	U	U			N					100365
3943 GUNDERSON AVENUE 3919 GUNDERSON AVENUE	N/A N/A	N N	N N	1976 1948	1976 1948		U	U	U	U			N N					100369 100377
3913 GUNDERSON AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					100379
3912 RIDGELAND AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					100381
3920 S RIDGELAND AVENUE 3924 RIDGELAND AVENUE	N/A N/A	N N	N N	1957 1915	1957 1915		U	U	U	U			N N					100383 100384
3936 RIDGELAND AVENUE	N/A N/A	N	N	1915	1915		U	U	U	U			N					100384
4008 RIDGELAND AVENUE	N/A	N	N	1931	1931		U	U	U	U			N					100393
4012 RIDGELAND AVENUE	N/A	N	N	1925	1925		U	U	U	U			N					100394
6400 41ST STREET 6420 41ST STREET	N/A N/A	N N	N N	1953 1957	1953 1957		U	U	U	U			N N					100402 100407
4029 ELMWOOD AVENUE	N/A	N	N	1924	1924		U	U	U	U			N N					100409
4025 ELMWOOD AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					100410
4021 ELMWOOD AVENUE 4011 ELMWOOD AVENUE	N/A N/A	N N	N N	1920 1940	1920 1940		U	U	U	U			N N					100411
4011 ELMWOOD AVENUE	LP1C038	N N	N N	1940	1940		U	U	U	U			N					100414
3931 ELMWOOD AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					100422
3911 ELMWOOD AVENUE	N/A	N	N	1962	1962	Visual Inspection	U	U	С	U			N					100428
3944 EUCLID AVENUE 4034 EUCLID AVENUE	N/A N/A	N N	N N	1969 1957	1969 1957		U	U	U	U			N N					100438 100442
4036 EUCLID AVENUE	N/A	N	N	1922	1922		U	U	U	U			N					100442
6734 41ST STREET	N/A	N	N	1924	1924		U	U	U	U			N					100448
6742 41ST STREET	N/A	N	N	1959	1959		U	U	U	U	<u> </u>		N					100450

				T			Lead Ser	vice Line Inve	ntory Temp T	late			Π					
*Please enter information in the empty box next to each section	Water	System Nai	me 		Stickne	ey .	System	ID Number:		13000	Current Inve	ntory Date:	-	/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Gal Requiring re		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	y.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					Copper - No Lead	EXAMPLES: Copper - No Lead Solder	Copper - No Lead	EXAMPLES:					EXAMPLES:			
		Group Homes,					Solder (C) Copper - Lead Solde	(C) Copper - Lead Solder (CLS	Solder (C) Copper - Lead Solde	er Galvanized Requiring	If any galvanized service line material was ever downstream of a Lead				Copper - No Lead Solder (C)			
	Lead and Copper Sample site number is the 7 digit	Parks, Playgrounds Special Care Facilities, Hospitals	,			How was the Material of this	(CLS) Galvanized (G)	Galvanized (G)	(CLS) Galvanized (G)	Replacemnt (GRR) Unknown (U)	section, mark Yes (Y). If the galvanized service line material was never	Enter date customer was		If previous column was	Galvanized (G)		IF customer refused access to property, date waiver obtained	
	number starting with "LP" or " LA". / If address is not a lead and	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line	What year was the customer side service line	Service Line Identified? EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring	Non-Lead (NL)	downstream of any Lead section, mark No (N). /	notified of Lead Service Line.	Yes (Y) or No (N)	marked (Y), provide date the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron of	Lead (L) Cast/Ductile Iron or	Replacemnt (GRR) Lead (L) Cast/Ductile Iron or		If Yes, that section of service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
		V (V) N- (N)					Plastic - PVC, HDPE PEX (P) Unknown (U)	Transite (O) Plastic - PVC, HDPE, PEX (I	Transite (O) Plastic - PVC, HDPE PEX (P)		Requiring Replacement in the appropriate immediately preceding				Leave blank if no Lead		refused access.	
		Yes (Y) or No (N)					Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)		column(s).				Service Line was replaced.			
								Unknown Not Lead (UNL	Unknown Not Lead (UNL)									
4027 OAK PARK AVENUE 4017 OAK PARK AVENUE	N/A N/A	N N	N N	1956 1956	1956 1956		U	U	U	U			N N					100451 100455
4013 OAK PARK AVENUE	N/A	N	N	1959	1959		U	U	U	U			N					100456
4011 OAK PARK AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					100457
3945 OAK PARK AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					100460
3943 OAK PARK AVENUE 3921 OAK PARK AVENUE	N/A N/A	N N	N N	1957 1950	1957 1950		U	U	U	U			N N					100461 100468
3924 WESLEY AVENUE	N/A N/A	N N	N N	1930	1931		U	U	U	U			N					100468
3930 WESLEY AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					100478
3940 WESLEY AVENUE	N/A	N	N	1925	1925		U	U	U	U			N					100480
3942 WESLEY AVENUE	N/A	N	N	1916	1916		U	U	U	U			N					100481
3944 WESLEY AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					100482
4010 WESLEY AVENUE 4020 WESLEY AVENUE	N/A N/A	N N	N N	1955 1957	1955 1957		U	U	U	U			N N					100485 100488
4022 WESLEY AVENUE	N/A	N N	N	1958	1958		U	U	U	U			N					100489
4032 WESLEY AVENUE	LP1A006	N	N	1989	1989	Visual Inspection	U	U	С	U			N					100493
6714 41ST STREET	N/A	N	N	1970	1970		U	U	U	U			N					100498
4033 EUCLID AVENUE	N/A	N	N	1919	1919		U	U	U	U			N					100501
4005 EUCLID AVENUE 4001 EUCLID AVENUE	N/A N/A	N N	N N	1960 2023	1960 2023		U	U	U	U			N N					100509 100510
3945 EUCLID AVENUE	N/A N/A	N N	N N	1928	1928		U	U	U	U			N N					100510
3929 EUCLID AVENUE	N/A	N	N	1925	1925		U	U	U	U			N					100516
3944 CLARENCE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					100529
4000 CLARENCE AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					100530
4022 CLARENCE AVENUE	N/A	N N	N N	1952	1952		U	U	U	U			N N					100537
4028 CLARENCE AVENUE 6630 41ST STREET	N/A N/A	N N	N N	1954 1952	1954 1952		U	U	U	U			N N					100539 100543
6638 W 41ST STREET	N/A N/A	N N	N N	1952	1952		U	U	U	U			N					100543
4027 WESLEY AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					100550
4025 WESLEY AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					100551
4019 WESLEY AVENUE	N/A	N	N	1961	1961		U	U	U	U			N					100552
4017 WESLEY AVENUE	N/A	N	N	1929	1929		U	U	U	U			N					100553
4011 WESLEY AVENUE	N/A	N N	N N	1960	1960		U	U	U	U			N N					100555
4005 WESLEY AVENUE 3941 WESLEY AVENUE	N/A N/A	N N	N N	1955 1958	1955 1958		U	U	U	U			N N					100557 100561
3912 EAST AVENUE	N/A	N N	N N	1958	1958		U	U	U	U			N					100569

							Land Can			lata								
*Places antor information in the				I				vice Line Inver					<u> </u>					
*Please enter information in the empty box next to each section	Water	System Nar	me		Stickne	έλ	System	ID Number:	IL03	13000	Current Inver	ntory Date:	4/15,	/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Solder (C)	(C)	Solder (C)	Lead (L)	If any galvanized service line material was ever				Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds,					Copper - Lead Solde (CLS)	Copper - Lead Solder (CLS	Copper - Lead Solde (CLS)	r Galvanized Requiring Replacemnt (GRR)	downstream of a Lead section, mark Yes (Y). If						IF customer refused access to property,	
	Lead and Copper Sample site number is the 7 digit	Special Care Facilities, Hospitals, Clinics, Child Care		What year was the	What year was the	How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never downstream of any Lead	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		date waiver obtained by PWS or date PWS	
	number starting with "LP" or " LA". / If address is not a lead and	Facilities	Yes (Y) or No (N)	PWS-Owned service line	customer side service line	EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	section, mark No (N). /	notified of Lead Service Line. /	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	notified IDPH of refusal to sign waiver	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		If Yes, that section of service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if	
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE,		Requiring Replacement in the appropriate						customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (P	PEX (P) Unknown (U)		immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead									
3918 EAST AVENUE	N/A	N	N	1962	1962		U	U	(UNL)	U			N					100571
3928 EAST AVENUE	N/A	N	N	1917	1917		U	U	U	U			N					100574
3940 EAST AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					100577
3942 EAST AVENUE 4006 EAST AVENUE	N/A N/A	N N	N N	1939 1957	1939 1957		U	U	U	U			N N					100578 100581
4010 EAST AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					100581
6616 41ST STREET	LP1A001	N	N	1987	1987		U	U	U	U			N					100595
6618 41ST STREET	N/A	N	N	1988	1988		U	U	U	U			N					100596
4027 CLARENCE AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					100599
4025 CLARENCE AVENUE 4021 CLARENCE AVENUE	N/A N/A	N N	N N	1955 1956	1955 1956	Visual Inspection	U	U	C U	U			N N					100600 100601
4011 CLARENCE AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					100601
4005 CLARENCE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					100606
3939 CLARENCE AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					100609
3915 CLARENCE AVENUE	N/A	N	N	1915	1915		U	U	U	U			N					100616
6613 41ST STREET 6625 41ST STREET	N/A N/A	N N	N N	1978 1978	1978 1978		U	U	U	U			N N					100619 100624
6625 41ST STREET	N/A N/A	N N	N N	1978	1978 1978		U	U	U	U			N N					100624
6639 41ST STREET	N/A	N	N	1978	1978		U	U	U	U			N					100629
6645 41ST STREET	N/A	N	N	1978	1978		U	U	U	U			N					100631
6705 41ST STREET	N/A	N	N	1978	1978		U	U	U	U			N					100632
6707 41ST STREET 6709 W 41ST STREET	N/A N/A	N N	N N	1978 1978	1978 1978		U	U	U	U			N N					100633 100634
6709 W 41ST STREET	N/A N/A	N N	N N	1978	1978 1979		U	U	U	U			N N					100634
4132 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					100642
4130 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					100643
4126 MAPLE AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					100645
4116 MAPLE AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					100648
4110 MAPLE AVENUE 4108 MAPLE AVENUE	N/A N/A	N N	N N	1923 1922	1923 1922		U	U	U	U			N N					100650 100651
4113 MAPLE AVENUE	N/A N/A	N	N	1922	1922		U	U	U	U			N					100651
4123 MAPLE AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					100664
4125 MAPLE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					100665
4101 WISCONSIN AVENUE	N/A	N	N	1982	1982		U	U	U	U			N					100689
4105 WISCONSIN AVENUE 4125 WISCONSIN AVENUE	N/A N/A	N N	N N	1924 1955	1924 1955		U	U	U	U			N N					100692 100699

							Lead Ser	vice Line Inve	ntory Temp	late			Г					
*Please enter information in the empty box next to each section	Water	System Nai	me		Stickne	ey .	System	ID Number:	IL03	13000	Current Inver	ntory Date:	4/15	/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Gal Requiring re		0	Total Unknown:	1722		k to Material	https://lead-service	e-line-inventory-1-novotny	y.hub.arcgis.com/	
, , , , ,						L		Requiring re	piacement.		OTIKITOWIT.	L	liive	ntory:				
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Solder (C)	(C)	Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds	·,				Copper - Lead Solde (CLS)	r Copper - Lead Solder (CLS	(CLS)	r Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If				copper No Lead Solder (c)		IF customer refused	
	Lead and Copper Sample site number is the 7 digit	Special Care Facilities, Hospitals	i,			How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		access to property, date waiver obtained	
	number starting with "LP" or " LA". /	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line	What year was the customer side service line	Service Line Identified? EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring	Non-Lead (NL)	downstream of any Lead section, mark No (N).	notified of Lead Service Line.	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver	
	If address is not a lead and copper sample site mark				installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron or	Lead (L)	Replacemnt (GRR)		If Yes, that section of service line should be	/ If Service Line is not		/ Leave blank if previous column was (N).	Cast/Ductile Iron or Transite		/ Leave blank if	
	"N/A"					,	Transite (O) Plastic - PVC, HDPE PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron of Transite (O)	r	marked as Galvanized Requiring Replacement in	Lead put N/R		Column was (N).	(O)		customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U)	Plastic - PVC, HDPE, PEX (F	Plastic - PVC, HDPE PEX (P)	,	the appropriate immediately preceding				Leave blank if no Lead			
		res (1) of No (N)					Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)		column(s).				Service Line was replaced.			
								Unknown Not Lead (UNL	(UNL)									
4135 WISCONSIN AVENUE 4137 WISCONSIN AVENUE	N/A N/A	N N	N N	1964 1924	1964 1924		U	U	U	U			N N					100702 100703
4122 WENONAH AVENUE	N/A	N N	N N	1949	1949		U	U	U	U			N					100703
4116 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					100714
4114 WENONAH AVENUE	N/A	N	N	1951	1951		U	U	U	U			N					100715
4108 WENONAH AVENUE 4101 WENONAH AVENUE	N/A N/A	N N	N N	1955 1929	1955 1929		U	U	U	U			N N					100717 100720
4103 WENONAH AVENUE	N/A	N	N	1996	1996		U	U	U	U			N					100721
4107 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					100723
4121 WENONAH AVENUE	N/A N/A	N N	N N	1952	1952		U	U	U	U			N N					100728
4127 WENONAH AVENUE 4137 WENONAH AVENUE	N/A N/A	N N	N N	1953 1924	1953 1924		U	U	U	U			N N					100731 100735
4132 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					100742
4128 HOME AVENUE	N/A	N	N	1931	1931		U	U	U	U			N					100743
4120 HOME AVENUE	N/A N/A	N N	N N	1949	1949		U	U	U	U			N N					100746
4118 HOME AVENUE 4108 HOME AVENUE	N/A N/A	N N	N N	1929 1924	1929 1924		U	U	U	U			N N					100747 100751
4103 HOME AVENUE	N/A	N	N	1962	1962		U	U	U	U			N					100756
4105 HOME AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					100757
4115 HOME AVENUE 4137 HOME AVENUE	N/A N/A	N N	N N	1930 1956	1930 1956		U	U	U	U			N N					100762 100764
4143 HOME AVENUE	N/A N/A	N	N N	1954	1956		U	U	U	U			N					100766
4136 CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					100770
4134 CLINTON AVENUE	N/A	N	N	1952	1952	Nr. 11	U	U	U	U			N					100771
4126 CLINTON AVENUE 4118 CLINTON AVENUE	N/A LA1C080	N N	N N	1952 1952	1952 1952	Visual Inspection	U	U	C U	U			N N					100774 100777
4116 CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					100778
4108 CLINTON AVENUE	N/A	N	N	1926	1926		U	U	U	U			N					100781
4100 CLINTON AVENUE	LP1C087	N N	N	1952	1952		U	U	U	U			N N					100783
4101 CLINTON AVENUE 4103 CLINTON AVENUE	N/A N/A	N N	N N	1950 1950	1950 1950		U	U	U	U			N N					100784 100785
4105 CLINTON AVENUE	N/A	N N	N	1950	1950		U	U	U	U			N N					100786
4121 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U			N					100790
4125 CLINTON AVENUE 4132 GROVE AVENUE	N/A N/A	N N	N N	1950 1955	1950 1955		U	U	U	U			N N					100791 100804
4132 GROVE AVENUE	N/A N/A	N N	N N	1955	1955		U	U	U	U			N N					100804

							Lead Ser	vice Line Inver	ntory Temp	late								
*Please enter information in the empty box next to each section	Water	System Nai	me		Stickne	ey .	System	ID Number:	IL03	13000	Current Inven	ntory Date:	4/15,	/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		c to Material ntory:	https://lead-service	e-line-inventory-1-novotn	y.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last		Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	Group Homes, Parks, Playgrounds Special Care Facilities, Hospitals Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacemnt (GRR) Unknown (U) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4103 GROVE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					100817
4123 GROVE AVENUE	N/A	N N	N N	1961	1961		U	U	U	U			N					100823
4125 GROVE AVENUE 4135 GROVE AVENUE	N/A N/A	N N	N N	1931 1930	1931 1930		U	U U	U	U			N N					100824
4135 GROVE AVENUE	N/A N/A	N N	N N	1930	1930		U	U	U	U			N N					100827
4148 OAK PARK AVENUE	N/A	N	N	1928	1928		U	U	U U	li li			N					100831
4144 OAK PARK AVENUE	LA1C043	N	N	1953	1953	Visual Inspection	U	U	C	U			N					100832
4136 OAK PARK AVENUE	N/A	N	N	1919	1919	visual hispection	U	U	II	II.			N					100835
4126 OAK PARK AVENUE	N/A	N	N	1960	1960		U	U	U	U			N					100839
4020 OAK PARK AVENUE	N/A	N	N	1998	1998		U	U	U	U			N					100854
4016 OAK PARK AVENUE	N/A	N	N	1929	1929		U	U	U	U			N					100856
4006 OAK PARK AVENUE	N/A	N	N				U	U	U	U			N					100860
4035 GROVE AVENUE	N/A	N	N	1950	1950		U	U	U	U			N					100861
4024 GROVE AVENUE	N/A	N	N	1951	1951		U	U	U	U			N					100871
4020 GROVE AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					100872
4014 GROVE AVENUE	N/A	N	N	1919	1919		U	U	U	U			N					100875
4006 GROVE AVENUE	N/A	N	N	1919	1919		U	U	U	U			N					100878
4004 GROVE AVENUE	N/A	N	N	1919	1919		U	U	U	U			N					100879
4000 GROVE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					100880
4015 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					100887
4045 CLINTON AVENUE	N/A	N N	N	1955	1955		U	U	U	U			N					100898
4042 CLINTON AVENUE 4026 CLINTON AVENUE	N/A	N N	N N	1958	1958		U	U	U	U			N N					100900 100905
4026 CLINTON AVENUE 4014 CLINTON AVENUE	N/A N/A	N N	N N	1955 1927	1955 1927		U	U	U	U			N N					100905
4008 CLINTON AVENUE	N/A N/A	N N	N N	1927	1927		U II	U II	U	U			N N					100911
4011 HOME AVENUE	N/A N/A	N	N	1976	1976		U	U	U	U			N					100913
4011 HOME AVENUE	N/A	N	N	1931	1931		U	U	U	U			N					100919
4027 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					100925
4041 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					100930
7012 41ST STREET	N/A	N	N	1953	1953		U	U	U	U			N					100933
7038 41ST STREET	N/A	N	N	1978	1978		U	U	U	U			N					100942
7042 41ST STREET	N/A	N	N	1947	1947		U	U	U	U			N					100943
7052 41ST STREET	N/A	N	N	1950	1950		U	U	U	U			N					100945
7102 41ST STREET	N/A	N	N	1955	1955		U	U	U	U			N					100946
7104 41ST STREET	N/A	N	N	1970	1970		U	U	U	U			N					100947
7106 41ST STREET	N/A	N	N	1970	1970		U	U	U	U			N		<u> </u>			100948

							Lead Ser	vice Line Inver	ntory Temp	late								
*Please enter information in the empty box next to each section	Water	System Nar	me		Stickne	ey		ID Number:		13000	Current Inver	ntory Date:	4/15	/2025				
*Please enter totals in the empty box next to each category	Total Service	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	-line-inventory-1-novotny	.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?		Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Lead (L)					EXAMPLES:			
		Group Homes, Parks, Playgrounds,					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Conner Lead Solder	Galvanized Requiring Replacemnt (GRR)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If				Copper - No Lead Solder (C)		IF customer refused	
	Lead and Copper Sample site number is the 7 digit number starting with "LP"	Special Care Facilities, Hospitals, Clinics, Child Care		What year was the	What year was the	How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never downstream of any Lead	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		access to property, date waiver obtained by PWS or date PWS	
	or " LA". / If address is not a lead and	Facilities	Yes (Y) or No (N)	PWS-Owned service line installed, if known?	customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey Response,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	section, mark No (N). / If Yes, that section of	notified of Lead Service Line. /	Yes (Y) or No (N)	the Lead Service Line was replaced. / Leave blank if previous	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	notified IDPH of refusal to sign waiver. /	
	copper sample site mark "N/A"					Maintenance Records, etc	Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P)	Lead (L) Cast/Ductile Iron or Transite (O)	Lead (L) Cast/Ductile Iron or Transite (O)		service line should be marked as Galvanized Requiring Replacement in the appropriate	If Service Line is not Lead put N/R		column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead (UNL)	Plastic - PVC, HDPE, PEX (P	Plastic - PVC, HDPE, PEX (P) Unknown (U)		immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
7128 41ST STREET	LA1A020	N	N	1986	1986		U	U	U	U			N					100955
7113 40TH PLACE 7111 40TH PLACE	N/A N/A	N N	N N	1917 1979	1917 1979		U	U	U	U			N N					100969 100970
7111 40TH PLACE 7101 40TH PLACE	N/A N/A	N	N N	1979	1979		U	U	U	U			N					100970
7041 40TH PLACE	N/A	N	N	1916	1916		U	U	U	U			N					100976
7037 40TH PLACE	N/A	N	N	1976	1976	Visual Inspection	U	U	С	U			N					100978
7035 40TH PLACE	N/A	N	N	1977	1977		U	U	U	U			N					100979
7007 40TH PLACE 7001 40TH PLACE	N/A N/A	N N	N N	1927 1955	1927 1955		U	U	U	U			N N					100988
7001 40TH PLACE 7000 40TH PLACE	N/A N/A	N	N N	1959	1955		U	U	U	U			N					100991
7004 40TH PLACE	N/A	N	N	1975	1975		U	U	U	U			N					100994
7020 40TH PLACE	N/A	N	N	1971	1971		U	U	U	U			N					100999
7024 40TH PLACE	N/A	N	N	1971	1971		U	U	U	U			N					101001
7030 40TH PLACE 7042 40TH PLACE	N/A N/A	N N	N N	1919 1914	1919 1914		U	U	U	U			N N					101004 101007
7042 40TH PLACE 7046 40TH PLACE	N/A N/A	N N	N N	1914	1914		U	U	U	U			N N					101007
7114 40TH PLACE	N/A	N	N	1914	1914		U	U	U	U			N					101014
7116 40TH PLACE	N/A	N	N	1998	1998		U	U	U	U			N					101015
7122 40TH PLACE	N/A	N	N	1965	1965		U	U	U	U			N					101017
7124 40TH PLACE 7126 40TH PLACE	N/A N/A	N N	N N	1919 1955	1919 1955		U U	U	U	U			N N					101018 101019
7131 40TH STREET	N/A N/A	N	N	1914	1933		U	U	U	U			N					101019
7119 40TH STREET	N/A	N	N	1914	1914		U	U	U	U			N					101028
7115 40TH STREET	N/A	N	N	1928	1928		U	U	U	U			N					101030
7105 40TH STREET	N/A	N	N	1924	1924		U	U	U	U			N					101033
7043 40TH STREET	N/A	N N	N N	1981	1981		U U	U	U	U			N N					101036
7039 40TH STREET 7009 40TH STREET	N/A N/A	N N	N N	1979 1953	1979 1953		U	U	U	U			N N					101038 101050
3928 OAK PARK AVENUE	N/A	N	N	1927	1927		U	U	U	U			N					101060
3920 OAK PARK AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					101062
3918 OAK PARK AVENUE	N/A	N	N	1951	1951		U	U	U	U			N					101063
3921 GROVE AVENUE	LP1A022	N	N	1988	1988		U	U	U	U			N					101071
3931 GROVE AVENUE 3914 GROVE AVENUE	N/A N/A	N N	N N	1955 1974	1955 1974		U	U	U	U			N N					101076 101089
3914 GROVE AVENUE 3929 CLINTON AVENUE	N/A N/A	N N	N N	1974	1974		U	U	U	U			N N					101089
3935 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U			N					101100

	ı			ı			Lead Ser	vice Line Inve	ntory Temp	late	ı				I			
*Please enter information in the empty box next to each section	Water	System Nai	me		Stickne	<u> </u>	System	ID Number:		13000	Current Inve	ntory Date:	·	/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Gal Requiring re		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	y.hub.arcgis.com/	
					<u>'</u>			, g				•		•				
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Solder (C)	(C)	Solder (C)	Lead (L)	If any galvanized service							
		Group Homes, Parks, Playgrounds	,				Copper - Lead Solde (CLS)	Copper - Lead Solder (CLS	Copper - Lead Solde (CLS)	r Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If				Copper - No Lead Solder (C)		IF customer refused	
	Lead and Copper Sample	Special Care Facilities, Hospitals				How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date		If previous column was	Galvanized (G)		access to property, date waiver obtained	
	site number is the 7 digit number starting with "LP"	Clinics, Child Care Facilities		What year was the PWS-Owned	What year was the customer side	Service Line Identified? EXAMPLES: Construction		Galvanized Requiring	Galvanized	, ,	downstream of any Lead section, mark No (N).	customer was notified of Lead		marked (Y), provide date the Lead Service Line was			by PWS or date PWS notified IDPH of	
	or " LA". / If address is not a lead and	raciitles	Yes (Y) or No (N)	service line	service line installed, if known?	Records, Visual Inspections, Survey Response,	Lead (L)	Replacemnt (GRR)	Requiring Replacemnt (GRR)	Non-Lead (NL)	/ If Yes, that section of	Service Line. /	Yes (Y) or No (N)	replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	refusal to sign waiver.	
	copper sample site mark "N/A"			ilistalleu, il kilowii:	ilistalleu, il kilowii:	Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite		Leave blank if	
							Plastic - PVC, HDPE PEX (P)	, Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron of Transite (O)	•	Requiring Replacement in the appropriate				(6)		customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U)	Plastic - PVC, HDPE, PEX (I	Plastic - PVC, HDPE PEX (P)		immediately preceding				Leave blank if no Lead			
		163 (1) 01 140 (14)					Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)		column(s).				Service Line was replaced.			
								Unknown Not Lead (UNL	Unknown Not Lead (UNL)									
3939 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U			N					101102
3941 CLINTON AVENUE 3926 CLINTON AVENUE	N/A N/A	N N	N N	1950 1957	1950 1957		U	U	U	U			N N					101103 101109
3914 CLINTON AVENUE	N/A	N N	N	1957	1957		U	U	U	U			N					101105
6935 PERSHING ROAD	N/A	N	N	1957	1957		U	U	U	U			N					101117
6937 PERSHING ROAD	N/A	N	N	1957	1957		U	U	U	U			N					101118
6939 PERSHING ROAD 6941 PERSHING ROAD	N/A N/A	N N	N N	1957 1957	1957 1957		U	U	U	U			N N					101119 101120
3915 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					101125
3917 HOME AVENUE	N/A	N	N	1950	1950		U	U	U	U			N					101126
3925 HOME AVENUE	N/A N/A	N N	N N	1924 1947	1947 1947		U	U	U	U			N N					101130 101137
3944 HOME AVENUE	N/A N/A	N N	N N	1947	1947		U	U	U	U			N					101137
7004 40TH STREET	N/A	N	N	1947	1947		U	U	U	U			N					101149
7020 40TH STREET	N/A	N	N	1947	1947		U	U	U	U			N					101153
7032 40TH STREET 7040 40TH STREET	N/A N/A	N N	N N	1947 1947	1947 1947		U	U	U	U			N N					101156 101158
7052 40TH STREET	N/A	N N	N N	1947	1947		U	U	U	U			N					101138
7108 40TH STREET	N/A	N	N	1947	1947		U	U	U	U			N					101164
4203 MAPLE AVENUE	N/A	N N	N N	1968	1968	Visual Inspection	U	U	C	U			N N					101236
4219 MAPLE AVENUE 4225 MAPLE AVENUE	N/A N/A	N N	N N	1957 1925	1957 1925		U	U	U	U			N N					101241 101243
7120 43RD STREET	N/A	N	N	1954	1954		U	U	U	U			N					101247
4226 WISCONSIN AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					101255
4201 WISCONSIN AVENUE 7034 43RD STREET	N/A N/A	N N	N N	1955 1952	1955 1952		U	U	U	U			N N					101264 101278
4218 WENONAH AVENUE	N/A N/A	N	N N	1952	1952		U	U	U	U			N					101278
4200 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					101292
4209 WENONAH AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					101296
4213 WENONAH AVENUE 4237 WENONAH AVENUE	N/A N/A	N N	N N	1925 1953	1925 1953		U	U	U	U			N N					101297 101304
7024 43RD STREET	N/A	N	N	1970	1970		U	U	U	U			N					101305
7006 43RD STREET	N/A	N	N	1950	1950		U	U	U	U			N					101311
7004 43RD STREET	N/A	N	N	1950	1950		U	U	U	U			N					101312
4230 HOME AVENUE 4224 HOME AVENUE	N/A N/A	N N	N N	1933 1955	1933 1955	Visual Inspection	U	U	C	U			N N					101314 101316
4224 NUIVIE AVENUE	IN/A	IN	IN	1900	1933	I	1 0	U	1 0	U	I	1	IN	I	I		1	101210

				1			Lead Ser	vice Line Inve	ntory Temp	late			ı					
*Please enter information in the empty box next to each section	Water	System Nai	me		Stickne	y .	System	ID Number:		13000	Current Inve	ntory Date:	-	/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Gal Requiring re		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	y.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Solder (C)	(C)	Solder (C)	Lead (L)	If any galvanized service line material was ever				Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds Special Care	,				Copper - Lead Solde (CLS)	Copper - Lead Solder (CLS	(CLS)	r Galvanized Requiring Replacemnt (GRR)	downstream of a Lead section, mark Yes (Y). If the galvanized service line						IF customer refused access to property,	
	Lead and Copper Sample site number is the 7 digit	Facilities, Hospitals Clinics, Child Care	,	What year was the	What year was the	How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never downstream of any Lead	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		date waiver obtained by PWS or date PWS	
	number starting with "LP" or " LA". / If address is not a lead and	Facilities	Yes (Y) or No (N)	PWS-Owned service line	customer side service line	EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	section, mark No (N).	notified of Lead Service Line.	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron of Transite (O)	Lead (L)	Lead (L)		If Yes, that section of service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
							Plastic - PVC, HDPE PEX (P)	, Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron of Transite (O) Plastic - PVC, HDPE	•	Requiring Replacement in the appropriate						refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (F	PEX (P)	1	immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown (U) Unknown Not Lead (UNL	Unknown (U) Unknown Not Lead		-							
4218 HOME AVENUE	N/A	N	N	1937	1937		U	U	(UNL)	U			N					101318
4216 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					101319
4203 HOME AVENUE	N/A	N N	N	1954	1954		U	U	U	U			N 					101325
4217 HOME AVENUE 4221 HOME AVENUE	N/A N/A	N N	N N	1960 1962	1960 1962		U	U	U	U			N N					101329 101331
4225 HOME AVENUE	N/A	N	N	1963	1963		U	U	U	U			N					101333
4239 HOME AVENUE	N/A	N	N N	1954	1954		U	U	U	U			N 					101338
4240 CLINTON AVENUE 4236 CLINTON AVENUE	N/A N/A	N N	N N	1954 1955	1954 1955		U	U	U	U			N N					101342 101343
4204 CLINTON AVENUE	N/A	N	N	1899	1899		U	U	U	U			N					101353
4200 CLINTON AVENUE	N/A	N	N	1973	1973		U	U	U	U			N					101354
4205 CLINTON AVENUE 4229 CLINTON AVENUE	N/A N/A	N N	N N	1955	1955		U	U	U	U			N N					101357 101367
4237 CLINTON AVENUE	N/A	N	N N	1956	1956		U	U	U	U			N N					101369
4238 GROVE AVENUE	N/A	N	N	1979	1979		U	U	U	U			N					101374
4228 GROVE AVENUE 4226 GROVE AVENUE	N/A N/A	N N	N N	1956 1955	1956 1955	Visual Inspection	U	U	U C	U			N N					101376 101377
4218 GROVE AVENUE	N/A N/A	N	N N	1935	1955	Visual Inspection	U	U	U	U			N					101377
4216 GROVE AVENUE	N/A	N	N	1927	1927		U	U	U	U			N	_				101381
4204 GROVE AVENUE	N/A	N N	N N	1954	1954	Visual Inspection	U	U	С	U			N N					101384
4219 GROVE AVENUE 4223 GROVE AVENUE	N/A N/A	N N	N N	1976 1925	1976 1925		U	U	U	U			N N					101392 101393
4231 GROVE AVENUE	N/A	N	N	1927	1927		U	U	U	U			N					101395
4235 GROVE AVENUE	N/A	N	N	1929	1929		U	U	U	U			N					101396
4239 GROVE AVENUE 4218 OAK PARK AVENUE	N/A N/A	N N	N N	1925 1925	1925 1925		U	U	U	U			N N					101398 101404
4210 OAK PARK AVENUE	N/A	N	N	1931	1931		U	U	U	U			N N					101406
4208 OAK PARK AVENUE	N/A	N	N	1927	1927		U	U	U	U			N					101407
4200 OAK PARK AVENUE 4306 MAPLE AVENUE	N/A N/A	N N	N N	1961 1960	1961 1960		U	U	U	U			N N					101410 101414
4330 MAPLE AVENUE	N/A N/A	N N	N N	1960	1960		U	U	U	U			N N					101414
4331 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U			N					101427
4327 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U			N					101429
4323 MAPLE AVENUE 4311 MAPLE AVENUE	N/A N/A	N N	N N	1960 1960	1960 1960		U	U	U	U			N N					101431 101437
4307 MAPLE AVENUE	N/A	N	N	1959	1959		U	U	U	U			N					101439

							Load Son	vice Line Inver	tory Tomp	late								
*Please enter information in the empty	Mator	Sustan Na	mo		Cticles						Current Inven	stani Datai	4/15,	/2025				
box next to each section	vvater	System Na	T		Stickne	:y T	System	ID Number:		13000	Current Inver	itory Date:						
*Please enter totals in the empty box next to each category	Total Service	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722	Website link	c to Material ntory:	https://lead-service	e-line-inventory-1-novotny	/.hub.arcgis.com/	
								i itequiiig rep	nacement.		OTHER DESIGNATION OF THE PERSON OF THE PERSO			10171				
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?		Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service							
		Group Homes, Parks, Playgrounds					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead				Copper - No Lead Solder (C)		IF customer refused	
	Lead and Copper Sample	Special Care Facilities, Hospitals	Ž.			How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	section, mark Yes (Y). If the galvanized service line material was never	Enter date		If previous column was	Galvanized (G)		access to property,	
	site number is the 7 digit number starting with "LP"	Clinics, Child Care Facilities		What year was the PWS-Owned	What year was the customer side	Service Line Identified? EXAMPLES: Construction		Galvanized Requiring	Galvanized		downstream of any Lead section, mark No (N).	notified of Lead	Voc (V) or No (N)	marked (Y), provide date the Lead Service Line was		Voc (V) or No (N)	by PWS or date PWS notified IDPH of	
	or " LA". / If address is not a lead and copper sample site mark		Yes (Y) or No (N)	service line installed, if known?	service line installed, if known?	Records, Visual Inspections, Survey Response,	Lead (L)	Replacemnt (GRR)	Requiring Replacemnt (GRR)	Non-Lead (NL)	/ If Yes, that section of	Service Line. /	Yes (Y) or No (N)	replaced. / Leave blank if previous	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	refusal to sign waiver. /	
	"N/A"					Maintenance Records, etc	Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE,	Lead (L) Cast/Ductile Iron or	Lead (L) Cast/Ductile Iron or		service line should be marked as Galvanized Requiring Replacement in	If Service Line is not Lead put N/R		column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
							PEX (P) Unknown (U)	Transite (O) Plastic - PVC, HDPE, PEX (P)	Transite (O) Plastic - PVC, HDPE,		the appropriate immediately preceding						refused access.	
		Yes (Y) or No (N)					Unknown Not Lead (UNL)	Unknown (U)	PEX (P) Unknown (U)		column(s).				Leave blank if no Lead Service Line was replaced.			
							(0112)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4302 WISCONSIN AVENUE 4314 WISCONSIN AVENUE	N/A N/A	N N	N N	1958 1958	1958 1958		U	U	U	U			N N					101444 101448
4314 WISCONSIN AVENUE 4322 WISCONSIN AVENUE	N/A N/A	N N	N N	1958	1958		U	U	U	U			N N					101448
4334 WISCONSIN AVENUE	N/A	N	N	1959	1959		U	U	U	U			N					101454
4338 WISCONSIN AVENUE	N/A	N N	N N	1959	1959		U	U	U	U			N N					101456
4329 WISCONSIN AVENUE 7029 43RD STREET	N/A N/A	N N	N N	1930 1955	1930 1955		U	U U	U	U			N N					101461 101470
4332 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					101478
4337 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					101485
4329 WENONAH AVENUE 7021 43RD STREET	N/A N/A	N N	N N	1924 1954	1924 1954		U	U	U	U			N N					101486 101490
7011 43RD STREET	N/A	N	N	1954	1954		U	U	U	U			N					101493
7005 43RD STREET	N/A	N	N	1955	1955		U	U	U	U			N					101495
7001 43RD STREET 4312 HOME AVENUE	N/A N/A	N N	N N	1955 1954	1955 1954		U	U	U	U			N N					101496
4320 HOME AVENUE	N/A N/A	N	N	1954	1954		U	U	U	U			N N					101497 101499
4334 HOME AVENUE	N/A	N	N	1951	1951		U	U	U	U			N					101502
4340 HOME AVENUE	N/A N/A	N	N N	1951	1951		U	U	U	U			N N					101504
4344 HOME AVENUE 4337 HOME AVENUE	N/A N/A	N N	N N	1955 1955	1955 1955		U	U	U	U			N N					101505 101507
4313 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					101513
4324 CLINTON AVENUE	N/A	N	N	1934	1934		U	U	U	U			N					101520
4345 CLINTON AVENUE 4333 CLINTON AVENUE	N/A N/A	N N	N N	1955 1939	1955 1939		U	U	U	U			N N					101526 101528
4329 CLINTON AVENUE	N/A	N	N	1938	1938		U	U	U	U			N					101529
4315 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					101534
6905 43RD STREET 4332 KENILWORTH AVENUE	N/A N/A	N N	N N	1959 1925	1959 1925		U	U U	U	U			N N					101538 101545
4341 KENILWORTH AVENUE	N/A	N	N	1923	1925		U	U	U	U			N					101548
4346 KENILWORTH AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					101549
4343 KENILWORTH AVENUE	N/A	N	N	1925	1925		U	U	U	U			N					101550
4319 KENILWORTH AVENUE 4317 KENILWORTH AVENUE	N/A N/A	N N	N N	1957 1966	1957 1966		U	U U	U	U			N N					101555 101556
4315 KENILWORTH AVENUE	N/A	N	N	1967	1967		U	U	U	U			N					101557
6829 43RD STREET	N/A	N	N	1959	1959	Visual Inspection	U	U	C	U			N					101563
6825 43RD STREET	N/A	N	N	1955	1955		U	U	U	U			N					101564

							Load Sor	vice Line Inver	tory Tomp	lato								
*Please enter information in the empty				I				vice Line Inver				_						
box next to each section	Water	System Nar	me 		Stickne	ey	System	ID Number:		13000	Current Inver	ntory Date:	4/15	/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES: Lead (L)					EXAMPLES:			
		Group Homes,					Solder (C) Copper - Lead Solde	(C)	Solder (C) Copper - Lead Solde	Galvanized Requiring	If any galvanized service line material was ever				Copper - No Lead Solder (C)			
	Lead and Copper Sample	Parks, Playgrounds, Special Care				How was the Material of this	(CLS)	Copper - Lead Solder (CLS	(CLS)	Replacemnt (GRR)	downstream of a Lead section, mark Yes (Y). If the galvanized service line	Enter date		If previous column was	Galvanized (G)		IF customer refused access to property, date waiver obtained	
	site number is the 7 digit number starting with "LP" or " LA".	Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned	What year was the customer side	Service Line Identified? EXAMPLES: Construction	Galvanized (G)	Galvanized (G) Galvanized Requiring	Galvanized (G)	Unknown (U)	material was never downstream of any Lead section, mark No (N).	customer was notified of Lead Service Line.	Yes (Y) or No (N)	marked (Y), provide date the Lead Service Line was replaced.		Yes (Y) or No (N)	by PWS or date PWS notified IDPH of	
	If address is not a lead and copper sample site mark		163 (1) OF NO (N)	service line installed, if known?	service line installed, if known?	Records, Visual Inspections, Survey Response, Maintenance Records, etc	Lead (L) Cast/Ductile Iron or	Replacemnt (GRR)	Requiring Replacemnt (GRR)	Non-Lead (NL)	/ If Yes, that section of service line should be	/ If Service Line is not	163 (1) 01 140 (14)	Leave blank if previous	Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite	163 (1) 01 140 (14)	refusal to sign waiver. / Leave blank if	
	"N/A"					manite name need as, etc	Transite (O) Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		marked as Galvanized Requiring Replacement in the appropriate	Lead put N/R		column was (N).	(O)		customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (P	Plastic - PVC, HDPE, PEX (P)		immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown (U) Unknown Not Lead (UNL)	Unknown (U) Unknown Not Lead						·			
4320 GROVE AVENUE	N/A	N	N	1953	1953	Visual Inspection	U	U	(UNL)	U			N					101565
4342 GROVE AVENUE	N/A	N	N	1946	1946		U	U	U	U			N					101570
4343 GROVE AVENUE	N/A	N	N	1946	1946		U	U	U	U			N					101576
4335 GROVE AVENUE 4321 GROVE AVENUE	N/A N/A	N N	N N	1946 1948	1946 1948		U	U	U	U			N N					101578 101581
4310 OAK PARK AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					101583
4314 OAK PARK AVENUE	N/A	N	N				U	U	U	U			N					101584
4326 OAK PARK AVENUE	N/A	N 	N N	1952	1952		U	U	U	U			N N					101588
4400 OAK PARK AVENUE 4404 OAK PARK AVENUE	N/A N/A	N N	N N	1953 1953	1953 1953		U	U	U	U			N N					101592 101593
4412 OAK PARK AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					101595
4426 OAK PARK AVENUE	N/A	N	N	1988	1988		U	U	U	U			N					101598
4454 OAK PARK AVENUE	N/A	N	N	1949	1949		U	U	U	U			N					101604
4457 GROVE AVENUE 4453 GROVE AVENUE	N/A N/A	N N	N N	1947 1945	1947 1945		U	U	U	U			N N					101606 101607
4445 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U			N					101609
4441 GROVE AVENUE	N/A	N	N	1947	1947		U	U	U	U			N					101610
4437 GROVE AVENUE 4413 GROVE AVENUE	N/A N/A	N N	N N	1945 1945	1945 1945		U	U	U	U			N N					101611 101617
4413 GROVE AVENUE	N/A N/A	N N	N N	1945	1945		U	U	U	U			N					101617
4404 GROVE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					101622
4416 GROVE AVENUE	N/A	N	N	1965	1965		U	U	U	U			N					101625
4434 GROVE AVENUE 4459 KENILWORTH AVENUE	N/A N/A	N N	N N	1945 1924	1945 1924		U	U	U	U			N N					101629 101635
4447 KENILWORTH AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					101637
4427 KENILWORTH AVENUE	N/A	N	N	1947	1947		U	U	U	U			N					101642
4419 KENILWORTH AVENUE	N/A	N N	N N	1946	1946		U	U	U	U			N					101644
4412 KENILWORTH AVENUE 4418 KENILWORTH AVENUE	N/A N/A	N N	N N	1927 1954	1927 1954		U	U	U	U			N N					101652 101653
4428 KENILWORTH AVENUE	N/A	N	N	1946	1946		U	U	U	U			N					101655
4440 KENILWORTH AVENUE	N/A	N	N	1949	1949		U	U	U	U			N					101658
4446 KENILWORTH AVENUE	N/A	N N	N N	1954	1954		U	U	U	U			N					101660
4431 CLINTON AVENUE 4410 CLINTON AVENUE	N/A N/A	N N	N N	1960 1952	1960 1952		U	U	U	U			N N					101667 101678
4414 CLINTON AVENUE	N/A N/A	N	N	1956	1956		U	U	U	U			N					101679
4420 CLINTON AVENUE	N/A	N	N	1925	1925		U	U	U	U			N					101680

							Lead Ser	vice Line Inver	ntory Temp	lato								
*Please enter information in the empty	\A/atau	Custom No.			Cticlus						Comment laws	-t D-t	4/45	/2025				
box next to each section	water	System Nar	ne		Stickne	ey	System	ID Number:		13000	Current Inver	ntory Date:		/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Solder (C)	(C)	Solder (C)		If any galvanized service line material was ever				Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds, Special Care	,				Copper - Lead Solde (CLS)	r Copper - Lead Solder (CLS	Copper - Lead Solde (CLS)	r Galvanized Requiring Replacemnt (GRR)	downstream of a Lead section, mark Yes (Y). If						IF customer refused access to property,	
	Lead and Copper Sample site number is the 7 digit	Facilities, Hospitals, Clinics, Child Care	,	What year was the	What year was the	How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never downstream of any Lead	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		date waiver obtained by PWS or date PWS	
	number starting with "LP" or " LA". / If address is not a lead and	Facilities	Yes (Y) or No (N)	PWS-Owned service line	customer side service line	EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	section, mark No (N). /	notified of Lead Service Line. /	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		If Yes, that section of service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if	
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in the appropriate				,,,,		customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (P	Plastic - PVC, HDPE, PEX (P)		immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown (U) Unknown Not Lead (UNL)	Unknown (U) Unknown Not Lead						·			
4433 HOME AVENUE	N/A	N	N	1956	1956		U	U	(UNL) U	U			N					101693
4419 HOME AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					101696
4411 HOME AVENUE 4437 WENONAH AVENUE	N/A N/A	N N	N N	1955 1928	1955 1928		U	U	U	U			N N					101698 101704
4431 WENONAH AVENUE.	N/A	N	N	1929	1929		U	U	U	U			N					101705
4421 WENONAH AVENUE	N/A	N	N	1928	1928		U	U	U	U			N					101708
4415 WENONAH AVENUE 4402 WENONAH AVENUE	N/A N/A	N N	N N	1928 1956	1928 1956		U	U	U	U			N N					101709 101711
4408 WENONAH AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					101713
4420 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					101716
4426 WENONAH AVENUE 4415 WISCONSIN AVENUE	N/A N/A	N N	N N	1954 1924	1954 1924		U	U	U	U			N N					101718 101731
4412 WISCONSIN AVENUE	N/A	N	N	1951	1951		U	U	U	U			N					101735
4438 WISCONSIN AVENUE	N/A	N	N	1968	1968	Visual Inspection	U	U	С	U			N					101740
4442 WISCONSIN AVENUE 4437 MAPLE AVENUE	N/A N/A	N N	N N	1926 1940	1926 1940		U	U	U	U			N N					101742 101746
4437 MAPLE AVENUE 4431 MAPLE AVENUE	N/A N/A	N N	N N	1940	1940		U	U	U	U			N N					101746
4421 MAPLE AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					101749
4415 MAPLE AVENUE	N/A	N N	N	1925	1925		U	U	U	U			N					101750
4401 MAPLE AVENUE 4438 MAPLE AVENUE	N/A N/A	N N	N N	1960 1998	1960 1998		U	U	U	U			N N					101753 101763
4442 MAPLE AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					101764
41TH AND EUCLID	N/A	N	N				U	U	U	U			N					101769
4220 EAST AVENUE 43RD AND EAST AVENUE	N/A N/A	N N	N N				U	U	U	U			N N					101770 101771
4101 OAK PARK AVENUE	N/A N/A	N	N				U	U	U	U			N					101771
6501 PERSHING ROAD	N/A	N	N				U	U	U	U			N					101780
3904 GUNDERSON AVENUE	N/A	N N	N N				U	U	U	U			N					101781
3906 GUNDERSON AVENUE 6441 PERSHING ROAD	N/A N/A	N N	N N				U	U	U	U			N N					101782 101784
6421 PERSHING ROAD	N/A	N	N				U	U	U	U			N N					101785
6431 PERSHING ROAD	N/A	N	N				U	U	U	U			N					101786
6401 PERSHING ROAD 6743 PERSHING ROAD	N/A N/A	N N	N N				U	U	U	U			N N					101788 101789
6743 PERSHING ROAD	N/A N/A	N N	N N				U	U	U	U			N N					101789
6721 40TH STREET	N/A	N	N				U	U	U	U			N					101798

							Lead Ser	vice Line Inve	ntory Temp	late								
*Please enter information in the empty box next to each section	Water	System Nai	me		Stickne	ey .	System	ID Number:		13000	Current Inver	ntory Date:		/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Gal Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	y.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Solder (C)	(C)	Solder (C)	Lead (L)	If any galvanized service line material was ever				Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds	,				Copper - Lead Solde (CLS)	r Copper - Lead Solder (CLS	Copper - Lead Solde (CLS)	r Galvanized Requiring Replacemnt (GRR)	downstream of a Lead section, mark Yes (Y). If						IF customer refused access to property,	
	Lead and Copper Sample site number is the 7 digit	Special Care Facilities, Hospitals	,	Mile at the state of the state	What year was the	How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		date waiver obtained	
	number starting with "LP" or " LA". / If address is not a lead and	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	customer side service line	Service Line Identified? EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring	Non-Lead (NL)	downstream of any Lead section, mark No (N). /	notified of Lead Service Line.	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Replacemnt (GRR)		If Yes, that section of service line should be marked as Galvanized	/ If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if	
							Plastic - PVC, HDPE PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in the appropriate				Λ=/		customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (F) Plastic - PVC, HDPE PEX (P)		immediately preceding column(s).				Leave blank if no Lead			
							(UNL)	Unknown (U)	Unknown (U) Unknown Not Lead		.,				Service Line was replaced.			
4442 HADIFAA AVENUE	N/A	N	N	1965	1005		U	Unknown Not Lead (UNL)	(UNL)	11			N					101020
4143 HARLEM AVENUE 4108 OAK PARK AVENUE	N/A N/A	N N	N N	1965	1965		U	U	U	U			N					101820 101823
6825 40TH STREET	N/A	N	N				U	U	U	U			N					101824
4029 HARLEM AVENUE	N/A	N	N	1973	1973		U	U	U	U			N					101829
4023 HARLEM AVENUE 4003 HARLEM AVENUE	N/A N/A	N N	N N				U	U	U	U			N N					101830 101831
6905 PERSHING ROAD	N/A	N	N	1995	1995		U	U	U	U			N					101843
7122 40TH STREET	N/A	N	N				U	U	U	U			N					101848
4201 HARLEM AVENUE	N/A	N N	N N	1005	1005		U	U	U	U			N					101850
4209 HARLEM AVENUE 4211 HARLEM AVENUE	N/A N/A	N N	N N	1996 1996	1996 1996		U	U	U	U			N N					101853 101854
4217 HARLEM AVENUE	N/A	N	N				U	U	U	U			N					101856
4227 HARLEM AVENUE	N/A	N	N	1941	1941		U	U	U	U			N					101859
4235 HARLEM AVENUE	N/A N/A	N Y	N N				U	U	U	U			N N					101861
6800 43RD STREET 4307 HARLEM AVENUE	N/A N/A	N N	N N				U	U	U	U			N					101863 101872
6805 43RD STREET	N/A	N	N	1959	1959		U	U	U	U			N					101877
4100 JOLIET AVENUE	N/A	N	N				U	U	U	U			N					101878
3740 CICERO AVENUE 4100 JOLIET AVE	N/A N/A	N N	N N				U	U	U	U			N N					101882 101884
4950 PERSHING ROAD	N/A	N	N				U	U	U	U			N					101893
3900 LARAMIE AVENUE	N/A	N	N				U	U	U	U			N					101894
3900 LARAMIE AVE	N/A	N	N				U	U	U	U			N					101895
3900 LARAMIE AVE 4100 LARAMIE AVENUE	N/A N/A	N N	N N				U	U	U	U			N N					101896 101897
4100 CICERO AVENUE	N/A	N	N				U	U	U	U			N					101898
5000 41ST STREET EAST	N/A	N	N				U	U	U	U			N					101899
3910 CICERO AVENUE	N/A	N	N				U	U	U	U			N					101901
3800 LARAMIE AVENUE 37TH & LARAMIE AVE WEST	N/A N/A	N N	N N				U	U	U	U			N N					101904 101906
37TH & CICERO AVENUE EAST	N/A	N	N				U	U	U	U			N					101907
4232 WISCONSIN AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					101934
3924 ELMWOOD AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					101943
4028 GROVE AVENUE 3926 GROVE AVENUE	N/A N/A	N N	N N	1949 1964	1949 1964		U	U	U	U			N N					101945 101946
3928 GROVE AVENUE	N/A	N	N	1964	1964		U	U	U	U			N					101953

							Lead Ser	vice Line Inver	ntory Temp	late								
*Please enter information in the empty box next to each section	Water	System Nai	me		Stickne	ξλ	System	ID Number:	IL03	13000	Current Inven	ntory Date:	4/15,	/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotn	y.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". / If address is not a lead and copper sample site mark "N/A"	Group Homes, Parks, Playgrounds Special Care Facilities, Hospitals Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacemnt (GRR) Unknown (U) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
6629 41ST STREET	N/A	N	N	1978	1978		U	U	U	U			N					101959
4146 ELMWOOD AVENUE	N/A	N	N	1967	1967		U	U	U	U			N					101960
4119 SCOVILLE AVENUE	N/A	N N	N N	1955	1955		U	U	U	U			N N					101974
3917 EAST AVENUE	N/A N/A	N N	N N	1956 1968	1956 1968		U	U	U	U			N N					101976 101978
4001 OAK PARK AVENUE 3944 RIDGELAND AVENUE	N/A N/A	N N	N N	1954	1958		U	U	U	II.			N N					101978
6503 PERSHING ROAD	N/A	N	N	1934	1934		U	U	U	U			N					101994
4104 WENONAH AVENUE	N/A	N	N	1930	1930		U	U	U	U U			N					101997
7025 W. 43 RD ST	N/A	N	N	1955	1955		U	U	U	U			N					102000
4446 S GROVE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					102001
4117 HOME AVENUE	N/A	N	N	1988	1988		U	U	U	U			N					102013
3932 CLINTON AVENUE	N/A	N	N	1919	1919		U	U	U	U			N					102014
4430 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					102016
4231 HARLEM AVENUE	N/A	N	N				U	U	U	U			N					102017
4021 EAST AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					102023
4212 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					102028
4102 WISCONSIN AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					102030
4100 WISCONSIN AVENUE	LA1A016	N	N	1986	1986		U	U	U	U			N					102032
4101 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					102033
7048 40TH STREET	N/A	N	N	1947	1947		U	U	U	U			N					102034
4204 RIDGELAND AVENUE 4214 CLINTON AVENUE	N/A N/A	N N	N N	1944 1954	1944 1954		U	U	U	U			N N					102037 102046
4214 CLINTON AVENUE 4224 RIDGELAND AVENUE	N/A N/A	N N	N N	1954	1954		U	U	U	U			N N					102046
3914 SCOVILLE AVENUE	N/A N/A	N N	N N	1938	1938		U	U	U	U			N					102048
4431 KENILWORTH AVENUE	N/A	N N	N	1946	1946		U	U	U	U			N					102051
4229 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					102053
4425 HARLEM AVENUE	N/A	N	N				U	U	U	U			N					102055
4145 HOME AVENUE	N/A	N	N	1960	1960		U	U	U	U			N					102060
7008 40TH STREET	N/A	N	N	1947	1947		U	U	U	U			N					102064
4336 HOME AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					102066
4043 HARLEM AVENUE	N/A	N	N	2023	2023		U	U	U	U			N					102073
4215 MAPLE AVENUE	N/A	N	N	1926	1926		U	U	U	U			N					102074
6610 41ST STREET	N/A	N	N	1997	1997		U	U	U	U			N					102076
4137 SCOVILLE AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					102091
4353 GROVE AVENUE	N/A	N	N	1955	1955	Visual Inspection	U	U	U	U		9/27/2024	N					102092
4127 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U			N	<u> </u>	<u> </u>		1	102094

							Lead Ser	vice Line Inver	ntory Temp	late								
*Please enter information in the empty box next to each section	Water	System Nar	me		Stickne	ey .		ID Number:		13000	Current Inver	ntory Date:	4/15	/2025				
*Please enter totals in the empty box next to each category	Total Service	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	-line-inventory-1-novotny	.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	e Is this a high-risk Facility or Area?		Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Lead (L)					EXAMPLES:			
		Group Homes,					Copper - Lead Solder	Copper - Lead Solder (CLS)	Capper Load Solder	Galvanized Requiring Replacemnt (GRR)	If any galvanized service line material was ever downstream of a Lead				Copper - No Lead Solder (C)		IF austomor refused	
	Lead and Copper Sample site number is the 7 digit	Parks, Playgrounds, Special Care Facilities, Hospitals,	,			How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	section, mark Yes (Y). If the galvanized service line material was never	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		IF customer refused access to property, date waiver obtained	
	number starting with "LP" or " LA". / If address is not a lead and	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	What year was the customer side service line	Service Line Identified? EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N).	notified of Lead Service Line. /	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"		_	installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE,	Lead (L) Cast/Ductile Iron or	Lead (L) Cast/Ductile Iron or		If Yes, that section of service line should be marked as Galvanized Requiring Replacement in	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
		Yes (Y) or No (N)					PEX (P) Unknown (U)	Transite (O) Plastic - PVC, HDPE, PEX (P	Transite (O) Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding column(s).				Leave blank if no Lead		refused access.	
							Unknown Not Lead (UNL)	Unknown (U) Unknown Not Lead (UNL)	Unknown (U) Unknown Not Lead		column(s).				Service Line was replaced.			
4223 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					102095
4007 OAK PARK AVENUE	N/A	N	N	1981	1981		U	U	U	U			N					102110
3933 EUCLID AVENUE	N/A	N	N	1928	1928		U	U	U	U			N					102111
3916 EAST AVENUE	N/A	N	N	1925	1925		U	U	U	U			N					102114
7108 43RD STREET 3923 EAST AVENUE	N/A N/A	N N	N N	1955 1958	1955 1958		U	U	U	U			N N					102115
4230 CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					102136
4436 MAPLE AVENUE	N/A	N	N	1998	1998		U	U	U	U			N					102139
4213 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					102141
4341 CLINTON AVENUE	N/A	N	N	1964	1964		U	U	U	U			N					102142
4223 HOME AVENUE 4014 EAST AVENUE	N/A N/A	N N	N N	1962 1955	1962 1955		U	U	U	U			N N					102143
4017 SCOVILLE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					102145
4334 GROVE AVENUE	N/A	N	N	1946	1946		U	U	U	U			N					102154
4233 HOME AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					102155
3940 CLARENCE AVENUE	N/A	N N	N N	1940	1940		U	U	U	U			N					102156
4014 RIDGELAND AVENUE 4112 GROVE AVENUE	N/A N/A	N N	N N	1956 1950	1956 1950		U	U	U	U			N N					102159 102160
4112 CLINTON AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					102162
7030 43RD STREET	N/A	N	N	1957	1957		U	U	U	U			N					102164
3939 EUCLID AVENUE	N/A	N	N	1926	1926		U	U	U	U			N					102165
7129 40TH PLACE 4115 GROVE AVENUE	N/A N/A	N N	N N	1925 1960	1925 1960		U	U	U	U			N N					102166 102170
3911 WESLEY AVENUE	N/A N/A	N N	N N	1960	1960		U	U	U	U			N					102170
4430 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					102175
4214 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					102180
5041 PERSHING ROAD	N/A	N	N				U	U	U	U			N 					102182
3936 HOME AVENUE 7109 40TH STREET	N/A N/A	N N	N N	1947 1975	1947 1975		U	U	U	U			N N					102187
4018 SCOVILLE AVENUE	N/A N/A	N N	N N	1975	1975		U	U	U	U			N					102188
3908 HOME AVENUE	N/A	N	N	1947	1947		U	U	U	U			N					102198
4142 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					102200
4313 MAPLE AVENUE	N/A	N	N	1961	1961		U	U	U	U			N					102205
4018 RIDGELAND AVENUE	N/A	N N	N N	1957	1957		U	U	U	U			N					102206
4455 HARLEM AVENUE 4455 HARLEM AVE	N/A N/A	N N	N N	1999	1999		U	U	U	U			N N					102207 102208
4455 HARLEM AVE	N/A	N N	N N	1999	1999	1	U	l u	l u	L U	l .		N	1				102208

							Lead Ser	vice Line Inver	ntory Temp	late								
*Please enter information in the empty box next to each section	Water	System Nai	me		Stickne	ey .		ID Number:		13000	Current Inven	ntory Date:	4/15,	/2025				
*Please enter totals in the empty box next to each category	Total Servic	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotn	y.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	t Line was	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	5, 5, Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacemnt (GRR) Unknown (U) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4455 HARLEM AVE	N/A	N	N	1999	1999		U	U	U	U			N					102209
4455 HARLEM AVE	N/A	N	N	1999	1999		U	U	U	U			N					102210
4455 HARLEM AVE UNIT 3N	N/A	N	N	1999	1999		U	U	U	U			N					102211
4453 HARLEM AVENUE	N/A	N	N	2000	2000		U	U	U	U			N					102213
4453 HARLEM AVE	N/A	N	N	2000	2000		U	U	U	U			N					102214
4453 HARLEM AVE UNIT 3S	N/A	N	N	1999	1999		U	U	U	U			N					102215
4453 HARLEM AVENUE	N/A	N	N	1999	1999		U	U	U	U			N					102216
4453 HARLEM AVENUE	N/A	N N	N N	2000	2000		U	U	U	U			N N					102217
4453 HARLEM AVE 4016 GROVE AVENUE	N/A N/A	N N	N N	2000 1919	2000 1919		U II	U	U II	U II			N N					102218
4016 GROVE AVENUE 4425 GROVE AVENUE	N/A N/A	N N	N N	1919	1919		U	U	U	U			N N					102229 102236
7127 40TH STREET	N/A	N	N	1929	1922		U	U	U	U			N					102238
7112 41ST STREET	N/A	N	N	1917	1917		U U	U	U	U			N					102245
4111 SCOVILLE AVENUE	N/A	N	N N	1957	1957		U	U	U	U			N					102250
4107 MAPLE AVENUE	N/A	N	N	1927	1927		U	U	U	U			N					102254
4044 GROVE AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					102255
3913 ELMWOOD AVENUE	N/A	N	N	1926	1926		U	U	U	U			N					102256
6637 41ST STREET	N/A	N	N	1978	1978		U	U	U	U			N					102257
3946 GUNDERSON AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					102260
7125 40TH PLACE	N/A	N	N	1954	1954		U	U	U	U			N					102262
4205 WISCONSIN AVENUE	N/A	N	N	1951	1951		U	U	U	U			N					102264
4208 GROVE AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					102265
4128 WENONAH AVENUE	N/A	N	N	1949	1949		U	U	U	U			N					102269
4012 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					102272
4319 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					102273
4013 WESLEY AVENUE	N/A	N	N	1959	1959		U	U	U	U			N					102275
4225 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					102279
7022 41ST STREET	LP1C105 N/A	N N	N N	1942 1960	1942 1960		U	U	U	U			N N					102284
4329 MAPLE AVENUE 4102 OAK PARK AVENUE	N/A N/A	N N	N N	1960 1926	1960 1926		U	U	U	U			N N					102290 102291
6933 PERSHING ROAD	N/A	N N	N N	1926	1926		U	U	U	U			N N					102291
4124 CLINTON AVENUE	N/A	N N	N	1958	1958		U	U	U	U			N N					102294
4318 WISCONSIN AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					102303
3915 EAST AVENUE	N/A	N	N	1955	1955	Visual Inspection	U	U	С	U			N					102311
4212 SCOVILLE AVENUE	N/A	N	N	1916	1916	The state of the s	U	U	U	U			N					102317
4245 GUNDERSON AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					102322

							Lead Sen	vice Line Inver	ntory Temp	late								
*Please enter information in the empty	\M/ator	System Na	mo		Stickno						Current Inven	story Data:	4/15,	/2025				
box next to each section	water	System Na	me T		Stickne	ey T	System	ID Number:		13000	Current Inver	itory Date:						
*Please enter totals in the empty box next to each category	Total Service	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722	Website link Inver	c to Material ntory:	https://lead-service	e-line-inventory-1-novotn	/.hub.arcgis.com/	
					l	l				l					•			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?		Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service							
		Group Homes, Parks, Playgrounds					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead				Copper - No Lead Solder (C)		IF customer refused	
	Lead and Copper Sample	Special Care Facilities, Hospitals				How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	section, mark Yes (Y). If the galvanized service line material was never	Enter date		If previous column was	Galvanized (G)		access to property, date waiver obtained	
	site number is the 7 digit number starting with "LP"	Clinics, Child Care Facilities		What year was the PWS-Owned	What year was the customer side	Service Line Identified? EXAMPLES: Construction		Galvanized Requiring	Galvanized		downstream of any Lead section, mark No (N).	customer was notified of Lead		marked (Y), provide date the Lead Service Line was			by PWS or date PWS notified IDPH of	
	or " LA". / If address is not a lead and	i demities	Yes (Y) or No (N)	service line	service line installed, if known?	Records, Visual Inspections, Survey Response,	Lead (L)	Replacemnt (GRR)	Requiring Replacemnt (GRR)	Non-Lead (NL)	/ If Yes, that section of	Service Line.	Yes (Y) or No (N)	replaced. /	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	refusal to sign waiver.	
	copper sample site mark "N/A"					Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L) Cast/Ductile Iron or	Lead (L)		service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
							Plastic - PVC, HDPE, PEX (P)	Transite (O)	Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE,		Requiring Replacement in the appropriate						refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (P) Unknown (U)	PEX (P) Unknown (U)		immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
5050 39TH STREET	N/A	N	N				U	U	U	U			N					102326
4111 HOME AVENUE 7044 40TH PLACE	N/A N/A	N N	N N	1953 1928	1953 1928		U	U	U	U			N N					102327 102328
4137 ELMWOOD AVENUE	N/A N/A	N N	N N	1928	1928		U	U	U	U			N N					102328
4338 S KENILWORTH AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					102337
7014 40TH PLACE	N/A	N	N	1927	1927		U	U	U	U			N					102339
4111 WISCONSIN AVENUE 4110 CLINTON AVENUE	N/A N/A	N N	N N	1924 1954	1924 1954	Visual Inspection	U	U U	C	U			N N					102340 102341
4036 RIDGELAND AVENUE	N/A	N	N	1956	1956	Visual hispection	U	U	U	U			N					102342
6901 43RD STREET	N/A	N	N	1992	1992		U	U	U	U			N					102347
4141 GUNDERSON AVENUE	N/A	N	N	1913	1913		U	U	U	U			N					102348
4301 MAPLE AVENUE 4336 WISCONSIN AVENUE	N/A N/A	N N	N N	1959 1959	1959 1959		U	U	U	U			N N					102350 102351
4205 SCOVILLE AVENUE	N/A	N	N	1921	1921		U	U	U	U			N					102353
4443 KENILWORTH AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					102354
4420 OAK PARK AVENUE 6727 PERSHING ROAD	N/A N/A	N N	N N	1953	1953		U	U	U	U			N N					102356
4005 GUNDERSON AVENUE	N/A N/A	N N	N N	1927	1927		U	U	U	U			N N					102361 102362
7119 40TH PLACE	N/A	N	N	1955	1955		U	U	U	U			N					102364
6641 41ST STREET	N/A	N	N	1979	1979		U	U	U	U			N					102369
4317 HARLEM AVENUE 6921 43RD STREET	N/A N/A	N N	N N	1954	1954		U	U	U	U			N N					102372 102374
4219 ELMWOOD AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					102379
4132 OAK PARK AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					102385
4208 WENONAH AVENUE 3943 WESLEY AVENUE	N/A N/A	N	N N	1955 1960	1955 1960		U	U	U	U			N N					102391 102394
4117 GROVE AVENUE	N/A N/A	N N	N N	1960	1960		U	U	U	U			N N					102394
4310 WISCONSIN AVENUE	N/A	N	N	1960	1960		U	U	U	U			N					102400
7018 41ST STREET	N/A	N	N	1931	1931		U	U	U	U			N					102401
7118 40TH PLACE 4223 MAPLE AVENUE	N/A N/A	N N	N N	1924 1920	1924 1920		U	U	U	U			N N					102402
4118 GROVE AVENUE	N/A N/A	N	N	1920	1920		U	U	U	U			N					102406
6701 PERSHING ROAD	N/A	N	N				U	U	U	U			N					102407
6623 41ST STREET	N/A	N	N	1978	1978		U	U	U	U			N					102410
4138 HOME AVENUE 4124 ELMWOOD AVENUE	N/A N/A	N N	N N	1930 1949	1930 1949		U	U U	U	U			N N					102414 102415
4124 ELINIWOOD AVENUE	N/A	N	IN IN	1949	1949]	l 0	J 0	l 0	υ			I N	l			1	102415

	1			1			Lead Ser	vice Line Inve	ntory Temp T	late								
*Please enter information in the empty box next to each section	Water	System Na	me		Stickne	ey	System	ID Number:		13000	Current Inve	ntory Date:	·	/2025				
*Please enter totals in the empty box next to each category	t Total Servic	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Gal Requiring re		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	y.hub.arcgis.com/	
														,				
			, Service Line Newly	Year PWS-	Year Customer				Customer Side	Classification for	Was Galvanized	Date Customer	Was a Lead Service Line			Has the customer	Date of customer waiver	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last Submitted Inventory	Owned Service Line was Installed	Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Service Line Material	Entire Serivice Line	Service Line Material ever downstream of Lead?	Notified of Lead Service Line	Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	refused access to the property?	or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Solder (C)	(C)	Solder (C) Copper - Lead Solde	Lead (L) r Galvanized Requiring	If any galvanized service line material was ever				Copper - No Lead Solder (C)			
	Lead and Copper Sample	Group Homes, Parks, Playgrounds Special Care	;,				Copper - Lead Solde (CLS)	Copper - Lead Solder (CLS	(CLS)	Replacemnt (GRR)	downstream of a Lead section, mark Yes (Y). If the galvanized service line	Enter date		15			IF customer refused access to property,	
	site number is the 7 digit number starting with "LP"	Facilities, Hospitals Clinics, Child Care	s,	What year was the	What year was the	How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never downstream of any Lead	customer was notified of Lead		If previous column was marked (Y), provide date the Lead Service Line was	Galvanized (G)		date waiver obtained by PWS or date PWS	
	or " LA". / If address is not a lead and	Facilities	Yes (Y) or No (N)	PWS-Owned service line installed if known?	customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey Response,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	section, mark No (N). / If Yes, that section of	Service Line. /	Yes (Y) or No (N)	replaced. /	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	notified IDPH of refusal to sign waiver	
	copper sample site mark "N/A"			motanea, mano um	mstanca, m known.	Maintenance Records, etc	Cast/Ductile Iron of Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
							Plastic - PVC, HDPE PEX (P)	, Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron of Transite (O)	•	Requiring Replacement in the appropriate						refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (I) Plastic - PVC, HDPE PEX (P)	•	immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown (U)	Unknown (U) Unknown Not Lead						Service Line was replaced.			
3914 OAK PARK AVENUE	N/A	N	N	1953	1953		U	Unknown Not Lead (UNL	(UNL)	11			N					102419
4208 WISCONSIN AVENUE	N/A	N	N N	1933	1933		U	U	U	U			N					102419
3901 HOME AVENUE	N/A	N	N	1950	1950		U	U	U	U			N					102427
4118 RIDGELAND AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					102436
4107 HOME AVENUE 4436 CLINTON AVENUE	N/A N/A	N N	N N	1953 1954	1953 1954		U	U	U	U			N N					102438 102439
4216 WISCONSIN AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					102446
6611 PERSHING ROAD	N/A	N	N	1924	1924		U	U	U	U			N					102447
4220 OAK PARK AVENUE 4115 SCOVILLE AVENUE	N/A N/A	N N	N N	1929 1919	1929 1919		U	U	U	U			N N					102449 102452
5030 39TH STREET	N/A	N	N	1313	1313		U	U	U	U			N					102455
7029 40TH PLACE	N/A	N	N	1956	1956		U	U	U	U			N					102459
4332 WISCONSIN AVENUE	N/A	N	N	1959	1959		U	U	U	U			N					102461
6429 PERSHING ROAD 4434 OAK PARK AVENUE	N/A N/A	N N	N N	1949	1949		U	U	U	U			N N					102462 102463
3928 EUCLID AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					102466
3913 OAK PARK AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					102468
4316 WENONAH AVENUE 3931 OAK PARK AVENUE	N/A N/A	N N	N N	1955 1954	1955 1954		U	U	U	U			N N					102469 102471
4213 GROVE AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					102471
3940 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					102474
4207 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					102476
7036 40TH STREET 6426 41ST STREET	N/A N/A	N N	N N	1947 1954	1947 1954		U	U	U	U			N N					102484 102492
4303 HARLEM AVENUE	N/A	N	N				U	U	U	U			N					102493
3936 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					102494
4415 CLINTON AVENUE 3932 RIDGELAND AVENUE	N/A N/A	N N	N N	1955 1957	1955 1957		U	U	U	U			N N					102498 102500
6831 43RD STREET	N/A	N N	N N	1957	1957		U	U	U	U			N					102508
3940 OAK PARK AVENUE	N/A	N	N	1909	1909		U	U	U	U			N					102510
4211 GROVE AVENUE	N/A	N	N	1926	1926		U	U	U	U			N					102512
4019 EUCLID AVENUE 3920 HOME AVENUE	N/A N/A	N N	N N	1959 1947	1959 1947		U	U	U	U			N N					102516 102519
3923 ELMWOOD AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					102511
3908 GUNDERSON AVENUE	N/A	N	N				U	U	U	U			N					102523
6600 41ST STREET	N/A	N	N	1955	1955		U	U	U	U			N					102526

Total Service International Principles Walter Spaces Name																			
Proceedings Process					·			Lead Ser	vice Line Inve	ntory Temp	late			I					
March Marc		Water	System Nai	me		Stickne	ey .	System			13000	Current Inve	ntory Date:	-					
Part		Total Service	e lines:	1904	Total Lead:	71	Total Non-Lead:	111			0		1722			https://lead-service	e-line-inventory-1-novotny	y.hub.arcgis.com/	
Marie Mari																			
Transfer Transfer	Service Address Le	ead and Copper Sample	Is this a high-risk	and the same of th	Owned Service	Side Service Line				Service Line	Entire Serivice	Service Line Material	Notified of Lead	Previously Replaced at			refused access to the	or IDPH notification, if	Water Account Number
March Marc		510 1101113211		Submitted Inventory	Installed	was Installed				Material	Line		Service Line	this Location?			property?	to property	
Part			EXAMPLES:					Copper - No Lead		Copper - No Lead						EXAMPLES:			
Column C			Group Homes							Copper - Lead Solds		line material was ever				Copper - No Lead Solder (C)			
Second Control Contr	L		Parks, Playgrounds, Special Care				How was the Material of this			(CLS)		section, mark Yes (Y). If the galvanized service line	Enter date		If previous column was	Calvariand (C)		access to property,	
Part	n	number starting with "LP"	Clinics, Child Care	Vos (V) oz No (N)			Service Line Identified?		, ,	Galvanized	, ,	downstream of any Lead	notified of Lead	Vos (V) or No (N)	marked (Y), provide date the Lead Service Line was		Vos (V) or No (N)	by PWS or date PWS	
Part	If	f address is not a lead and copper sample site mark		162 (1) OF NO (N)			Survey Response,		Replacemnt (GRR)	Replacemnt (GRR)	Non-Lead (NL)		/ If Service Line is not	res (1) Of NO (N)	/ Leave blank if previous		res (1) OF NO (N)	/	
Part		"N/A"					Waliterlance Records, etc	Transite (O) Plastic - PVC, HDPE	, Cast/Ductile Iron or	Cast/Ductile Iron or		marked as Galvanized Requiring Replacement in	Lead put N/R		column was (N).			customer has not	
Add CANTON CANADA No. No. 1.095			Yes (Y) or No (N)					Unknown (U)	Plastic - PVC, HDPE, PEX (I	Plastic - PVC, HDPE PEX (P)		immediately preceding							
### Control NA								(UNL)	1 '	Unknown Not Lead									
Anti-Control Print Part	4219 CLINTON AVENUE	N/A	N	N	1956	1956		U			U			N					102530
Control Cont		•	N	N			Visual Inspection	U	U	С	U			N					102534
ADD MERCHAN ANNIE No. No. No. 190 190 U U U U U U U U U		•							-		-								102540
Column C		·																	102542
SOUR PROGRAM PARTIEL NA N 3284 3864 U U U U U U U U U		,						-	-	-	-								102549 102552
### AND PRODUCTION PARTIES NA		·																	102553
MARKASTINIST N/A N	4344 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					102554
### ASSENTING PROPERTY NAME	4102 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					102555
### ### ### ### ### ### ### ### ### ##		·																	102556
### ASPA CAM PARK AND METER NAME NOR NOR 1922 1922 U. U. U. U. U. U. U. W. W. N.		,																	102561
### ### ### ### ### ### ### ### ### ##		·							-										102566 102568
### T100 DELINE FORCE N/A N N 1948 1948 U U U U U U U U U	120701111111111111111111111111111111111	•	.,	.,		-			-										102570
4120 ELIMINODO AVENUE	4014 OAK PARK AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					102574
7019 40TH STREET	7100 40TH STREET	N/A	N	N	1948	1948		U	U	U	U			N					102576
3927 SCOVILE AVENUE		,																	102577
4220 WENDNAH AVENUE N/A N N 1952 1952 U U U U U U U N N N 1955 1955 U U U U U U U U N N N N 1955 1955 U U U U U U U U U U N N N N 1955 1956 U U U U U U U U U U U U U U U U U U U		,																	102578 102580
3940 RIDGELAND AVENUE N/A N N 1955 1955 U U U U U U U N N N N 1954 1955 U U U U U U U N N N N N N 1955 1955 U U U U U U U N N N N N N N 1955 1955 U U U U U U U U N N N N N N N 1955 1955 U U U U U U U U U U U U U U U U U U		•								_									102580
7136 40TH PLACE N/A N N 1925 1925 U U U U U U U N N N 1956 1955 U U U U U U U U N N N N 1957 1958 U U U U U U U U U U N N N N N 1958 1955 U U U U U U U U U U U U U U U U U U		,						_	-	_									102587
4314 CLINTON AVENUE N/A N N 1924 1924 U U U U U U N N N N 1919 1919 U U U U U U U N	7136 40TH PLACE	N/A	N	N	1925	1925		U	U	U	U			N					102590
## 4027 CLINTON AVENUE N/A N N 1919 1919 U U U U U U N N N 1956 1956 U U U U U U N N N N N N N 1956 1956 U U U U U U U U N N N N N N N N N N N		•	N	N	1955	1955		U	U	U	U			N					102601
7025 40TH PLACE N/A N N 1956 1956 U U U U U U U N									-	-									102609
6505 PERSHING ROAD																			102611
4141 ELMWOOD AVENUE N/A N N 1955 1955 U					1950	1956			-	_									102624 102626
TO53 40TH STREET					1955	1955					, ,								102631
4027 SCOVILLE AVENUE N/A N N 1955 1955 U U U U U U N N N N 1924 1924 U U U U U U U U N N N N 1930 1930 U		,	N					U		U									102632
4106 HOME AVENUE N/A N N 1924 1924 U U U U U N N N 1930 1930 1930 U U U U U U N N N N 1979 1979 1979 U U U U U U N N N N N N 1979 1979 U U U U U U U N	7017 40TH PLACE	N/A	N	N	1977	1977		U	U	U	U			N					102636
4232 ELMWOOD AVENUE N/A N N 1930 1930 U U U U U N N N N 1979 1979 U U U U U U N N N N N N 1979 1979 U U U U U U N			N	N	1955	1955		U	U	U	U			N					102638
4014 SCOVILLE AVENUE N/A N N 1979 1979 U U U U U N N			.,						-	_	_								102640
					1			-			-								102641
		,							-	_									102642 102647
6621 PERSHING ROAD N/A N N N U U U U N N		·			1300	1333			-		-								102647

				Т			Lead Ser	vice Line Inve	ntory Temp	late								
*Please enter information in the empty box next to each section	Water	System Nai	me		Stickne	2y	System	ID Number:		13000	Current Inver	ntory Date:	·	/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Gal Requiring re		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Solder (C)	(C)	Solder (C)	Lead (L)	If any galvanized service				Canada Na Land Caldes (C)			
		Group Homes, Parks, Playgrounds	,				Copper - Lead Solde (CLS)	Copper - Lead Solder (CLS	Copper - Lead Solde (CLS)	r Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If				Copper - No Lead Solder (C)		IF customer refused	
	Lead and Copper Sample site number is the 7 digit	Special Care Facilities, Hospitals	,			How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		access to property, date waiver obtained	
	number starting with "LP" or " LA". / If address is not a lead and	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line	customer side service line	Service Line Identified? EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring	Non-Lead (NL)	downstream of any Lead section, mark No (N). /	notified of Lead Service Line. /	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron of	Lead (L)	Replacemnt (GRR)		If Yes, that section of service line should be marked as Galvanized	/ If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite		/ Leave blank if	
	,		1				Plastic - PVC, HDPE PEX (P)	, Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron of Transite (O)	•	Requiring Replacement in the appropriate	,			(0)		customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (F	Plastic - PVC, HDPE PEX (P)		immediately preceding column(s).				Leave blank if no Lead			
							(UNL)	Unknown (U)	Unknown (U) Unknown Not Lead		(.,				Service Line was replaced.			
4442 GROVE AVENUE	N/A	N	N	1951	1051		U	Unknown Not Lead (UNL)	(UNL)	11			N					102649
4200 HOME AVENUE	N/A N/A	N N	N N	1951	1951 1955		U	U	U	U			N					102649
4407 WISCONSIN AVENUE	N/A	N	N	1930	1930		U	U	U	U			N					102657
4004 CLARENCE AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					102660
4137 MAPLE AVENUE 3920 SCOVILLE AVENUE	N/A N/A	N N	N N	1957 1954	1957 1954		U	U	U	U			N N					102661 102663
6620 41ST STREET	N/A	N	N	1919	1919		U	U	U	U			N					102664
4135 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U			N					102670
4211 WISCONSIN AVENUE 3937 CLINTON AVENUE	N/A	N N	N N	1954	1954		U	U	U	U			N N					102672
4023 SCOVILLE AVENUE	N/A N/A	N N	N N	1950 1956	1950 1956		U	U	U	U			N N					102681 102687
4109 GROVE AVENUE	N/A	N	N	1959	1959		U	U	U	U			N					102689
4141 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					102690
4020 CLARENCE AVENUE 3937 GUNDERSON AVENUE	N/A N/A	N N	N N	1953 1955	1953 1955		U	U	U	U			N N					102701 102709
3930 OAK PARK AVENUE	N/A	N N	N	1926	1926		U	U	U	U			N					102711
4209 MAPLE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					102712
4995 PERSHING ROAD	N/A	N	N	465.	405.1		U	U	U	U			N N					102714
4324 HOME AVENUE 4209 CLINTON AVENUE	N/A N/A	N N	N N	1954 1956	1954 1956		U	U	U	U			N N					102715 102720
7000 43RD STREET	N/A	N	N	1950	1950		U	U	U	U			N					102721
4130 GROVE AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					102723
7104 43RD STREET 4107 WISCONSIN AVENUE	N/A N/A	N N	N N	1959 1924	1959 1924		U	U	U	U			N N					102726 102727
4111 CLINTON AVENUE	N/A	N N	N N	1950	1950		U	U	U	U			N					102727
4025 CLINTON AVENUE	N/A	N	N	1914	1914		U	U	U	U			N					102738
4237 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					102744
4112 MAPLE AVENUE 4311 HARLEM AVENUE	N/A N/A	N N	N N	1961	1961		U	U	U	U			N N					102748 102750
4038 CLARENCE AVENUE	N/A	N	N	1962	1962		U	U	U	U			N					102756
3933 GUNDERSON AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					102759
4240 MAPLE AVENUE	N/A	N N	N N	1973	1973		U	U	U	U			N N					102763
4227 HOME AVENUE 4406 CLINTON AVENUE	N/A N/A	N N	N N	1986 1954	1986 1954		U	U	U	U			N N					102765 102778
4133 MAPLE AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					102779
3917 EUCLID AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					102794

										1 .								
				1			Lead Ser	vice Line Inve	ntory Temp T	late								
*Please enter information in the empty box next to each section	Water	System Nai	me		Stickne	ey .	System	ID Number:		13000	Current Inver	ntory Date:	·	/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Gal Requiring re		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	y.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	, Line was	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
				Installed	was instanca				Widterial	Emc	Lead?	Service Eme				proposol.	to property	
		EXAMPLES:					EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Lead (L)					EXAMPLES:			
		Group Homes, Parks, Playgrounds	,				Copper - Lead Solde (CLS)	Copper - Lead Solder (CLS	Copper - Lead Solde (CLS)	r Galvanized Requiring Replacemnt (GRR)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If				Copper - No Lead Solder (C)		IF customer refused	
	Lead and Copper Sample site number is the 7 digit	Special Care Facilities, Hospitals	,			How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		access to property, date waiver obtained	
	number starting with "LP" or " LA". / If address is not a lead and	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line	customer side service line	Service Line Identified? EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N).	notified of Lead Service Line.	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver	
	copper sample site mark			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron of	Lead (L)	Lead (L)		If Yes, that section of service line should be	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite		/ Leave blank if	
	,,,						Plastic - PVC, HDPE PEX (P)	, Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		marked as Galvanized Requiring Replacement in the appropriate	zeda pac ny n			(0)		customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U)	Plastic - PVC, HDPE, PEX (F	Plastic - PVC, HDPE PEX (P)	,	immediately preceding column(s).				Leave blank if no Lead			
		(.,					Unknown Not Lead (UNL)	Unknown (U)	Unknown (U) Unknown Not Lead		column(s).				Service Line was replaced.			
								Unknown Not Lead (UNL)	(UNL)									
4332 CLINTON AVENUE 4019 ELMWOOD AVENUE	N/A N/A	N N	N N	1931 1927	1931 1927		U	U	U	U			N N					102799 102804
6713 41ST STREET	N/A	N	N	1978	1978		U	U	U	U			N					102807
7048 41ST STREET	N/A	N	N	1950	1950		U	U	U	U			N					102808
4117 WISCONSIN AVENUE 4342 WISCONSIN AVENUE	N/A N/A	N N	N N	1958 1959	1958 1959		U	U	U	U			N N					102809 102812
4041 HARLEM AVENUE	N/A	N N	N N	1939	1939		U	U	U	U			N					102815
3917 SCOVILLE AVENUE	N/A	N	N	1932	1932		U	U	U	U			N					102818
4008 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					102826
6722 41ST STREET 4426 GROVE AVENUE	N/A N/A	N N	N N	1919 1986	1919 1986		U	U	U	U			N N					102828 102830
4236 S RIDGELAND AVENUE	N/A	N	N	1965	1965		U	U	U	U			N					102839
3937 OAK PARK AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					102845
7021 40TH PLACE	N/A	N	N	1960	1960		U	U	U	U			N					102859
3926 S EUCLID AVENUE 4330 HOME AVENUE	N/A N/A	N N	N N	1948 1951	1948 1951		U	U	U	U			N N					102867 102868
4130 ELMWOOD AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					102869
4220 GROVE AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					102870
3925 SCOVILLE AVENUE	N/A N/A	N N	N N	1956 1957	1956 1957		U	U	U	U			N N					102871 102872
4140 ELMWOOD AVENUE 5001 W 40TH STREET	N/A N/A	N N	N N	193/	122/		U	U	U	U			N N					102872
4142 OAK PARK AVENUE	N/A	N	N	1919	1919		U	U	U	U			N					102879
4030 EUCLID AVENUE	N/A	N	N	1928	1928		U	U	U	U			N					102881
4134 RIDGELAND AVENUE 4218 RIDGELAND AVENUE	N/A N/A	N N	N N	1956 1957	1956 1957		U	U	U	U			N N					102884 102885
4425 WENONAH AVENUE	N/A	N	N	1928	1928		U	U	U	U			N					102887
7122 43RD STREET	N/A	N	N	1954	1954		U	U	U	U			N					102889
4323 HARLEM AVENUE	N/A	N	N				U	U	U	U			N					102892
4323 GROVE AVENUE 3924 CLINTON AVENUE	N/A N/A	N N	N N	1925 1959	1925 1959		U	U	U	U			N N					102901 102904
4452 GROVE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					102905
4320 OAK PARK AVENUE	N/A	N	N	1948	1948		U	U	U	U			N					102916
3923 CLINTON AVENUE	N/A	N	N N	1950	1950		U	U	U	U			N					102923
3935 EAST AVENUE 7026 40TH PLACE	N/A N/A	N N	N N	1955 1978	1955 1978		U	U	U	U			N N					102924 102928
4428 OAK PARK AVENUE	N/A	N	N	1987	1987		U	U	U	U			N					102932

							Lead Ser	vice Line Inver	itory Temp	late								
*Please enter information in the empty box next to each section	Water	System Nai	me		Stickne	žλ	System	ID Number:	IL03	13000	Current Inven	ntory Date:	4/15,	/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		c to Material ntory:	https://lead-service	e-line-inventory-1-novotn	y.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	t	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized (G) Galvanized (G) Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacemnt (GRR) Unknown (U) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4217 WISCONSIN AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					102936
4225 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					102938
7022 40TH PLACE	N/A	N	N	1933	1933		U	U	U	U			N					102939
4142 WISCONSIN AVENUE	N/A	N N	N	1951	1951		U	U	U	U			N					102940
4114 GROVE AVENUE 4131 WENONAH AVENUE	N/A N/A	N N	N N	1945 1955	1945 1955		U	U	U	U			N N					102943 102949
7023 43RD STREET	N/A N/A	N N	N N	1955	1955		U	U	U	U			N N					102949
4021 OAK PARK AVENUE	N/A N/A	N N	N	1958	1958		U	U	II	U			N N					102951
3925 OAK PARK AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					102972
4313 HARLEM AVENUE	N/A	N	N	1936	1938		II.	U	II	ii ii			N					102977
4129 MAPLE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					102977
7042 43RD STREET	N/A	N	N	1954	1954		U	U	U	U			N					102984
4339 S GROVE AVENUE	N/A	N	N	1946	1946		U	U	U	U			N					102988
4142 S CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					102990
4215 HARLEM AVENUE	N/A	N	N				U	U	U	U			N					102993
4017 HOME AVENUE	N/A	N	N	1933	1933		U	U	U	U			N					102997
4153 MAPLE AVENUE	N/A	N	N	1950	1950		U	U	U	U			N					103002
4210 HOME AVENUE	N/A	N	N	1948	1948		U	U	U	U			N					103004
4315 HARLEM AVENUE	N/A	N	N				U	U	U	U			N					103007
4409 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					103010
4404 MAPLE AVENUE	N/A	N	N	1987	1987		U	U	U	U			N					103011
4142 RIDGELAND AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103014
6603 PERSHING ROAD	N/A	N N	N	1964	1964		U	U	U	U			N					103023
6601 PERSHING ROAD	N/A	N N	N	1964	1964		U	U	U	U			N N					103024
7014 41ST STREET.	N/A N/A	N N	N N	1913	1913		U	U	U	U			N N					103028
4235 SCOVILLE AVENUE 6507 PERSHING ROAD	N/A N/A	IN N	N N	1953	1953		U	U	U	U			N N					103031 103032
3931 GUNDERSON AVENUE	N/A N/A	N N	N N	1955	1955		U	U	U	U			N N					103032
4313 KENILWORTH AVENUE	N/A N/A	N	N	1966	1966		U	U	U	U			N N					103038
6733 PERSHING ROAD	N/A	N	N	1926	1926		U	U	U	U			N					103038
7026 43RD STREET	N/A	N	N	1953	1953		U	U	U	U			N					103039
4404 KENILWORTH AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103041
4144 S MAPLE AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103047
4209 SCOVILLE AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					103049
7033 43RD STREET	N/A	N	N	1955	1955	_	U	U	U	U			N					103051
4215 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103052

	1			Т			Lead Ser	vice Line Inve	ntory Temp	late	l							
*Please enter information in the empty box next to each section	Water	System Na	me		Stickne	ey .	System	ID Number:		13000	Current Inve	ntory Date:	·	/2025				
*Please enter totals in the empty box next to each category	t Total Servic	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Gal Requiring re		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	y.hub.arcgis.com/	
												•						
Service Address	Lead and Copper Sample site number.	: Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access	Water Account Number
				Installed	was ilistalieu				Waterial	Lille	Lead?	Service Line	ting Location.			property.	to property	
		EXAMPLES:					EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Lead (L)					EXAMPLES:			
		Group Homes, Parks, Playgrounds					Copper - Lead Solde (CLS)		Copper - Lead Solds	r Galvanized Requiring Replacemnt (GRR)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If				Copper - No Lead Solder (C)		IF customer refused	
	Lead and Copper Sample	Special Care Facilities, Hospitals				How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date		If previous column was	Galvanized (G)		access to property, date waiver obtained	l l
	site number is the 7 digit number starting with "LP" or " LA". /	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line	What year was the customer side service line	Service Line Identified? EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring	Non-Lead (NL)	downstream of any Lead section, mark No (N).	customer was notified of Lead Service Line.	Yes (Y) or No (N)	marked (Y), provide date the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver	
	If address is not a lead and copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE	Lead (L) Cast/Ductile Iron or	Replacemnt (GRR) Lead (L) Cast/Ductile Iron or		If Yes, that section of service line should be marked as Galvanized	/ If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		/ Leave blank if customer has not	
							PEX (P) Unknown (U)	Transite (O) Plastic - PVC, HDPE, PEX (I	Transite (O) Plastic - PVC, HDPE		Requiring Replacement in the appropriate immediately preceding						refused access.	
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	PEX (P) Unknown (U)		column(s).				Leave blank if no Lead Service Line was replaced.			
							(ONE)	Unknown Not Lead (UNL	Unknown Not Lead									
4414 MAPLE AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					103058
4118 GUNDERSON AVE 4309 HARLEM AVENUE	N/A N/A	N N	N N	1960	1960		U	U	U	U			N N					103060 103061
4309 HARLEIN AVENUE	N/A N/A	N N	N N	1946	1946		U	U	U	U			N N					103061
4216 SCOVILLE AVENUE	N/A	N	N	1933	1933		U	U	U	U			N					103063
3914 CLARENCE AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					103064
4128 GROVE AVENUE 4041 GROVE AVENUE	N/A N/A	N N	N N	1965 1954	1965 1954		U	U	U	U			N N					103067 103068
4012 S SCOVILLE AVENUE	N/A	N	N N	1925	1925		U	U	U	U			N					103008
4201 CLINTON AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					103073
4111 S GROVE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103079
6001 PERSHING ROAD 4209 S WISCONSIN AVENUE	N/A N/A	N N	N N	1954	1954		U	U	U	U			N N					103081
4217 CLINTON AVENUE	N/A	N	N N	1927	1927		U	U	U	U			N					103083
4045 GROVE AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103084
6412 41ST STREET	N/A	N	N	1955	1955		U	U	U	U			N					103085
6919 43RD STREET 4304 MAPLE AVENUE	N/A N/A	N N	N N	1955 1961	1955 1961		U	U	U	U			N N					103086 103089
7001 40TH STREET	N/A	N	N	1953	1953		U	U	U	U			N					103089
7120 41ST STREET	N/A	N	N	1917	1917		U	U	U	U			N					103092
4119 HARLEM AVENUE	N/A	N	N				U	U	U	U			N					103096
4121 HARLEM AVENUE 4233 CLINTON AVENUE	N/A N/A	N N	N N	1955	1955		U	U	U	U			N N					103097 103101
4032 RIDGELAND AVENUE	N/A	N	N N	1955	1955		U	U	U	U			N					103101
4115 HARLEM AVENUE	N/A	N	N				U	U	U	U			N					103105
4320 KENILWORTH AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103109
3948 ELMWOOD AVENUE 6740 41ST STREET	N/A N/A	N N	N N	1926 1919	1926 1919		U	U	U	U			N N					103115 103116
4421 GROVE AVENUE	N/A	N	N	1919	1919		U	U	U	U			N					103117
4228 ELMWOOD AVENUE	N/A	N	N	1972	1972		U	U	U	U			N					103125
4230 ELMWOOD AVENUE	N/A	N	N	1935	1935		U	U	U	U			N					103127
6517 W 41ST STREET 4039 GROVE AVENUE	N/A N/A	N N	N N	1958 1930	1958 1930		U	U	U	U			N N					103129 103131
4039 GROVE AVENUE 4100 MAPLE AVENUE	N/A N/A	N N	N N	1930	1930 1954		U	U	U	U			N N					103131
4309 KENILWORTH AVENUE	N/A	N	N	1966	1966		Ü	U	Ü	U			N					103144
4418 MAPLE AVENUE	N/A	N	N	1942	1942		U	U	U	U			N					103146

							Lead Ser	vice Line Inver	ntory Temp	late								
*Please enter information in the empty box next to each section	Water	System Na	me		Stickne	ey		ID Number:		13000	Current Inver	ntory Date:	4/15,	/2025				
*Please enter totals in the empty box next to each category	Total Servic	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv		0	Total Unknown:	1722	Website link	k to Material	https://lead-service	e-line-inventory-1-novotn	y.hub.arcgis.com/	
								requiring rep	nacement.		OTIKITOWIT.		mver	itory.				
Service Address	Lead and Copper Sample site number.	e Is this a high-risk Facility or Area?		Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	Group Homes, Parks, Playgrounds Special Care Facilities, Hospitals Clinics, Child Care Facilities	s, s, Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known'	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PvC, HDPE,	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or	EXAMPLES: Lead (L) Galvanized Requiring Replacemnt (GRR) Unknown (U) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O)	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not	
		Yes (Y) or No (N)					PEX (P) Unknown (U) Unknown Not Lead (UNL)	Plastic - PVC, HDPE, PEX (P Unknown (U) Unknown Not Lead (UNL)	Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)		Requiring Replacement in the appropriate immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.		refused access.	
4025 SCOVILLE AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					103148
4040 GUNDERSON AVENUE	N/A	N	N	1962	1962		U	U	U	U			N					103149
4001 EAST AVENUE	N/A	N	N	1962	1962		U	U	U	U			N					103152
4229 GUNDERSON AVENUE 6435 41ST STREET	N/A N/A	N N	N N	1953 1953	1953 1953		U	U	U	U			N N					103153 103154
4207 WISCONSIN AVENUE	N/A	N N	N	1933	1933		U	U	U	U			N					103158
7012 40TH PLACE	N/A	N	N	1962	1962		U	U	U	U			N					103160
4210 MAPLE AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103164
4212 GUNDERSON AVENUE	N/A	N	N	1955	1955	Visual Inspection	U	U	С	U			N					103166
4030 EAST AVENUE	N/A	N	N	1930	1930		U	U	U	U			N					103167
6923 43RD STREET	N/A	N	N	1931	1931		U	U	U	U			N					103170
3918 CLINTON AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					103175
4017 ELMWOOD AVENUE	N/A	N	N N	1926	1926		U	U	U	U			N					103177
4102 GROVE AVENUE 4122 RIDGELAND AVENUE	N/A N/A	N N	N N	1955 1956	1955 1956		U	U	U	U			N N					103178 103180
4126 WISCONSIN AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103186
4020 RIDGELAND AVENUE	N/A	N	N	1921	1921		U	U	U	U			N					103187
4221 WENONAH AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					103191
4037 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					103192
4033 EAST AVENUE	N/A	N	N				U	U	U	U			N					103193
4301 HOME AVENUE	N/A N/A	N N	N N	1952	1952		U	U	U	U			N N					103194
4997 PERSHING ROAD 4350 WENONAH AVENUE	N/A N/A	N N	N N	1956	1956		U	U	U	U			N N					103196 103197
4200 WISCONSIN AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103200
3939 GUNDERSON AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103203
7005 40TH STREET	N/A	N	N	1953	1953		U	U	U	U			N					103204
4226 RIDGELAND AVENUE	N/A	N	N	1941	1941		U	U	U	U			N					103207
6526 41ST STREET	N/A	N	N	1959	1959		U	U	U	U			N					103208
3909 HOME AVENUE 4010 GUNDERSON AVENUE	N/A N/A	N	N N	1950 1925	1950 1925		U	U	U	U			N N					103209 103211
3935 SCOVILLE AVENUE	N/A N/A	N N	N N	1925	1925		U	U	U	U			N N					103211
3928 CLINTON AVENUE	N/A	N	N	1933	1933		U	U	U	U			N					103212
4416 WISCONSIN AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103218
4019 EAST AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103221
4319 GROVE AVENUE	N/A	N	N	1947	1947		U	U	U	U			N					103224
7018 43RD STREET	N/A	N	N	1934	1934		U	U	U	U			N					103227

							Load Son	vice Line Inver	story Tomp	lato								
*Please enter information in the empty		<u> </u>		1										/				
box next to each section	Water	System Nai	me 		Stickne	ey	System	ID Number:		13000	Current Inver	ntory Date:	4/15,					
*Please enter totals in the empty box next to each category	Total Service	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722	Website link	k to Material ntory:	https://lead-service	e-line-inventory-1-novotn	y.hub.arcgis.com/	
								ricquirilg rep	nacement.		OTIKITOWIT.		IIIVCI	itory.				
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?		Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Solder (C)	(C)	Solder (C)	Lead (L)	If any galvanized service							
		Group Homes, Parks, Playgrounds	5,				Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	r Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If				Copper - No Lead Solder (C)		IF customer refused	
	Lead and Copper Sample site number is the 7 digit	Special Care Facilities, Hospitals	5,			How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date customer was		If previous column was	Galvanized (G)		access to property, date waiver obtained	
	number starting with "LP" or " LA".	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned	customer side	Service Line Identified? EXAMPLES: Construction	Lead (L)	Galvanized Requiring	Galvanized Requiring	Non-Lead (NL)	downstream of any Lead section, mark No (N).	notified of Lead Service Line.	Yes (Y) or No (N)	marked (Y), provide date the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of	
	If address is not a lead and copper sample site mark		100 (17 01 110 (14)	service line installed, if known?	service line installed, if known	Records, Visual Inspections, Survey Response,	Lead (L) Cast/Ductile Iron or	Replacemnt (GRR)	Replacemnt (GRR)	Non-Lead (NL)	If Yes, that section of	/ If Service Line is not		/ Leave blank if previous	Cast/Ductile Iron or Transite	100 (17) 01 110 (11)	refusal to sign waiver.	
	"N/A"		4			Maintenance Records, etc	Transite (O) Plastic - PVC, HDPE,	Lead (L) Cast/Ductile Iron or	Lead (L) Cast/Ductile Iron or		service line should be marked as Galvanized Requiring Replacement in	Lead put N/R		column was (N).	(O)		Leave blank if customer has not	
							PEX (P) Unknown (U)	Transite (O) Plastic - PVC, HDPE, PEX (P	Transite (O) Plastic - PVC, HDPE,		the appropriate immediately preceding				Leave blank if no Lead		refused access.	
		Yes (Y) or No (N)					Unknown Not Lead (UNL)	Unknown (U)	PEX (P) Unknown (U)		column(s).				Service Line was replaced.			
								Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4332 OAK PARK AVENUE	N/A	N N	N N	1958	1958		U	U	U	U			N					103228
4326 KENILWORTH AVENUE 4148 WISCONSIN AVENUE	N/A N/A	N N	N N	1956 1955	1956 1955		U	U	U	U			N N					103232 103238
3928 RIDGELAND AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103240
7045 43RD STREET	N/A	N	N	1955	1955	Visual Inspection	U	U	С	U			N					103243
3925 WESLEY AVENUE 4104 CLINTON AVENUE	N/A N/A	N N	N N	1954 1952	1954 1952		U	U	U	U			N N					103245 103250
3915 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103251
4204 WENONAH AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					103252
7123 40TH PLACE	N/A	N	N	1954	1954		U	U	U	U			N					103253
7034 40TH PLACE 4211 SCOVILLE AVENUE	N/A N/A	N N	N N	1952 1956	1952 1956		U	U	U	U			N N					103256 103261
6432 41ST STREET	N/A	N	N	1927	1927		U	U	U	U			N					103263
4244 SCOVILLE AVENUE	N/A	N	N	1914	1914		U	U	U	U			N					103264
4206 WISCONSIN AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					103265
7023 40TH STREET 6504 41ST STREET	N/A N/A	N N	N N	1961 1955	1961 1955		U	U	U	U			N N					103267 103269
4138 ELMWOOD AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					103270
4016 SCOVILLE AVENUE	N/A	N	N	1981	1981		U	U	U	U			N					103271
4432 CLINTON AVENUE 4106 WISCONSIN AVENUE	N/A N/A	N N	N N	1954 1931	1954 1931		U	U	U	U			N N					103272 103276
4435 WISCONSIN AVENUE	N/A N/A	N	N	1931	1953		U	U	U	U			N N					103276
4019 SCOVILLE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103279
4042 OAK PARK AVENUE	N/A	N	N	1923	1923		U	U	U	U			N					103281
4044 OAK PARK AVENUE 4215 GROVE AVENUE	N/A N/A	N N	N N	1954 1976	1954 1976		U	U	U	U			N N					103282 103285
4111 ELMWOOD AVENUE	N/A	N	N	1923	1923		U	U	U	U			N					103286
4017 GUNDERSON AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103288
3922 OAK PARK AVENUE 3928 GUNDERSON AVENUE	N/A N/A	N N	N N	1924 1949	1924 1949		U	U	U	U			N N					103292 103295
4424 GROVE AVENUE	N/A N/A	N	N N	1949	1949		U	U	U	U			N N					103295
4035 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103298
3924 EUCLID AVENUE	N/A	N	N	1949	1949		U	U	U	U			N					103299
4326 CLINTON AVENUE 4118 OAK PARK AVENUE	N/A N/A	N N	N N	1931	1931		U	U	U	U			N N					103303 103304
4347 GROVE AVENUE	N/A	N	N	1950	1950		U	U	U	U			N					103305

							Lead Ser	vice Line Inver	ntory Temp	late								
*Please enter information in the empty box next to each section	Water	System Nai	me		Stickne	ey .	System	ID Number:	IL03	13000	Current Inver	ntory Date:	4/15	/2025				
*Please enter totals in the empty box next to each category	Total Servic	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	2-line-inventory-1-novotny	.hub.arcgis.com/	
				Year PWS-							Was Galvanized						Date of customer waiver	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Lead (L)	-				EXAMPLES:			
		Group Homes,					Solder (C) Copper - Lead Solde (CLS)	(C) Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	If any galvanized service line material was ever downstream of a Lead				Copper - No Lead Solder (C)		IF austomor refused	
	Lead and Copper Sample site number is the 7 digit	Parks, Playgrounds, Special Care Facilities, Hospitals,				How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	section, mark Yes (Y). If the galvanized service line material was never	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		IF customer refused access to property, date waiver obtained	
	number starting with "LP" or " LA". / If address is not a lead and	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line	customer side service line	Service Line Identified? EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N).	notified of Lead Service Line. /	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE,	Lead (L) Cast/Ductile Iron or	Lead (L) Cast/Ductile Iron or		If Yes, that section of service line should be marked as Galvanized Requiring Replacement in	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
		Yes (Y) or No (N)					PEX (P) Unknown (U) Unknown Not Lead	Transite (O) Plastic - PVC, HDPE, PEX (P	Transite (O) Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding column(s).				Leave blank if no Lead		refused access.	
							(UNL)	Unknown (U) Unknown Not Lead (UNL)	Unknown (U) Unknown Not Lead (UNL)						Service Line was replaced.			
7037 40TH STREET	N/A	N	N	1924	1924		U	U	U	U			N					103311
4025 OAK PARK AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					103314
4117 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U			N					103315
4028 GUNDERSON AVENUE 3916 OAK PARK AVENUE	N/A N/A	N N	N N	1914 1951	1914 1951		U	U	U	U			N N					103316 103318
4111 MAPLE AVENUE	N/A	N	N	1929	1929		U	U	U	U			N					103318
4022 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103323
6510 41ST STREET	LP1A013	N	N	1989	1989		U	U	U	U			N					103327
3927 OAK PARK AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103328
4421 HARLEM AVENUE 3927 CLINTON AVENUE	N/A N/A	N N	N N	1953 1950	1953 1950		U	U	U	U			N N					103329 103333
4238 SCOVILLE AVENUE	N/A N/A	N N	N N	1940	1950		U	U	U	U			N N					103333
3917 GROVE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103336
4242 SCOVILLE AVENUE	N/A	N	N	1909	1909		U	U	U	U			N					103338
4446 MAPLE AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					103339
4403 MAPLE AVENUE	N/A	N N	N N	1935	1935		U	U	U	U			N N					103342
4104 MAPLE AVENUE 4118 WENONAH AVENUE	N/A N/A	N N	N N	1954 1956	1954 1956		U	U	U	U			N N					103343 103344
6728 41ST STREET	N/A	N	N	1954	1954		U	U	U	U			N					103346
4204 MAPLE AVENUE	N/A	N	N	1925	1925		U	U	U	U			N					103347
4012 CLARENCE AVENUE	N/A	N	N	1931	1931		U	U	U	U			N					103349
4022 GUNDERSON AVENUE	N/A	N	N	1938	1938		U	U	U	U			N					103352
4326 MAPLE AVENUE 4125 WENONAH AVENUE	N/A N/A	N N	N N	1961 1953	1961 1953		U	U	U	U			N N					103354 103358
4001 SCOVILLE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103359
6507 41ST STREET	N/A	N	N	1954	1954		U	U	U	U			N					103362
3936 OAK PARK AVENUE	N/A	N	N	1919	1919		U	U	U	U			N					103363
4218 MAPLE AVENUE	N/A	N	N	1923	1923		U	U	U	U			N					103364
4333 WISCONSIN AVENUE	N/A	N N	N N	1953	1953		U	U	U	U			N N					103366
4306 WISCONSIN AVENUE 3945 SCOVILLE AVENUE	N/A N/A	N N	N N	1959 1956	1959 1956		U	U	U	U			N N					103367 103368
3900 OAK PARK AVENUE	N/A	N	N N	1990	1990		U	U	U	U			N					103368
6737 PERSHING ROAD	N/A	N	N				U	U	U	U			N					103376
4135 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103377
3920 GROVE AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					103378
6423 41ST STREET	N/A	N	N	1953	1953		U	U	U	U			N]	103380

				Γ			Lead Ser	vice Line Inve	ntory Temp	late			_					
*Please enter information in the empty box next to each section	Water	System Na	me		Stickne	ey .	System	ID Number:		13000	Current Inve	ntory Date:	-	/2025				
*Please enter totals in the empty box next to each category	t Total Servic	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Gal Requiring re		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	v.hub.arcgis.com/	
														·				
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	(C)	Solder (C)	Lead (L)	If any galvanized service							
		Group Homes, Parks, Playgrounds	5,				Copper - Lead Solde (CLS)	Copper - Lead Solder (CLS	Copper - Lead Solde (CLS)	r Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If				Copper - No Lead Solder (C)		IF customer refused	
	Lead and Copper Sample	Special Care Facilities, Hospitals	s.			How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date		If previous column was	Galvanized (G)		access to property, date waiver obtained	
	site number is the 7 digit number starting with "LP"	Clinics, Child Care Facilities		What year was the PWS-Owned	What year was the customer side	Service Line Identified? EXAMPLES: Construction		Galvanized Requiring	Galvanized	, ,	downstream of any Lead section, mark No (N).	customer was notified of Lead		marked (Y), provide date the Lead Service Line was			by PWS or date PWS notified IDPH of	
	or " LA". / If address is not a lead and	Tudilities	Yes (Y) or No (N)	service line	service line installed, if known?	Records, Visual Inspections, Survey Response,	Lead (L)	Replacemnt (GRR)	Requiring Replacemnt (GRR)	Non-Lead (NL)	/ If Yes, that section of	Service Line. /	Yes (Y) or No (N)	replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	refusal to sign waiver.	
	copper sample site mark "N/A"			mstanea, ii known:	instanca, ii knowii:	Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if	
							Plastic - PVC, HDPE PEX (P)	, Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in the appropriate						customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U)	Plastic - PVC, HDPE, PEX (I	Plastic - PVC, HDPE PEX (P)		immediately preceding column(s).				Leave blank if no Lead			
							Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)		column(s).				Service Line was replaced.			
								Unknown Not Lead (UNL	Unknown Not Lead (UNL)									
4141 MAPLE AVENUE 4201 GUNDERSON AVENUE	N/A N/A	N N	N N	1956 1926	1956 1926		U	U	U	U			N N					103383 103387
4201 GUNDERSON AVENUE 4143 SCOVILLE AVENUE	N/A N/A	N N	N N	1926	1926		U	U	U	U			N N					103387
3921 HOME AVENUE	N/A	N	N	1899	1899		U	U	U	U			N					103394
6715 41ST STREET	N/A	N	N	1978	1978		U	U	U	U			N					103395
4114 WISCONSIN AVENUE 4144 GROVE AVENUE	N/A N/A	N N	N N	1954 1919	1954 1919		U	U	U	U			N N					103396 103398
4324 WENONAH AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					103399
4315 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U			N					103400
7045 40TH PLACE 3900 LARAMIE AVE	N/A N/A	N N	N N	1953	1953		U	U	U	U			N N					103401 103403
4436 WISCONSIN AVENUE	N/A N/A	N	N N	1950	1950		U	U	U	U			N					103408
4444 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103410
4224 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103413
6735 PERSHING ROAD 4146 HOME AVENUE	N/A N/A	N N	N N	1953	1953		U	U	U	U			N N					103414 103420
3923 GUNDERSON AVENUE	N/A	N	N	1933	1933		U	U	U	U			N					103421
4445 MAPLE AVENUE	N/A	N	N	1951	1951		U	U	U	U			N					103422
4440 WENONAH AVENUE	N/A N/A	N N	N	1964	1964		U	U	U	U			N N					103423
4137 CLINTON AVENUE 7016 43RD STREET	N/A N/A	N N	N N	1950 1940	1950 1940		U	U	U	U			N N					103424 103426
4242 GUNDERSON AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					103428
4021 GUNDERSON AVENUE	N/A	N	N	1940	1940		U	U	U	U			N 					103430
4015 SCOVILLE AVENUE 4240 S SCOVILLE AVENUE	N/A N/A	N N	N N	1956 1954	1956 1954		U	U	U	U			N N					103432 103435
4147 CLINTON AVENUE	N/A	N	N	1966	1966		U	U	U	U			N					103436
4111 S GUNDERSON AVENUE	N/A	N	N	1918	1918		U	U	U	U			N					103438
4031 WESLEY AVENUE	N/A	N	N	1953	1953		U	U	U	U			N N					103441
4344 OAK PARK AVENUE 4339 KENILWORTH AVENUE	N/A N/A	N N	N N	1948 1956	1948 1956		U	U	U	U			N N					103443 103444
4242 ELMWOOD AVENUE	N/A	N	N	1964	1964		U	U	U	U			N					103445
4317 S WENONAH AVENUE	N/A	N	N	1928	1928		U	U	U	U			N					103446
6612 W 41ST STREET 4113 ELMWOOD AVENUE	N/A N/A	N N	N N	1930 1955	1930 1955		U	U	U	U			N N					103447 103448
4413 ELMWOOD AVENUE	N/A	N N	N N	1955	1956		U	U	U	U			N N					103448
4033 S SCOVILLE AVENUE	N/A	N	N	1931	1931		U	U	U	U			N					103452

							Lead Sen	vice Line Inver	ntory Temp	lato								
*Please enter information in the empty	Water	System Na	me		Stickne	2V		ID Number:		13000	Current Inver	ntory Date:	4/15,	/2025				
box next to each section					J. Comments	- y 	•	Total Galv		T	Total		Website link					
*Please enter totals in the empty box next to each category	Total Service	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Requiring rep		0	Unknown:	1722		ntory:	https://lead-service	e-line-inventory-1-novotn	/.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?		Year PWS- Owned Service t Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Solder (C)	(C)	Solder (C)	Lead (L)	If any galvanized service line material was ever				Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds	, ,				Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	r Galvanized Requiring Replacemnt (GRR)	downstream of a Lead section, mark Yes (Y). If						IF customer refused	
	Lead and Copper Sample site number is the 7 digit	Special Care Facilities, Hospitals	;,	What year was the	What year was the	How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		access to property, date waiver obtained by PWS or date PWS	
	number starting with "LP" or " LA". /	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	customer side service line	EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring	Non-Lead (NL)	downstream of any Lead section, mark No (N). /	notified of Lead Service Line.	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	notified IDPH of refusal to sign waiver.	
	If address is not a lead and copper sample site mark "N/A"			installed, if known?	installed, if known	Survey Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Replacemnt (GRR) Lead (L)		If Yes, that section of service line should be	/ If Service Line is not Lead put N/R		/ Leave blank if previous column was (N).	Cast/Ductile Iron or Transite		Leave blank if	
	NA						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		marked as Galvanized Requiring Replacement in the appropriate	Ledd put 14/11			(0)		customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (P	Plastic - PVC, HDPE, PEX (P)		immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown (U) Unknown Not Lead (UNL)	Unknown (U) Unknown Not Lead						Service Line was replaced.			
4341 HOME AVENUE	N/A	N	N	1925	1925		U	U	(UNL) U	U			N					103453
4227 S WISCONSIN AVENUE	N/A	N	N	1930	1930		U	U	U	U			N					103457
4005 S CLINTON AVENUE	N/A	N	N	1926	1926		U	U	U	U			N 					103458
4301 HARLEM AVENUE 4035 ELMWOOD AVENUE	N/A N/A	N N	N N	1959	1959		U	U	U	U			N N					103459 103460
7032 W 43RD STREET	N/A	N	N	1957	1957		U	U	U	U			N					103461
7131 W 40TH PLACE	N/A	N	N	1955	1955		U	U	U	U			N					103462
4123 S GUNDERSON AVENUE 4016 CLARENCE AVENUE	N/A N/A	N N	N N	1964 1956	1964 1956		U	U	U	U			N N					103463 103465
7017 W 40TH STREET	N/A	N	N	1930	1930		U	U	U	U			N					103466
3928 SCOVILLE AVENUE	N/A	N	N	1919	1919		U	U	U	U			N					103468
4240 GROVE AVENUE	N/A	N	N	1959	1959		U	U	U	U			N					103469
4024 S CLINTON AVENUE 4101 S MAPLE AVENUE	N/A N/A	N N	N N	1931 1960	1931 1960		U	U	U	U			N N					103470 103473
4437 WISCONSIN AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103474
4343 WISCONSIN AVENUE	N/A	N	N			Visual Inspection	U	U	С	U			N					103475
4040 S GROVE AVENUE 7104 W 40TH STREET	N/A N/A	N N	N N	1949 1947	1949 1947		U	U	U U	U			N N					103476 103479
4319 HARLEM AVENUE	N/A N/A	N N	N	174/	174/		U	U	U	U			N N					103479
4321 HARLEM AVENUE	N/A	N	N				U	U	U	U			N					103483
4033 WESLEY AVENUE	N/A	N	N	1924	1924		U	U	U	U			N 					103485
4144 S RIDGELAND AVENUE 4216 GUNDERSON AVENUE	N/A N/A	N N	N N	1955 1956	1955 1956		U	U	U	U			N N					103486 103487
4439 MAPLE AVENUE	N/A	N	N	1925	1925		U	U	U	U			N					103488
3912 SCOVILLE AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					103489
4139 S WISCONSIN AVENUE 4424 CLINTON AVENUE	N/A N/A	N N	N N	1972 1989	1972 1989		U	U	U	U			N N					103491 103493
4204 HOME AVENUE	N/A N/A	N	N	1989	1955		U	U	U	U			N					103494
4128 CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					103497
4219 HARLEM AVENUE	N/A	N	N				U	U	U	U			N					103498
4221 HARLEM AVENUE 4201 S HOME AVENUE	N/A N/A	N N	N N	2012	2012		U	U	U	U			N N					103499 103500
3946 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					103501
3933 S CLARENCE AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					103502
7100 43RD STREET	N/A N/A	N N	N N	1955	1955		U	U	U	U			N N					103503
4016 S GUNDERSON AVENUE	N/A	N	N	1917	1917		U	U	U	U			N N				I .	103506

							Lead Ser	vice Line Inver	itory Temp	late								
*Please enter information in the empty box next to each section	Water	System Nai	me		Stickne	ξ λ		ID Number:		13000	Current Inven	ntory Date:	4/15,	/2025				
*Please enter totals in the empty box next to each category	Total Servic	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotn	y.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	t	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (CLS) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) r Galvanized Requiring Replacemnt (GRR) Unknown (U) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4041 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103507
4207 GROVE AVENUE	N/A	N	N	1926	1926		U	U	U	U			N					103509
4329 S. HOME AVENUE	N/A	N	N	1947	1947		U	U	U	U			N					103510
3933 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U			N					103514
4122 OAK PARK AVENUE	N/A	N	N				U	U	U	U			N					103518
4118 MAPLE AVENUE	N/A	N	N	1975	1975		U	U	U	U			N					103519
4141 S CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U			N					103521
4405 S HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103522
3937 EUCLID AVENUE	N/A	N N	N	1936	1936		U	U	U	U			N N					103523
4025 GUNDERSON AVENUE 4239 GUNDERSON AVENUE	N/A N/A	N N	N N	1962	1962 1953		U	U	U	U			N N					103524 103530
4239 GUNDERSON AVENUE 4006 WESLEY AVENUE	N/A	N N	N	1953 1919	1953		U	U	U	U			N N					103530
7101 40TH STREET	N/A	N	N	1919	1919		U	U	U	U U			N					103533
4008 CLARENCE AVENUE	N/A	N	N	1957	1957		U	U	II	ii ii			N					103533
4005 ELMWOOD AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103544
4116 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103546
7002 W 40TH PLACE	N/A	N	N	1959	1959		U	U	U	U			N					103547
4128 ELMWOOD AVENUE	N/A	N	N	1951	1951		U	U	U	U			N					103550
3939 EAST AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103551
3920 ELMWOOD AVENUE	N/A	N	N	1929	1929		U	U	U	U			N					103552
7133 W 40TH PLACE	N/A	N	N	1925	1925		U	U	U	U			N					103556
4144 S ELMWOOD AVENUE	N/A	N	N	1922	1922		U	U	U	U			N					103558
4350 OAK PARK AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103559
4028 SCOVILLE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103561
4316 OAK PARK AVENUE	N/A	N	N	1964	1964		U	U	U	U			N					103563
4320 MAPLE AVENUE	N/A	N	N	1961	1961		U	U	U	U			N					103565
4427 CLINTON AVENUE	N/A	N	N	1946	1946		U	U	U	U			N					103566
4200 S GROVE AVENUE	N/A	N N	N	1953	1953		U	U	U	U			N N					103567
4226 ELMWOOD AVENUE 4212 RIDGELAND AVENUE	N/A N/A	N N	N N	1956 1962	1956 1962		U	U	U	U								103569
4212 RIDGELAND AVENUE 4241 GROVE AVENUE	N/A N/A	N N	N N	1962	1962		U	U	U	U			N N					103571 103573
4241 GROVE AVENUE 4111 WENONAH AVENUE	N/A N/A	N N	N N	1954	1954		U	U	U	U			N N					103573
3938 OAK PARK AVENUE	N/A N/A	N N	N N	1950	1950		II	U	IJ	U II			N N					103576
7007 40TH STREET	N/A N/A	N	N	1928	1928		U	U	U	U			N					103577
7039 40TH PLACE	N/A	N	N	1926	1926		U	U	U	U			N					103579
7103 40TH PLACE	N/A	N	N	1926	1926		U	U	U	U			N					103581

										1 .								
	1						Lead Ser	vice Line Inve	ntory Temp T	late			Г					
*Please enter information in the empty box next to each section	Water	System Na	me		Stickne	ey	System	ID Number:		13000	Current Inve	ntory Date:	-	/2025				
*Please enter totals in the empty box next to each category	t Total Servic	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Gal Requiring re		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	/.hub.arcgis.com/	
				<u> </u>				, ,						•				
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Solder (C)	(C)	Solder (C)	Lead (L)	If any galvanized service line material was ever				Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds	5,				Copper - Lead Solde (CLS)	Copper - Lead Solder (CLS	Copper - Lead Solde (CLS)	r Galvanized Requiring Replacemnt (GRR)	downstream of a Lead section, mark Yes (Y). If				(,,		IF customer refused access to property,	
	Lead and Copper Sample site number is the 7 digit	Special Care Facilities, Hospitals	5,	What was was the	What year was the	How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		date waiver obtained by PWS or date PWS	
	number starting with "LP" or " LA". / If address is not a lead and	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line	customer side service line	Service Line Identified? EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring	Non-Lead (NL)	downstream of any Lead section, mark No (N). /	notified of Lead Service Line.	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron of Transite (O)	r Lead (L)	Replacemnt (GRR)		If Yes, that section of service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
							Plastic - PVC, HDPE PEX (P)	, Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron of Transite (O)		Requiring Replacement in the appropriate	ı					refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (I	Plastic - PVC, HDPE PEX (P)	•	immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown (U)	Unknown (U) Unknown Not Lead						Service Line was replaced.			
4140 CLINTON AVENUE	N/A	N	N	1952	1952		U	Unknown Not Lead (UNL	(UNL)	11			N					103585
3905 HOME AVENUE	N/A N/A	N N	N N	1952	1952		U	U	U	U			N					103585
4444 KENILWORTH AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103591
4441 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					103596
4321 HOME AVENUE 6832 43RD STREET	N/A N/A	N N	N N	1937 1956	1937 1956		U	U	U	U			N N					103598 103599
4320 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103600
4419 CLINTON AVENUE	N/A	N	N	1947	1947		U	U	U	U			N					103602
3921 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U			N 					103604
4045 HOME AVENUE 4436 WENONAH AVENUE	N/A N/A	N N	N N	1953 1953	1953 1953		U	U	U	U			N N					103605 103606
4127 S HARLEM AVENUE	N/A	N	N				U	U	U	U			N					103608
4112 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103610
6732 W 41ST STREET	N/A	N	N	1938	1938		U	U	U	U			N					103618
3936 CLARENCE AVENUE 4228 WISCONSIN AVENUE	N/A N/A	N N	N N	1960 1952	1960 1952	Visual Inspection	U	U	U	U			N N					103619 103620
4458 OAK PARK AVENUE	N/A	N	N	1950	1950	The state of the s	U	U	U	U			N					103621
3920 CLINTON AVENUE	LP1C085	N	N	1957	1957		U	U	U	U			N					103624
4220 MAPLE AVENUE 3924 HOME AVENUE	N/A N/A	N N	N N	1959 1948	1959 1948		U	U	U	U			N N					103625 103627
7010 43RD STREET	N/A	N N	N N	1948	1948		U	U	U	U			N N					103627
4318 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U			N					103630
4009 CLINTON AVENUE	N/A	N	N	1979	1979		U	U	U	U			N 					103633
3918 RIDGELAND AVENUE 4115 GUNDERSON AVENUE	N/A N/A	N N	N N	1924 1953	1924 1953		U	U	U	U			N N					103634 103639
4402 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103640
4113 HOME AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					103641
4000 EAST AVENUE	N/A	N	N	1957	1957		U	U	U	U			N N					103643
4426 WISCONSIN AVENUE 4340 WISCONSIN AVENUE	N/A N/A	N N	N N	1962 1959	1962 1959		U	U	U	U			N N					103644 103646
4221 GUNDERSON AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103647
4008 OAK PARK AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					103648
4023 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U			N 					103649
4236 GROVE AVENUE 4425 WISCONSIN AVENUE	N/A N/A	N N	N N	1922 1929	1922 1929		U	U	U	U			N N					103653 103654
4449 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U			N					103655

							Load Son	vice Line Inver	tory Tomp	lato								
*Please enter information in the empty	Mator	Custom No.	m. o		Chialus						Commont lavor	atami Datai	4/15	/2025				
box next to each section	vvater	System Na	T		Stickne	:y T	System	ID Number:		13000	Current Inver	itory Date:	4/15,					
*Please enter totals in the empty box next to each category	Total Service	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722	Website link Inver	c to Material ntory:	https://lead-service	e-line-inventory-1-novotny	/.hub.arcgis.com/	
			<u> </u>		l	L		1aa8 . ab							•			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?		Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service							
		Group Homes, Parks, Playgrounds					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	r Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead				Copper - No Lead Solder (C)		IF customer refused	
	Lead and Copper Sample	Special Care Facilities, Hospitals	2,			How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	section, mark Yes (Y). If the galvanized service line material was never	Enter date		If previous column was	Galvanized (G)		access to property, date waiver obtained	
	site number is the 7 digit number starting with "LP" or " LA". /	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned	What year was the customer side	Service Line Identified? EXAMPLES: Construction		Galvanized Requiring	Galvanized		downstream of any Lead section, mark No (N).	customer was notified of Lead Service Line.	Yes (Y) or No (N)	marked (Y), provide date the Lead Service Line was replaced.		Yes (Y) or No (N)	by PWS or date PWS notified IDPH of	
	If address is not a lead and copper sample site mark		res (1) or No (N)	service line installed, if known?	service line installed, if known?	Records, Visual Inspections, Survey Response,	Lead (L)	Replacemnt (GRR)	Requiring Replacemnt (GRR)	Non-Lead (NL)	/ If Yes, that section of	/ If Service Line is not	162 (1) OF NO (N)	replaced. / Leave blank if previous	Plastic - PVC, HDPE, PEX (P)	165 (1) OF NO (N)	refusal to sign waiver. /	
	"N/A"		-			Maintenance Records, etc	Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE,	Lead (L) Cast/Ductile Iron or	Lead (L) Cast/Ductile Iron or		service line should be marked as Galvanized Requiring Replacement in	Lead put N/R		column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
							PEX (P) Unknown (U)	Transite (O) Plastic - PVC, HDPE, PEX (P)	Transite (O) Plastic - PVC, HDPE,		the appropriate immediately preceding				Leave blank if no Lead		refused access.	
		Yes (Y) or No (N)					Unknown Not Lead (UNL)	Unknown (U)	PEX (P) Unknown (U)		column(s).				Service Line was replaced.			
							(=::=/	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
6619 41ST STREET 4007 GUNDERSON AVENUE	N/A N/A	N N	N N	1978 1959	1978 1959		U	U	U	U			N N					103660 103661
4317 WISCONSIN AVENUE	N/A	N	N	1939	1927		U	U	U	U			N					103662
7043 40TH PLACE	N/A	N	N	1924	1924		U	U	U	U			N					103663
4131 WISCONSIN AVENUE 3916 CLINTON AVENUE	N/A N/A	N N	N N	1956 1957	1956 1957		U	U	U	U			N N					103664 103666
7031 40TH STREET	N/A	N	N	1973	1973		U	U	U	U			N					103670
4007 EAST AVENUE	N/A	N	N	1940	1940		U	U	U	U			N					103671
4121 SCOVILLE AVENUE 6520 41ST STREET	N/A N/A	N N	N N	1955 1956	1955 1956	Visual Inspection	U	U	U	U			N N					103673 103675
4017 EAST AVENUE	N/A	N	N	1935	1935	visual inspection	U	U	U	U			N					103678
6001 PERSHING RD	N/A	N	N				U	U	U	U			N					103681
4122 WISCONSIN AVENUE	N/A	N	N	1954	1954		U	U	U	U			N 					103683
7116 41ST STREET 4133 HARLEM AVENUE	N/A N/A	N N	N N	1928	1928		U	U	U	U			N N					103684 103685
4322 KENILWORTH AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103688
4031 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U			N 					103689
3945 CLARENCE AVENUE 4212 WISCONSIN AVENUE	N/A N/A	N N	N N	1952 1924	1952 1924		U	U	U	U			N N					103691 103694
4026 EAST AVENUE	N/A	N	N	1940	1940		U	U	U	U			N					103695
3939 OAK PARK AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					103696
7036 41ST STREET 4222 SCOVILLE AVENUE.	N/A N/A	N N	N N	1978 1956	1978 1956		U	U	U	U			N N					103697 103701
4120 MAPLE AVENUE	N/A N/A	N	N	1931	1936		U	U	U	U			N N					103701
4210 WISCONSIN AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					103706
7016 40TH STREET	N/A	N N	N N	1947	1947		U	U	U	U			N N					103707
4322 GROVE AVENUE 3912 WESLEY AVENUE	N/A N/A	N N	N N	1950 1923	1950 1923		U	U	U	U			N N					103709 103710
4207 WENONAH AVENUE	N/A	N	N	1959	1959		U	U	U	U			N					103715
4449 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103717
4112 WISCONSIN AVENUE 7124 41ST STREET	N/A N/A	N N	N N	1954 1917	1954 1917		U	U	U	U			N N					103718 103719
4003 EAST AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					103719
4039 HARLEM AVENUE	N/A	N	N				U	U	U	U			N					103722
3941 GROVE AVENUE	N/A	N	N N	1930	1930		U	U	U	U			N N					103724
4441 S HOME AVENUE	N/A	l N	N	1955	1955		U	U	U	U		<u> </u>	N	<u> </u>			<u> </u>	103726

							Load Sor	vice Line Inver	tory Tomp	lato								
*Please enter information in the empty	14/.1	6 N		I	G.: 1							. 5.	./	/2025				
box next to each section	water	System Nar	ne -		Stickne	ey	System	ID Number:		13000	Current Inver	ntory Date:		/2025				
*Please enter totals in the empty box next to each category	t Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	/.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES: Lead (L)					EXAMPLES:			
		Group Homes,					Solder (C) Copper - Lead Solde	(C)	Solder (C) Copper - Lead Solde	Galvanized Requiring	If any galvanized service line material was ever downstream of a Lead				Copper - No Lead Solder (C)			
	Lead and Copper Sample	Parks, Playgrounds, Special Care				Ilanina da Nasarial afabira	(CLS)	Copper - Lead Solder (CLS	(CLS)	Replacemnt (GRR)	section, mark Yes (Y). If the galvanized service line	Enter date		If previous column was			IF customer refused access to property,	
	site number is the 7 digit number starting with "LP"	Facilities, Hospitals, Clinics, Child Care Facilities	,	What year was the PWS-Owned	What year was the customer side	How was the Material of this Service Line Identified? EXAMPLES: Construction	Galvanized (G)	Galvanized (G) Galvanized Requiring	Galvanized (G) Galvanized	Unknown (U)	material was never downstream of any Lead section, mark No (N).	customer was notified of Lead		marked (Y), provide date the Lead Service Line was	Galvanized (G)		date waiver obtained by PWS or date PWS notified IDPH of	
	or " LA". / If address is not a lead and copper sample site mark	i delities	Yes (Y) or No (N)	service line installed, if known?	service line installed, if known?	Records, Visual Inspections, Survey Response,	Lead (L) Cast/Ductile Iron or	Replacemnt (GRR)	Requiring Replacemnt (GRR)	Non-Lead (NL)	If Yes, that section of service line should be	Service Line. / If Service Line is not	Yes (Y) or No (N)	replaced. / Leave blank if previous	Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite	Yes (Y) or No (N)	refusal to sign waiver. /	
	"N/A"					Maintenance Records, etc	Transite (O) Plastic - PVC, HDPE,	Lead (L) Cast/Ductile Iron or	Lead (L) Cast/Ductile Iron or		marked as Galvanized Requiring Replacement in	Lead put N/R		column was (N).	(O)		Leave blank if customer has not refused access.	
		Yes (Y) or No (N)					PEX (P) Unknown (U)	Transite (O) Plastic - PVC, HDPE, PEX (P	Transite (O) Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no Lead		reruseu decess.	
		163 (1) 61 116 (11)					Unknown Not Lead (UNL)	Unknown (U)	Unknown (U) Unknown Not Lead		column(s).				Service Line was replaced.			
4139 HOME AVENUE	N/A	N	N	1957	1957		U	Unknown Not Lead (UNL)	(UNL) U	U			N					103727
4007 EUCLID AVENUE	N/A	N	N	1962	1962		U	U	U	U			N					103727
6644 W 41ST STREET	N/A	N	N	1955	1955		U	U	U	U			N					103729
6401 W 41ST STREET	N/A	N N	N N	1954	1954		U	U	U	U			N N					103730
3930 S EAST AVENUE 7127 40TH PLACE	N/A N/A	N N	N N	1952 1954	1952 1954		U	U	U	U			N					103731 103733
4201 SCOVILLE AVENUE	N/A	N	N	1957	1957	Visual Inspection	U	U	С	U			N					103735
3933 OAK PARK AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103737
4100 WENONAH AVENUE 4022 ELMWOOD AVENUE	N/A N/A	N N	N N	1953 1953	1953 1953		U	U	U	U			N N					103738 103739
4109 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103733
4444 WISCONSIN AVENUE	N/A	N	N	1951	1951		U	U	U	U			N					103744
6427 41ST STREET	N/A	N	N	1954	1954		U	U	U	U			N					103745
4009 WESLEY AVENUE 3928 HOME AVENUE	N/A N/A	N N	N N	1952 1948	1952 1948		U	U	U	U			N N					103747 103749
4144 GUNDERSON AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103751
3932 EUCLID AVENUE	N/A	N	N	1949	1949		U	U	U	U			N					103752
7116 W 43RD STREET 4305 MAPLE AVENUE	N/A N/A	N N	N N	1956 1959	1956 1959		U	U	U	U			N N					103753 103754
4305 MAPLE AVENUE	N/A N/A	N N	N N	1959	1959		U	U	U	U			N					103754
4201 GROVE AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					103756
4328 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103757
4321 CLINTON AVENUE 4124 OAK PARK AVENUE	N/A N/A	N N	N N	1954 1960	1954 1960		U	U	U	U			N N					103758 103760
3921 EUCLID AVENUE	N/A	N	N	1923	1923		U	U	U	U			N					103761
4229 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103762
4119 S WISCONSIN AVENUE	N/A	N N	N N	1952	1952		U	U	U	U			N N					103765
4035 GUNDERSON AVENUE 6513 41ST STREET	N/A N/A	N N	N N	1959 1927	1959 1927		U	U	U	U			N N					103767 103768
4214 OAK PARK AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103769
4135 SCOVILLE AVENUE	N/A	N	N	1914	1914		U	U	U	U			N					103770
3911 GROVE AVENUE	N/A	N N	N N	1964	1964		U	U	U	U			N N					103771
6634 41ST STREET 3917 CLINTON AVENUE	N/A N/A	N N	N N	1919 1950	1919 1950		U	U	U	U			N N					103772 103773
4308 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U			N N					103774
4128 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103775

							Load Cor	vice Line Inves	tory Tomp	lata								
*Please enter information in the empty								vice Line Inver										
box next to each section	Water	System Nar	me		Stickne	ey	System	ID Number:	IL03	13000	Current Inver	ntory Date:	4/15	/2025				
*Please enter totals in the empty box next to each category	t Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	v.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Solder (C)	(C)	Solder (C)	Lead (L)	If any galvanized service line material was ever				Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds,					Copper - Lead Solde (CLS)	Copper - Lead Solder (CLS	Copper - Lead Solde (CLS)	r Galvanized Requiring Replacemnt (GRR)	downstream of a Lead section, mark Yes (Y). If						IF customer refused access to property,	
	Lead and Copper Sample site number is the 7 digit	Special Care Facilities, Hospitals, Clinics, Child Care	,	What year was the	What year was the	How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never downstream of any Lead	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		date waiver obtained by PWS or date PWS	
	number starting with "LP" or " LA". / If address is not a lead and	Facilities	Yes (Y) or No (N)	PWS-Owned service line	customer side service line	EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	section, mark No (N). /	notified of Lead Service Line. /	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		If Yes, that section of service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if	
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in the appropriate				, co		customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (P	Plastic - PVC, HDPE, PEX (P)		immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown (U) Unknown Not Lead (UNL)	Unknown (U) Unknown Not Lead									
4007 SCOVILLE AVENUE	N/A	N	N	1925	1925		U	U	(UNL) U	U			N					103776
7112 40TH PLACE	N/A	N	N	1915	1915		U	U	U	U			N					103777
4231 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103779
4018 GROVE AVENUE 4101 GROVE AVENUE	N/A N/A	N N	N N	1952 1953	1952 1953		U	U	U	U			N N					103780 103781
4444 CLINTON AVENUE	N/A	N	N	1951	1951		U	U	U	U			N					103782
4007 ELMWOOD AVENUE	N/A	N	N	1931	1931		U	U	U	U			N					103783
4211 HOME AVENUE 4402 MAPLE AVENUE	N/A N/A	N N	N N	1954 1989	1954 1989		U	U	U	U			N N					103784 103787
4343 WENONAH AVENUE	N/A N/A	N N	N N	1989	1989		U	U	U	U			N N					103787
4106 MAPLE AVENUE	N/A	N	N	1922	1922		U	U	U	U			N					103790
4030 WESLEY AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					103791
4220 CLINTON AVENUE 3941 GUNDERSON AVENUE	N/A	N N	N	1954	1954		U	U	U	U			N N					103793
4007 CLINTON AVENUE	N/A N/A	N N	N N	1923 1934	1923 1934		U	U	U	U			N N					103794 103796
4430 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U			N					103797
4136 S HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103798
4316 HOME AVENUE 4002 WESLEY AVENUE	N/A N/A	N N	N N	1954 1950	1954 1950		U	U	U	U			N N					103802 103805
4100 GROVE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103806
6633 41ST STREET	N/A	N	N	1978	1978		U	U	U	U			N					103807
4017 CLARENCE AVENUE	N/A	N N	N N	1957	1957		U	U	U	U			N					103814
6615 41ST STREET 4208 CLINTON AVENUE	N/A N/A	N N	N N	1978 1954	1978 1954		U	U	U	U			N N					103815 103817
3936 SCOVILLE AVENUE	N/A	N	N	1941	1941		U	U	U	U			N N					103819
4408 OAK PARK AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103822
3945 ELMWOOD AVENUE 4132 WENONAH AVENUE	N/A N/A	N N	N N	1954 1953	1954 1953		U	U	U	U			N N					103827 103828
4132 WENONAH AVENUE 4143 CLINTON AVENUE	N/A N/A	N N	N N	1953 1953	1953 1953		U	U	U	U			N N					103828
4136 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103830
6929 PERSHING ROAD	N/A	N	N				U	U	U	U			N					103831
7128 40TH PLACE 4450 GROVE AVENUE	N/A N/A	N N	N N	1954 1954	1954 1954		U	U	U	U			N N					103832 103834
3916 HOME AVENUE	N/A N/A	N N	N N	1954	1954		U	U	U	U			N					103834
6405 W 41ST STREET	N/A	N	N	1953	1953		U	U	U	U			N					103836
6708 41ST STREET	N/A	N	N	1954	1954		U	U	U	U			N					103838

							Lead Serv	vice Line Inver	itory Temp	late								
*Please enter information in the empty box next to each section	Water	System Nar	me		Stickne	ey .	System	ID Number:	IL03	13000	Current Inven	ntory Date:	4/15,	/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		c to Material ntory:	https://lead-service	e-line-inventory-1-novotn	r.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last		Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized (G) Galvanized (Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacemnt (GRR) Unknown (U) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
6511 41ST STREET	N/A	N	N	1955	1955		U	U	U	U			N					103839
6929 43RD STREET	N/A	N	N	1952	1952		U	U	U	U			N					103840
6437 41ST STREET	N/A	N	N	1933	1933		U	U	U	U			N					103841
4432 WENONAH AVENUE	N/A	N N	N	1953	1953		U	U	U	U			N					103842
4351 GROVE AVENUE 7105 40TH PLACE	N/A N/A	N N	N N	1946 1924	1946 1924		U	U	U	U			N N					103848 103849
4330 KENILWORTH AVENUE	N/A N/A	N N	N N	1924	1924		U	U	IJ	U			N N					103849
4140 OAK PARK AVENUE	N/A N/A	N N	N N	1959	1959		U	U	U U	U			N N					103851
4232 SCOVILLE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103852
4140 GROVE AVENUE	N/A	N	N	1955	1955		II	U	II	ii ii			N					103853
4123 WISCONSIN AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103855
3910 GROVE AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					103857
4116 HOME AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					103858
4003 HOME AVENUE	N/A	N	N	1920	1920		U	U	U	U			N					103859
4216 MAPLE AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103860
3934 GROVE AVENUE	N/A	N	N	1930	1930		U	U	U	U			N					103861
4129 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103862
4128 GUNDERSON AVENUE	N/A	N	N	1932	1932		U	U	U	U			N					103864
4121 GUNDERSON AVENUE	N/A	N	N	1914	1914		U	U	U	U			N					103865
3937 ELMWOOD AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103866
4425 MAPLE AVENUE	N/A	N	N	1949	1949		U	U	U	U			N					103869
6811 PERSHING ROAD	N/A	N 	N	1943	1943		U	U	U	U			N					103870
3914 ELMWOOD AVENUE	N/A N/A	N N	N N	1962 1952	1962 1952		U	U	U	U			N N					103873 103874
3912 OAK PARK AVENUE 4136 MAPLE AVENUE	N/A N/A	IN N	N N	1952	1952		U	U	U II	U			N N					103874
4231 SCOVILLE AVENUE	N/A N/A	N N	N N	1955	1955		U	U	U	U			N N					103875
7041 43RD STREET	N/A N/A	N N	N N	1955	1955		U	U	U	U			N N					103881
4334 KENILWORTH AVENUE	N/A	N	N	1988	1988		U	U	U	U			N					103885
4002 EAST AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					103886
4240 GUNDERSON AVENUE	N/A	N	N	1951	1951		U	U	U	U			N					103888
4119 MAPLE AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					103889
4016 EAST AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103890
7011 W 40TH PLACE	N/A	N	N	1955	1955		U	U	U	U			N					103891
4036 GUNDERSON AVENUE	N/A	N	N	1928	1928		U	U	U	U			N					103892
6607 PERSHING ROAD	N/A	N	N				U	U	U	U			N					103893
4201 WENONAH AVENUE	N/A	N	N	1952	1952		U	U	U	U			N		<u> </u>			103895

Service Address Lead and site num number or " LA" If address	and Copper Sample site number. Factor and Copper Sample number is the 7 digit per starting with "LP" A.". / ress is not a lead and ler sample site mark "N/A"	this a high-risk acility or Area? SEXAMPLES: Group Homes, rks, Playgrounds, Special Care cilities, Hospitals, linics, Child Care	1904 Service Line Newly Identified Since Last Submitted Inventory Yes (Y) or No (N)	Year PWS-Owned Service Line was Installed What year was the PWS-Owned service line installed, if known?	Year Customer Side Service Line was Installed	Total Non-Lead: Source of Information Used for Service Line Identification How was the Material of this	System 111 Gooseneck/	PWS-Owned Service Line Material EXAMPLES: Copper - No Lead Solder (C)	IL03 vanized	Classification for Entire Serivice Line EXAMPLES: Lead (L)	Current Inven Total Unknown: Was Galvanized Service Line Material ever downstream of Lead?	1722	4/15, Website link Inver Was a Lead Service Line Previously Replaced at this Location?	to Material	https://lead-service Material of Service Line Replacement EXAMPLES:	-line-inventory-1-novotny. Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
*Please enter totals in the empty box next to each category Service Address Lead and site num number or " LA" If address	and Copper Sample site number. Factor and Copper Sample number is the 7 digit per starting with "LP" A.". / ress is not a lead and ler sample site mark "N/A"	this a high-risk acility or Area? S EXAMPLES: Group Homes, rks, Playgrounds, Special Care cilities, Hospitals, linics, Child Care	1904 Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed What year was the customer side	Total Non-Lead: Source of Information Used for Service Line Identification	Gooseneck/ Pigtail EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder	PWS-Owned Service Line Material EXAMPLES: Copper - No Lead Solder (C)	Customer Side Service Line Material EXAMPLES: Copper - No Lead	Classification for Entire Serivice Line	Total Unknown: Was Galvanized Service Line Material ever downstream of	1722 Date Customer Notified of Lead	Website link Inver	to Material atory:	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access	Water Account Number
Service Address Lead and site num number or "LA" If address	and Copper Sample site number. Far and Copper Sample number is the 7 digit per starting with "LP" A". / ress is not a lead and ler sample site mark "N/A"	this a high-risk acility or Area? SEXAMPLES: Group Homes, rks, Playgrounds, Special Care cilities, Hospitals, linics, Child Care	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder	PWS-Owned Service Line Material EXAMPLES: Copper - No Lead Solder (C)	Customer Side Service Line Material EXAMPLES: Copper - No Lead	Classification for Entire Serivice Line EXAMPLES:	Unknown: Was Galvanized Service Line Material ever downstream of	Date Customer Notified of Lead	Inver Was a Lead Service Line Previously Replaced at	Date Lead Service Line	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access	Water Account Number
Lead an site nun number or " LA" If addres	and Copper Sample number is the 7 digit per starting with "LP" A". / ress is not a lead and ler sample site mark "N/A"	EXAMPLES: Group Homes, rks, Playgrounds, Special Care cilities, Hospitals, linics, Child Care	Identified Since Last Submitted Inventory	Owned Service Line was Installed What year was the PWS-Owned service line	Side Service Line was Installed What year was the customer side	for Service Line Identification	Pigtail EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder	EXAMPLES: Copper - No Lead Solder (C)	Service Line Material EXAMPLES: Copper - No Lead	Entire Serivice Line EXAMPLES:	Service Line Material ever downstream of	Notified of Lead	Previously Replaced at		Replacement	refused access to the	or IDPH notification, if customer refused access	Water Account Number
Lead an site nun number or " LA"	and Copper Sample number is the 7 digit per starting with "LP" A". / ress is not a lead and ler sample site mark "N/A"	EXAMPLES: Group Homes, rks, Playgrounds, Special Care cilities, Hospitals, linics, Child Care	Identified Since Last Submitted Inventory	Owned Service Line was Installed What year was the PWS-Owned service line	Side Service Line was Installed What year was the customer side	for Service Line Identification	Pigtail EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder	EXAMPLES: Copper - No Lead Solder (C)	Service Line Material EXAMPLES: Copper - No Lead	Entire Serivice Line EXAMPLES:	Service Line Material ever downstream of	Notified of Lead	Previously Replaced at		Replacement	refused access to the	or IDPH notification, if customer refused access	Water Account Number
site nun number or " LA" If addres	and Copper Sample number is the 7 digit per starting with "LP" A.". / ress is not a lead and ler sample site mark "N/A"	Group Homes, rks, Playgrounds, Special Care cilities, Hospitals, linics, Child Care	Yes (Y) or No (N)	PWS-Owned service line	customer side	How was the Material of this	Copper - No Lead Solder (C) Copper - Lead Solder	Copper - No Lead Solder (C)	Copper - No Lead						EXAMPLES:			
site nun number or " LA" If addres	and Copper Sample number is the 7 digit per starting with "LP" A". / ress is not a lead and er sample site mark "N/A"	rks, Playgrounds, Special Care cilities, Hospitals, linics, Child Care	Yes (Y) or No (N)	PWS-Owned service line	customer side	How was the Material of this	Copper - Lead Solder	_										
site nun number or " LA" If addres	and Copper Sample number is the 7 digit per starting with "LP" A.". / ress is not a lead and ler sample site mark "N/A"	Special Care cilities, Hospitals, linics, Child Care	Yes (Y) or No (N)	PWS-Owned service line	customer side	How was the Material of this			Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If				Copper - No Lead Solder (C)		IF customer refused	
number or " LA" If addres	per starting with "LP" LA". / ress is not a lead and her sample site mark "N/A"	linics, Child Care	Yes (Y) or No (N)	PWS-Owned service line	customer side		Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date customer was		If previous column was	Galvanized (G)		access to property, date waiver obtained	
	er sample site mark "N/A"			installed, if known?	service line	Service Line Identified? EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring	Non-Lead (NL)	downstream of any Lead section, mark No (N). /	notified of Lead Service Line.	Yes (Y) or No (N)	marked (Y), provide date the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver.	
	V				installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Replacemnt (GRR)		If Yes, that section of service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		/ Leave blank if customer has not	
	Ve						Plastic - PVC, HDPE, PEX (P) Unknown (U)	Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P	Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE,		Requiring Replacement in the appropriate immediately preceding						refused access.	
	Te	es (Y) or No (N)					Unknown Not Lead	Unknown (U)	PEX (P) Unknown (U)		column(s).				Leave blank if no Lead Service Line was replaced.			
							(ONL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4337 WISCONSIN AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					103896
4208 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103897
7114 41ST STREET 4231 WENONAH AVENUE	N/A N/A	N N	N N	1976 1955	1976 1955		U	U	U	U			N N					103898 103899
4445 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103901
4145 MAPLE AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103902
3942 RIDGELAND AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					103903
4424 KENILWORTH AVENUE	N/A	N	N 	1946	1946		U	U	U	U			N					103904
4042 GROVE AVENUE 4228 SCOVILLE AVENUE	N/A N/A	N N	N N	1924 1910	1924 1910		U	U	U	U			N N					103907 103910
4312 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					103911
4222 MAPLE AVENUE	N/A	N	N	1931	1931		U	U	U	U			N					103912
4322 MAPLE AVENUE	N/A	N	N	1961	1961		U	U	U	U			N					103913
4031 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					103915
4412 GROVE AVENUE	N/A N/A	N N	N	1954	1954		U	U	U	U			N N					103916
5000 PERSHING ROAD 5000 PERSHING RD	N/A N/A	N N	N N				U	U	U	U			N N					103917 103918
4226 OAK PARK AVENUE	N/A	N	N	1940	1940		U	U	U	U			N					103920
4212 HOME AVENUE	N/A	N	N	1941	1941		U	U	U	U			N					103922
6621 41ST STREET	N/A	N	N	1978	1978		U	U	U	U			N					103923
3929 WESLEY AVENUE	N/A N/A	N	N	1955	1955		U	U	U	U			N N					103925
4139 ELMWOOD AVENUE 3756 CICERO AVENUE	N/A N/A	N N	N N	1964	1964		U	U	U	U			N N					103927 103928
4149 MAPLE AVENUE	N/A	N	N	1950	1950		U	U	U	U			N					103928
7035 40TH STREET	N/A	N	N	1968	1968		U	U	U	U			N					103931
3944 SCOVILLE AVENUE	N/A	N	N	1918	1918		U	U	U	U			N					103932
7019 40TH PLACE	N/A	N	N	1979	1979		U	U	U	U			N					103934
4146 WISCONSIN AVENUE 4312 WISCONSIN AVENUE	N/A N/A	N N	N N	1954 1958	1954 1958		U	U	U	U			N N					103935 103937
4211 MAPLE AVENUE	N/A	N	N	1958	1958		U	U	U	U			N N					103937
4423 CLINTON AVENUE	N/A	N	N	1946	1946		U	U	U	U			N					103940
4322 OAK PARK AVENUE	N/A	N	N	1951	1951		U	U	U	U			N					103941
3924 GROVE AVENUE	N/A	N	N	1919	1919		U	U	U	U			N					103944
4116 WISCONSIN AVENUE	N/A	N	N N	1924	1924		U	U	U	U			N N					103946
4411 KENILWORTH AVENUE 4449 HOME AVENUE	N/A N/A	N N	N N	1946 1955	1946 1955		U	U	U	U			N N					103947 103948

	T			1			Lead Ser	vice Line Inve	ntory Temp	late	ı				1			
*Please enter information in the empty box next to each section	Water	System Na	me		Stickne	<u> </u>	System	ID Number:		13000	Current Inve	ntory Date:		/2025				
*Please enter totals in the empty box next to each category	t Total Servic	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Gal Requiring re		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	y.hub.arcgis.com/	
												•		·				
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
		Constant					Solder (C) Copper - Lead Solde	(C)	Solder (C) Copper - Lead Solde	r Galvanized Requiring	If any galvanized service line material was ever				Copper - No Lead Solder (C)			
	Lead and Copper Sample	Group Homes, Parks, Playgrounds Special Care	i,				(CLS)	Copper - Lead Solder (CLS	(CLS)	Replacemnt (GRR)	downstream of a Lead section, mark Yes (Y). If the galvanized service line	Enter date					IF customer refused access to property,	
	site number is the 7 digit number starting with "LP"	Facilities, Hospitals Clinics, Child Care	5,	What year was the	What year was the	How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never downstream of any Lead	customer was		If previous column was marked (Y), provide date	Galvanized (G)		date waiver obtained by PWS or date PWS	
	or " LA". / If address is not a lead and	Facilities	Yes (Y) or No (N)	PWS-Owned service line	customer side service line	Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	section, mark No (N). / If Yes, that section of	notified of Lead Service Line. /	Yes (Y) or No (N)	the Lead Service Line was replaced. /	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"			installed, if known :	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	r Lead (L)	Lead (L)		service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite		Leave blank if	
							Plastic - PVC, HDPE PEX (P)	, Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron of Transite (O)		Requiring Replacement in the appropriate				(6)		customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (I	Plastic - PVC, HDPE PEX (P)		immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown (U)	Unknown (U) Unknown Not Lead		.,				Service Line was replaced.			
3920 WESLEY AVENUE	N/A	N	N	1922	1922		U	Unknown Not Lead (UNL	(UNL)	11			N					103949
4027 EAST AVENUE	N/A	N	N N	1960	1960		U	U	U	U			N					103949
7013 43RD STREET	N/A	N	N	1954	1954		U	U	U	U			N					103951
3901 HARLEM AVENUE	N/A N/A	N N	N N	4025	4035		U	U	U	U			N N					103952 103953
7125 40TH STREET 6921 PERSHING ROAD	N/A N/A	N	N N	1925	1925		U	U	U	U			N					103954
6925 PERSHING ROAD	N/A	N	N				U	U	U	U			N					103955
4126 HOME AVENUE	N/A	N	N	1932	1932		U	U	U	U			N					103957
4131 CLINTON AVENUE 4436 KENILWORTH AVENUE	N/A N/A	N N	N N	1950 1955	1950 1955		U	U	U	U			N N					103959 103964
3940 SCOVILLE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103965
3935 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					103966
4024 WESLEY AVENUE 4142 GROVE AVENUE	N/A N/A	N N	N	1957	1957	Visual Inspection	U	U	С	U			N N					103968
4311 KENILWORTH AVENUE	N/A	N N	N N	1927 1966	1927 1966	Visual Inspection	U	U	C	U			N N					103969 103971
3936 WESLEY AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					103972
4244 CLINTON AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103973
6524 41ST STREET 4012 GROVE AVENUE	N/A N/A	N N	N N	1925 1953	1925 1953		U	U	U	U			N N					103976 103978
7011 40TH STREET	N/A	N	N	1981	1981		U	U	U	U			N					103984
4423 KENILWORTH AVENUE	N/A	N	N	1946	1946		U	U	U	U			N					103985
4140 S WISCONSIN AVENUE 6911 43RD STREET	N/A N/A	N N	N N	1951 1958	1951 1958		U	U	U	U			N N					103986 103987
7106 40TH PLACE	N/A N/A	N	N N	1958	1958		U	U	U	U			N					103987
4013 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					103990
4406 WISCONSIN AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					103991
7044 40TH STREET 4128 RIDGELAND AVENUE	N/A N/A	N N	N N	1947 1955	1947 1955		U	U	U	U			N N					103992 103993
4124 WENONAH AVENUE	N/A	N	N	1951	1951		Ü	U	U	U			N					103994
4001 CLINTON AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					103995
4225 SCOVILLE AVENUE 4134 HOME AVENUE	N/A N/A	N N	N N	1965	1965		U	U	U	U			N N					103998 103999
4134 HOME AVENUE 4028 ELMWOOD AVENUE	N/A N/A	N N	N N	1953 1953	1953 1953		U	U	U	U			N N					103999
4316 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U			N					104001
7005 40TH PLACE	N/A	N	N	1961	1961		U	U	U	U			N					104002
4222 GROVE AVENUE	N/A	N	N	1931	1931	1	U	U	U	U	<u> </u>	1	N	1			1	104004

							Lead Sen	vice Line Inver	ntory Temp	lato								
*Please enter information in the empty	W/ator	System Na	me		Stickne	2V		ID Number:		13000	Current Inver	ntory Date:	4/15,	/2025				
box next to each section	vvater	System Na	T		I	= y 	System	Total Galv		13000 T	Total	ltory Date.	Website link					
*Please enter totals in the empty box next to each category	Total Service	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Requiring rep		0	Unknown:	1722		ntory:	https://lead-service	e-line-inventory-1-novotny	/.hub.arcgis.com/	
						•												
Service Address	Lead and Copper Sample site number.	: Is this a high-risk Facility or Area?		Year PWS- Owned Service t Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Lead (L)	If any galvanized service line material was ever				EXAMPLES: Copper - No Lead Solder (C)			
	Lead and Copper Sample	Group Homes, Parks, Playgrounds Special Care	5,				Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	(CLS)	r Galvanized Requiring Replacemnt (GRR)	downstream of a Lead section, mark Yes (Y). If the galvanized service line	Enter date		lf and in a selection			IF customer refused access to property,	
	site number is the 7 digit number starting with "LP"	Facilities, Hospitals Clinics, Child Care Facilities		What year was the PWS-Owned	What year was the customer side	How was the Material of this Service Line Identified? EXAMPLES: Construction	Galvanized (G)	Galvanized (G) Galvanized Requiring	Galvanized (G) Galvanized	Unknown (U)	material was never downstream of any Lead section, mark No (N).	customer was notified of Lead		If previous column was marked (Y), provide date the Lead Service Line was	Galvanized (G)		date waiver obtained by PWS or date PWS notified IDPH of	
	or " LA". / If address is not a lead and copper sample site mark	racilities	Yes (Y) or No (N)	service line	service line 'installed, if known	Records, Visual Inspections, Survey Response, Maintenance Records, etc	Lead (L) Cast/Ductile Iron or	Replacemnt (GRR)	Requiring Replacemnt (GRR)	Non-Lead (NL)	/ If Yes, that section of service line should be	Service Line. / If Service Line is not	Yes (Y) or No (N)	replaced. / Leave blank if previous	Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite	Yes (Y) or No (N)	refusal to sign waiver. / Leave blank if	
	"N/A"					maintenance necorally etcin	Transite (O) Plastic - PVC, HDPE, PEX (P)	Lead (L) Cast/Ductile Iron or Transite (O)	Lead (L) Cast/Ductile Iron or Transite (O)		marked as Galvanized Requiring Replacement in the appropriate	Lead put N/R		column was (N).	(O)		customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (P	Plastic - PVC, HDPE, PEX (P) Unknown (U)		immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
3924 EAST AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					104007
3939 SCOVILLE AVENUE	N/A	N	N	1971	1971		U	U	U	U			N					104008
4218 CLINTON AVENUE 4331 GROVE AVENUE	N/A N/A	N N	N N	1954 1946	1954 1946		U	U	U	U			N N					104009 104011
4025 EUCLID AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					104011
4206 ELMWOOD AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					104016
4023 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					104018
4246 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					104019
4020 GUNDERSON AVENUE 4224 OAK PARK AVENUE	N/A N/A	N N	N N	1919 1934	1919 1934		U	U	U	U			N N					104021 104023
4017 CLINTON AVENUE	N/A	N	N	1934	1934		U	U	U	U			N N					104025
3927 CLARENCE AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					104026
3925 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U			N					104027
7111 40TH STREET	N/A	N	N	1925	1925		U	U	U	U			N					104029
4036 GROVE AVENUE	N/A	N	N	1930	1930		U	U	U	U			N					104031
4141 GROVE AVENUE 4220 HOME AVENUE	N/A N/A	N N	N N	1930 1925	1930 1925		U	U	U	U			N N					104032 104033
3916 CLARENCE AVENUE	N/A N/A	N	N	1923	1923		U	U	U	U			N					104035
4325 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					104038
3800 CICERO AVENUE	N/A	N	N	2023	2023		U	U	U	U			N					104040
7021 40TH STREET	N/A	N	N	1919	1919		U	U	U	U			N					104041
4008 GROVE AVENUE 4115 MAPLE AVENUE	N/A N/A	N N	N N	1934 1925	1934 1925		U	U	U	U			N N					104042 104043
4244 GUNDERSON AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					104044
7040 40TH PLACE	N/A	N	N	1984	1984		U	U	U	U			N					104048
3929 EAST AVENUE	N/A	N	N	1925	1925		U	U	U	U			N					104049
3939 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					104050
4139 SCOVILLE AVENUE 3916 WESLEY AVENUE	N/A N/A	N N	N N	1939 1925	1939 1925		U	U	U	U			N N					104051 104052
4034 OAK PARK AVENUE	N/A	N	N	1925	1925		U	U	U	U			N					104052
4126 RIDGELAND AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					104057
4425 HOME AVENUE	N/A	N	N	1928	1928		U	U	U	U			N					104061
4242 GROVE AVENUE	N/A	N	N	1923	1923		U	U	U	U			N					104062
3922 CLINTON AVENUE	N/A	N	N N	1957	1957		U	U	U	U			N					104063
3934 GUNDERSON AVENUE 4026 CLARENCE AVENUE	N/A N/A	N N	N N	1959 1953	1959 1953		U	U	U	U			N N					104064 104065
4020 CLAKENCE AVENUE	N/A	I N	I N	1953	1923	<u> </u>	l 0		l 0	l 0			I N	<u> </u>	[1	104065

							Lead Sen	vice Line Inver	ntory Temp	late								
*Please enter information in the empty	\M/ator	System Nai	mo		Stickne					13000	Current Inven	story Data:	4/15,	/2025				
box next to each section	vvater	System Nai	T		JUCKIN	:y T	System	ID Number:		13000 T	Current Inver	itory Date.						
*Please enter totals in the empty box next to each category	Total Service	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722	Website link Inver	c to Material ntory:	https://lead-service	e-line-inventory-1-novotn	/.hub.arcgis.com/	
								1							•			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?		Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service							
		Group Homes,					Copper - Lead Solder	Copper - Lead Solder (CLS)	Copper - Lead Solde	Galvanized Requiring	line material was ever downstream of a Lead				Copper - No Lead Solder (C)			
	Lead and Copper Sample	Parks, Playgrounds Special Care	i,				(CLS)		(CLS)	Replacemnt (GRR)	section, mark Yes (Y). If the galvanized service line	Enter date		If previous column was			IF customer refused access to property,	
	site number is the 7 digit number starting with "LP"	Facilities, Hospitals Clinics, Child Care	;,	What year was the		How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G) Galvanized	Unknown (U)	material was never downstream of any Lead	customer was notified of Lead		marked (Y), provide date the Lead Service Line was	Galvanized (G)		date waiver obtained by PWS or date PWS	
	or " LA". / If address is not a lead and	Facilities	Yes (Y) or No (N)	PWS-Owned service line	customer side service line	Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Requiring Replacemnt (GRR)	Non-Lead (NL)	section, mark No (N). /	Service Line.	Yes (Y) or No (N)	replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		If Yes, that section of service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite		Leave blank if	
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in the appropriate	,			(0)		customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown (U) Unknown Not Lead (UNL)	Unknown (U) Unknown Not Lead						Service Line was replaced.			
3738 CICERO AVENUE	N/A	N	N				U	U	(UNL) U	U			N					104068
6419 41ST STREET	N/A	N	N	1953	1953		U	U	U	U			N					104072
4128 WISCONSIN AVENUE 4004 RIDGELAND AVENUE	N/A N/A	N N	N N	1952 1954	1952 1954		U	U	U	U			N N					104073 104074
4124 GROVE AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					104074
4217 WENONAH AVENUE	N/A	N N	N N	1986	1986		U	U	U	U			N N					104077
4008 GUNDERSON AVENUE 3938 ELMWOOD AVENUE	N/A N/A	N N	N N	1958 1957	1958 1957		U	U	U	U			N N					104078 104079
4215 GUNDERSON AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					104080
7104 40TH PLACE 4400 KENILWORTH AVENUE	N/A N/A	N N	N N	1951 1954	1951 1954		U	U U	U	U			N N					104082 104083
4415 KENILWORTH AVENUE	N/A	N	N	1946	1946		U	U	U	U			N					104085
3940 GROVE AVENUE	N/A	N	N	1938	1938		U	U	U	U			N 					104086
7013 40TH STREET 4221 SCOVILLE AVENUE	N/A N/A	N N	N N	1983 1957	1983 1957		U	U	U	U			N N					104087 104088
4024 RIDGELAND AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					104089
6827 PERSHING ROAD 4136 GUNDERSON AVENUE	N/A N/A	N N	N N	1955	1955		U	U	U U	U			N N					104090 104091
4009 CLARENCE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					104093
4006 SCOVILLE AVENUE 4015 CLARENCE AVENUE	N/A N/A	N N	N N	1921 1958	1921 1958		U	U	U	U			N N					104094 104095
4015 CLARENCE AVENUE 4032 GROVE AVENUE	N/A N/A	N N	N N	1958	1958		U	U	U	U			N N					104095
4216 RIDGELAND AVENUE	N/A	N	N	1964	1964		U	U	U	U			N					104099
4340 WENONAH AVENUE 4202 GUNDERSON AVENUE	N/A N/A	N N	N N	1954 1955	1954 1955		U	U	U	U			N N					104100 104102
7130 43RD STREET	N/A	N	N	1960	1960		U	U	U	U			N					104103
4000 CLINTON AVENUE 4235 WENONAH AVENUE	N/A N/A	N N	N N	1951 1954	1951 1954		U	U	U	U			N N					104104 104105
4235 WENONAH AVENUE 4415 HOME AVENUE	N/A N/A	N N	N N	1954 1956	1954 1956		U	U	U	U			N N					104105
4230 RIDGELAND AVENUE	N/A	N	N	1949	1949		U	U	U	U			N					104109
3924 CLARENCE AVENUE 4120 WENONAH AVENUE	N/A N/A	N N	N N	1959 1953	1959 1953		U	U U	U	U			N N					104110 104111
7033 W 40TH STREET	N/A	N	N	1927	1927		U	U	U	U			N					104111
7027 40TH STREET	N/A	N	N	1924	1924		U	U	U	U			N					104113
4424 WISCONSIN AVENUE 4201 MAPLE AVENUE	N/A N/A	N N	N N	1954 1956	1954 1956		U	U	U	U			N N					104116 104117

				1			Lead Ser	vice Line Inve	ntory Temp	late								
*Please enter information in the empty box next to each section	Water	System Na	me		Stickne	<u> </u>	System	ID Number:		13000	Current Inve	ntory Date:	·	/2025				
*Please enter totals in the empty box next to each category	t Total Servic	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Gal Requiring re		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	y.hub.arcgis.com/	
			•		•										•			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
							Solder (C)	(C)	Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds	,				Copper - Lead Solde (CLS)	Copper - Lead Solder (CLS	Copper - Lead Solde (CLS)	r Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If				copper - No Lead Solder (c)		IF customer refused	
	Lead and Copper Sample site number is the 7 digit	Special Care Facilities, Hospitals	,			How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		access to property, date waiver obtained	
	number starting with "LP" or " LA". / If address is not a lead and	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line	What year was the customer side service line	Service Line Identified? EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring	Non-Lead (NL)	downstream of any Lead section, mark No (N). /	notified of Lead Service Line.	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron o Transite (O)	r Lead (L)	Replacemnt (GRR)		If Yes, that section of service line should be marked as Galvanized	/ If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if	
							Plastic - PVC, HDPE PEX (P)	, Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron of Transite (O)		Requiring Replacement in the appropriate						customer has not refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (F	Plastic - PVC, HDPE PEX (P)	•	immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.			
							(UNL)	Unknown (U) Unknown Not Lead (UNL	Unknown (U) Unknown Not Lead						service zine was replaced.			
4240 ELMWOOD AVENUE	N/A	N	N	1947	1947		U	OTKTOWN NOT LEAG (ONE,	(UNL)	11			N					104118
3931 EAST AVENUE	N/A	N	N	1975	1975		U	U	U	U			N					104119
4027 EUCLID AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					104120
4227 GROVE AVENUE	N/A	N	N	1937	1937		U	U	U	U			N					104123
4319 MAPLE AVENUE 4228 MAPLE AVENUE	N/A N/A	N N	N N	1960 1955	1960 1955		U	U	U	U			N N					104125 104127
4145 CLINTON AVENUE	N/A	N N	N N	1955	1955		U	U	U	U			N					104127
4401 S HARLEM AVENUE	N/A	N	N				U	U	U	U			N					104130
3915 GUNDERSON AVENUE	N/A	N	N	1925	1925		U	U	U	U			N					104132
7136 41ST STREET	N/A	N	N	1915	1915		U	U	U	U			N					104133
4004 CLINTON AVENUE	N/A N/A	N N	N N	1930 1924	1930		U	U	U	U			N N					104135
4013 GUNDERSON AVENUE 6509 PERSHING ROAD	N/A N/A	N N	N N	1924	1924		II	U	U II	U			N N					104137 104139
6511 PERSHING ROAD	N/A	N	N				U	U	U	U			N					104140
4001 GUNDERSON AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					104141
4032 GUNDERSON AVENUE	N/A	N	N	1925	1925		U	U	U	U			N					104144
7126 W 41ST STREET	N/A	N	N N	1915	1915		U	U	U	U			N					104145
4328 WISCONSIN AVENUE 4225 S WISCONSIN AVENUE	N/A N/A	N N	N N	1959 1955	1959 1955		U	U	U	U			N N					104146 104147
6408 41ST STREET	N/A	N	N	1955	1955		U	U	U	U			N					104148
4129 GUNDERSON AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					104149
3944 ELMWOOD AVENUE	N/A	N	N	1949	1949		U	U	U	U			N					104150
3932 CLARENCE AVENUE	N/A	N	N N	1954	1954		U	U	U	U			N N					104152
7039 43RD STREET 6416 41ST STREET	N/A N/A	N N	N N	1955 1955	1955 1955		U	U	U	U			N N					104153 104155
7012 40TH STREET	N/A	N	N	1948	1948		U	U	U	U			N					104156
4309 MAPLE AVENUE	N/A	N	N	1959	1959		U	U	U	U			N					104157
4342 WENONAH AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					104158
3931 CLINTON AVENUE	N/A N/A	N N	N N	1952	1952		U	U	U	U			N N					104159
4117 MAPLE AVENUE 4441 WISCONSIN AVENUE	N/A N/A	N N	N N	1925 1953	1925 1953		U	U	U	U			N N					104161 104162
4414 WENONAH AVENUE	N/A	N	N	1956	1956	Visual Inspection	U	U	С	U			N					104163
4330 GROVE AVENUE	N/A	N	N	1946	1946	·	U	U	U	U			N					104164
4313 WISCONSIN AVENUE	N/A	N	N	1927	1927		U	U	U	U			N					104166
4302 MAPLE AVENUE	N/A	N	N N	1960	1960		U	U	U	U			N					104167
7020 43RD STREET	N/A	N	N	1970	1970]	U	U	U	U	<u> </u>	<u> </u>	N					104168

							Load Sor	vice Line Inver	tory Tomp	lato								
*Please enter information in the empty				1				vice Line Inver										
box next to each section	Water	System Nar	me 		Stickne	ey	System	ID Number:		13000	Current Inver	ntory Date:	4/15	/2025				
*Please enter totals in the empty box next to each category	Total Servic	e lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES: Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES: Lead (L)					EXAMPLES:			
		Group Homes,					Solder (C) Copper - Lead Solde	(C)	Solder (C) Copper - Lead Solde	Galvanized Requiring	If any galvanized service line material was ever				Copper - No Lead Solder (C)			
	Lead and Copper Sample	Parks, Playgrounds, Special Care	,				(CLS)	Copper - Lead Solder (CLS	(CLS)	Replacemnt (GRR)	downstream of a Lead section, mark Yes (Y). If the galvanized service line	Enter date		If previous column was			IF customer refused access to property,	
	site number is the 7 digit number starting with "LP"	Facilities, Hospitals, Clinics, Child Care	,	What year was the		How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G) Galvanized	Unknown (U)	material was never downstream of any Lead	customer was notified of Lead		marked (Y), provide date the Lead Service Line was	Galvanized (G)		by PWS or date PWS	
	or " LA". / If address is not a lead and copper sample site mark	Facilities	Yes (Y) or No (N)	PWS-Owned service line installed, if known?	customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey Response,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Requiring Replacemnt (GRR)	Non-Lead (NL)	section, mark No (N). / If Yes, that section of	Service Line. / If Service Line is not	Yes (Y) or No (N)	replaced. / Leave blank if previous	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	notified IDPH of refusal to sign waiver. /	
	"N/A"					Maintenance Records, etc	Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE,	Lead (L) Cast/Ductile Iron or	Lead (L) Cast/Ductile Iron or		service line should be marked as Galvanized Requiring Replacement in	Lead put N/R		column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
							PEX (P) Unknown (U)	Transite (O) Plastic - PVC, HDPE, PEX (P	Transite (O) Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no Lead		refused access.	
		Yes (Y) or No (N)					Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)		column(s).				Service Line was replaced.			
								Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4123 SCOVILLE AVENUE	N/A	N 	N	1955	1955		U	U	U	U			N					104169
4305 HARLEM AVENUE 3932 SCOVILLE AVENUE	N/A N/A	N N	N N	1956	1956		U	U	U	U			N N					104170 104171
4115 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					104172
7030 41ST STREET	N/A	N	N	1933	1933		U	U	U	U			N					104173
3919 OAK PARK AVENUE 3915 OAK PARK AVENUE	N/A N/A	N N	N N	1960 1958	1960 1958		U	U	U	U			N N					104174 104175
4420 WISCONSIN AVENUE	N/A N/A	N N	N	1956	1956		U	U	U	U			N					104175
4224 MAPLE AVENUE	N/A	N	N	1980	1980		U	U	U	U			N					104177
7017 43RD STREET	N/A	N	N	1954	1954		U	U	U	U			N					104179
3919 HOME AVENUE 4210 S RIDGELAND AVENUE	N/A N/A	N N	N N	1950 1958	1950 1958		U	U	U	U			N N					104180 104181
4004 ELMWOOD AVENUE	N/A	N N	N	1938	1925		U	U	U	U			N					104181
4232 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					104184
4214 S MAPLE AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					104185
3934 OAK PARK AVENUE 4975 PERSHING ROAD	N/A N/A	N N	N N	1924	1924		U	U	U	U			N N					104186 104187
4330 CLINTON AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					104190
3927 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					104191
4112 HOME AVENUE 4300 WISCONSIN AVENUE	N/A N/A	N N	N N	1960 1958	1960 1958		U	U	U	U			N N					104193 104194
4300 WISCONSIN AVENUE 4230 WENONAH AVENUE	N/A N/A	N N	N N	1958	1958 1954		U	U	U	U			N N					104194
4408 KENILWORTH AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					104196
4422 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					104197
4323 CLINTON AVENUE 4224 WENONAH AVENUE	N/A N/A	N N	N N	1953 1954	1953 1954		U	U	U	U			N N					104198 104199
3945 WESLEY AVENUE	N/A	N	N	1929	1934		U	U	U	U			N					104199
4141 WISCONSIN AVENUE	N/A	N	N	1973	1973		U	U	U	U			N					104202
4009 EUCLID AVENUE	N/A	N 	N	1958	1958		U	U	U	U			N					104203
6704 41ST STREET 4012 WESLEY AVENUE	N/A N/A	N N	N N	1955 1955	1955 1955		U	U	U	U			N N					104204 104206
3934 EUCLID AVENUE	N/A	N	N	1947	1947		U	U	U	U			N					104207
4303 MAPLE AVENUE	N/A	N	N	1959	1959		U	U	U	U			N					104210
6604 41ST STREET	N/A	N N	N N	1955	1955		U	U	U	U			N N					104211
7024 40TH STREET 4315 WENONAH AVENUE	N/A N/A	N N	N N	1947 1952	1947 1952		U	U	U	U			N N					104212 104213

							Lead Ser	vice Line Inver	ntory Temp	late								
*Please enter information in the empty box next to each section	Water	System Na	me		Stickne	ey .		ID Number:		13000	Current Inver	ntory Date:	4/15	/2025				
*Please enter totals in the empty box next to each category	Total Servic	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	y.hub.arcgis.com/	
		_																
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Lead (L)					EXAMPLES:			
		Group Homes, Parks, Playgrounds	5,				Copper - Lead Solde (CLS)	r Copper - Lead Solder (CLS	Copper - Lead Solde (CLS)	r Galvanized Requiring Replacemnt (GRR)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If				Copper - No Lead Solder (C)		IF customer refused	
	Lead and Copper Sample site number is the 7 digit	Special Care Facilities, Hospitals	5,	What year was the	What year was the	How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date customer was		If previous column was marked (Y), provide date	Galvanized (G)		access to property, date waiver obtained by PWS or date PWS	
	number starting with "LP" or " LA". / If address is not a lead and	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line installed, if known?	customer side service line	EXAMPLES: Construction Records, Visual Inspections, Survey Response,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. /	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"		_			Maintenance Records, etc	Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE	Lead (L) Cast/Ductile Iron or	Lead (L) Cast/Ductile Iron or		service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
							PEX (P) Unknown (U)	Transite (O) Plastic - PVC, HDPE, PEX (P	Transite (O) Plastic - PVC, HDPE, PEX (P)		Requiring Replacement in the appropriate immediately preceding				Leave blank if no Lead		refused access.	
		Yes (Y) or No (N)					Unknown Not Lead (UNL)	Unknown (U)	Unknown (U) Unknown Not Lead		column(s).				Service Line was replaced.			
44404440154145				4027	4007			Unknown Not Lead (UNL)	(UNL)									404047
4410 MAPLE AVENUE 4003 CLINTON AVENUE	N/A N/A	N N	N N	1937 1949	1937 1949		U	U	U	U			N N					104217 104219
7100 40TH PLACE	N/A	N	N	1986	1986		U	U	U	U			N					104220
4036 CLARENCE AVENUE	N/A	N	N	1927	1927		U	U	U	U			N					104221
3921 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					104222
3925 EUCLID AVENUE 3920 CLARENCE AVENUE	N/A N/A	N N	N N	1929 1952	1929 1952		U	U	U	U			N N					104226 104227
3946 EUCLID AVENUE	N/A	N	N	1922	1922		U	U	U	U			N					104227
3938 GROVE AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					104229
4044 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					104231
7000 41ST STREET	N/A	N	N	1956	1956		U	U	U	U			N					104232
4243 SCOVILLE AVENUE 4221 CLINTON AVENUE	N/A N/A	N N	N N	1953 1954	1953 1954		U	U	U	U			N N					104233 104234
7130 41ST STREET	N/A	N	N	1913	1913		U	U	U	U			N					104235
6626 41ST STREET	N/A	N	N	1953	1953		U	U	U	U			N					104236
3911 CLARENCE AVENUE	N/A	N	N	1926	1926		U	U	U	U			N					104238
4438 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U			N					104240
3923 WESLEY AVENUE 7112 40TH STREET	N/A N/A	N N	N N	1957 1947	1957 1947		U	U	U	U			N N					104241 104242
4405 CLINTON AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					104242
4126 GROVE AVENUE	LP1A023	N	N	1987	1987		U	U	U	U			N					104246
4124 HOME AVENUE	N/A	N	N	1930	1930		U	U	U	U			N					104247
4108 GROVE AVENUE	N/A	N	N	1928	1928		U	U	U	U			N N					104248
6645 PERSHING ROAD 3913 EUCLID AVENUE	N/A N/A	N N	N N	1937	1937		U	U	U	U			N N					104249 104250
4202 MAPLE AVENUE	N/A	N	N	1925	1925		U	U	U	U			N					104251
3935 S CLARENCE AVENUE	N/A	N	N	1920	1920		U	U	U	U			N					104252
3937 WESLEY AVENUE	N/A	N	N	1957	1957		U	U	U	U			N					104253
4039 GUNDERSON AVENUE	N/A	N	N	1953	1953		U	U	U	U			N N					104256
4325 KENILWORTH AVENUE 4138 WISCONSIN AVENUE	N/A N/A	N N	N N	1950 1953	1950 1953		U	U	U	U			N N					104257 104258
4331 KENILWORTH AVENUE	N/A N/A	N	N	1953	1953		U	U	U	U			N					104258
4234 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					104261
4127 GROVE AVENUE	N/A	N	N	1930	1930		U	U	U	U			N					104262
6629 PERSHING ROAD	N/A	N	N				U	U	U	U			N					104263
6627 PERSHING ROAD	N/A	N	N				U	U	U	U			N					104264

	T						Lead Ser	vice Line Inve	ntory Temp T	late								
*Please enter information in the empty box next to each section	Water	System Na	me		Stickne	ey .	System	ID Number:		13000	Current Inve	ntory Date:	·	/2025				
*Please enter totals in the empty box next to each category	t Total Servic	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Gal Requiring re		0	Total Unknown:	1722		k to Material ntory:	https://lead-service	e-line-inventory-1-novotny	y.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					Copper - No Lead	Copper - No Lead Solder	EXAMPLES: Copper - No Lead	EXAMPLES:					EXAMPLES:			
		Group Homes,					Solder (C) Copper - Lead Solde	(C) Copper - Lead Solder (CLS	Solder (C) Copper - Lead Solde	r Galvanized Requiring	If any galvanized service line material was ever downstream of a Lead				Copper - No Lead Solder (C)			
	Lead and Copper Sample site number is the 7 digit	Parks, Playgrounds Special Care Facilities, Hospitals	,			How was the Material of this	(CLS) Galvanized (G)	Galvanized (G)	(CLS) Galvanized (G)	Replacemnt (GRR) Unknown (U)	section, mark Yes (Y). If the galvanized service line material was never	Enter date customer was		If previous column was	Galvanized (G)		IF customer refused access to property, date waiver obtained	
	number starting with "LP" or " LA". /	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line	What year was the customer side service line	Service Line Identified? EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring	Non-Lead (NL)	downstream of any Lead section, mark No (N). /	notified of Lead Service Line.	Yes (Y) or No (N)	marked (Y), provide date the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver.	
	If address is not a lead and copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron of Transite (O)	r Lead (L)	Replacemnt (GRR)		If Yes, that section of service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		/ Leave blank if customer has not	
							Plastic - PVC, HDPE PEX (P) Unknown (U)	, Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (I	Cast/Ductile Iron of Transite (O) Plastic - PVC, HDPE PEX (P)		Requiring Replacement in the appropriate immediately preceding				Leave blank if no Lead		refused access.	
		Yes (Y) or No (N)					Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)		column(s).				Service Line was replaced.			
								Unknown Not Lead (UNL	Unknown Not Lead (UNL)									
4227 MAPLE AVENUE 4445 WENONAH AVENUE	N/A N/A	N N	N N	1935 1953	1935 1953		U	U	U	U			N N					104265 104266
3924 GUNDERSON AVENUE	N/A N/A	N N	N N	1953	1953		U	U	U	U			N N					104266
7114 43RD STREET	N/A	N	N	1928	1928		U	U	U	U			N					104268
4416 OAK PARK AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					104269
4203 GROVE AVENUE 7028 40TH STREET	N/A N/A	N N	N N	1927 1947	1927 1947		U	U	U	U			N N					104270 104271
3919 CLARENCE AVENUE	N/A	N N	N N	1947	1947		U	U	U	U			N					104271
4325 WISCONSIN AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					104273
3931 SCOVILLE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					104274
4109 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					104275
4439 KENILWORTH AVENUE 4212 WENONAH AVENUE	N/A N/A	N N	N N	1946 1953	1946 1953		U	U	U	U			N N					104276 104280
4412 WENONAH AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					104283
4430 OAK PARK AVENUE	N/A	N	N	1950	1950		U	U	U	U			N					104284
3910 EUCLID AVENUE	N/A	N	N N	1961	1961		U	U	U	U			N					104285
4224 ELMWOOD AVENUE 6944 W 40TH STREET	N/A N/A	N N	N N	1959 1924	1959 1924		U	U	U	U			N N					104286 104287
4029 CLINTON AVENUE	N/A	N	N	1946	1946		U	U	U	U			N					104289
3911 EUCLID AVENUE	N/A	N	N	1976	1976		U	U	U	U			N					104290
3915 GROVE AVENUE 3912 EUCLID AVENUE	N/A N/A	N N	N N	1956 1932	1956 1932		U	U	U	U			N N					104291 104292
4228 WENONAH AVENUE	N/A	N	N N	1956	1952		U	U	U	U			N					104293
4317 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U			N					104294
4435 CLINTON AVENUE	N/A	N	N 	1956	1956		U	U	U	U			N					104295
4400 CLINTON AVENUE 4132 GUNDERSON AVENUE	N/A N/A	N N	N N	1956 1928	1956 1928		U	U	U	U			N N					104296 104297
4033 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					104298
4117 WENONAH AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					104299
4321 MAPLE AVENUE	N/A	N	N 	1960	1960		U	U	U	U			N					104300
4100 HOME AVENUE 6413 41ST STREET	N/A N/A	N N	N N	1954 1956	1954 1956		U	U	U	U			N N					104301 104303
4232 CLINTON AVENUE	N/A N/A	N N	N N	1956	1956		U	U	U	U			N N					104305
6525 PERSHING ROAD	N/A	N	N				U	U	U	U			N					104306
4328 MAPLE AVENUE	N/A	N	N	1961	1961		U	U	U	U			N					104307
4028 RIDGELAND AVENUE	N/A	N	N	1955	1955		U	U	U	U	<u> </u>		N				1	104308

							Load Son	vice Line Inver	story Tomp	lato								
*Please enter information in the empty	Mator	Custom No.	m. o		Chinlen						Commont lavor	atami Datai	4/15	/2025				
box next to each section	water	System Na	т	Stickney			System	tem ID Number: IL0313000		13000	Current Inventory Date:		4/15/2025					
*Please enter totals in the empty box next to each category	Total Service	ce lines:	1904	Total Lead:	71	Total Non-Lead:	111	Total Galv Requiring rep		0	Total Unknown:	Total 1722		Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/		
					<u> </u>		<u> </u>	1		l					•			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?		Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service							
		Group Homes, Parks, Playgrounds	5.				Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If				Copper - No Lead Solder (C)		IF customer refused	
	Lead and Copper Sample Spec	d Copper Sample Special Care				How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date customer was		If previous column was	Galvanized (G)		access to property, date waiver obtained	
	number starting with "LP" or " LA".	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned	customer side	Service Line Identified? EXAMPLES: Construction	Lord (L)	Galvanized Requiring	Galvanized	Non-Lead (NL)	downstream of any Lead section, mark No (N).	notified of Lead Service Line.	Yes (Y) or No (N)	marked (Y), provide date the Lead Service Line was replaced.	Plactic - DVC HDDE DEV /DV	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of	
	If address is not a lead and copper sample site mark		Tes (1) OF NO (N)	service line installed, if known?	service line installed, if known	Records, Visual Inspections, Survey Response,	Lead (L)	Replacemnt (GRR)	Requiring Replacemnt (GRR)	Non-Lead (NL)	If Yes, that section of	/ If Service Line is not	163 (1) 01 140 (14)	/ Leave blank if previous	Plastic - PVC, HDPE, PEX (P)		refusal to sign waiver. /	
	"N/A"		-			Maintenance Records, etc	Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE,	Lead (L) Cast/Ductile Iron or	Lead (L) Cast/Ductile Iron or		service line should be marked as Galvanized Requiring Replacement in	Lead put N/R		column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
							PEX (P) Unknown (U)	Transite (O) Plastic - PVC, HDPE, PEX (P	Transite (O) Plastic - PVC, HDPE,		the appropriate immediately preceding				Leave blank if no Lead		refused access.	
		Yes (Y) or No (N)					Unknown Not Lead (UNL)	Unknown (U)	PEX (P) Unknown (U)		column(s).				Service Line was replaced.			
								Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4020 CLINTON AVENUE 4401 KENILWORTH AVENUE.	N/A N/A	N N	N N	1957 1957	1957 1957		U	U	U U	U			N N					104309 104310
4243 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					104312
6900 43RD STREET	N/A	N	N	1932	1932		U	U	U	U			N					104313
4433 GROVE AVENUE 6719 PERSHING ROAD	N/A N/A	N N	N N	1945	1945		U	U	U	U			N N					104314 104315
3916 GROVE AVENUE	N/A	N	N	1944	1944		U	U	U	U			N					104316
4019 1/2 EAST AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					104317
3938 GUNDERSON AVENUE 4224 GUNDERSON AVENUE	N/A N/A	N N	N N	1956 1967	1956 1967		U	U	U	U			N N					104318 104320
4036 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					104321
3927 GUNDERSON AVENUE	N/A	N	N	1923	1923		U	U	U	U			N					104322
6515 PERSHING ROAD 4241 ELMWOOD AVENUE	N/A N/A	Y N	N N	1970	1970		U	U	U	U			N N					104323 104326
4335 KENILWORTH AVENUE	N/A	N	N	1970	1970		U	U	U	U			N					104328
4011 SCOVILLE AVENUE	N/A	N	N	1931	1931		U	U	U	U			N					104329
3933 GROVE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					104331
3922 WESLEY AVENUE 6811-A PERSHING ROAD	N/A N/A	N N	N N	1931	1931		U	U	U	U			N N					104333 104335
7003 40TH PLACE	N/A	N	N	1953	1953		U	U	U	U			N					104336
4016 ELMWOOD AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					104337
4126 WENONAH AVENUE 6536 41ST STREET	N/A N/A	N N	N N	1952 1955	1952 1955		U	U	U	U			N N					104338 104339
7038 43RD STREET	N/A	N	N	1954	1954		U	U	U	U			N					104342
4204 WISCONSIN AVENUE	N/A	N	N	1930	1930		U	U	U	U			N					104343
3923 GROVE AVENUE 4105 MAPLE AVENUE	N/A N/A	N N	N N	1938 1955	1938 1955		U	U	U	U			N N					104344 104345
4038 GROVE AVENUE	N/A N/A	N	N	1930	1930		U	U	U	U			N N					104345
7007 43RD STREET	N/A	N	N	1954	1954		U	U	U	U			N					104348
6411 41ST STREET	N/A	N	N	1953	1953		U	U	U	U			N					104349
3919 WESLEY AVENUE 4000 ELMWOOD AVENUE	N/A N/A	N N	N N	1953 1928	1953 1928		U	U	U	U			N N					104350 104351
4224 SCOVILLE AVENUE	N/A	N	N	1989	1989		U	U	U	U			N					104352
4122 GUNDERSON AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					104354
4015 HOME AVENUE 4235 GUNDERSON AVENUE	N/A N/A	N N	N N	1954	1954 1953		U	U	U	U			N N					104355 104356
4235 GUNDERSON AVENUE	N/A	N	I N	1953	1953		L U		l u	Ι υ			I N	1			1	104356

	Lead Service Line Inventory Template																	
				T														
*Please enter information in the empty box next to each section	Water	System Na	me		Stickney			System ID Number:		13000	Current Inventory Date:							
*Please enter totals in the empty box next to each category	Total Service lines: 1904 Total Lead: 71 Total Non-Lead:				111	Total Gal Requiring re		0	Total Unknown:	1722	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/					
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					Copper - No Lead	EXAMPLES: Copper - No Lead Solder	Copper - No Lead	EXAMPLES:					EXAMPLES:			
		Group Homes,					Solder (C) Copper - Lead Solde	(C)	Solder (C) Copper - Lead Solde	r Galvanized Requiring Replacemnt (GRR)	If any galvanized service line material was ever downstream of a Lead				Copper - No Lead Solder (C)			
	Lead and Copper Sample site number is the 7 digit	Parks, Playgrounds Special Care Facilities, Hospitals	,			How was the Material of this	(CLS) Galvanized (G)	Galvanized (G)	(CLS) Galvanized (G)	Unknown (U)	section, mark Yes (Y). If the galvanized service line material was never	Enter date customer was notified of Lead Service Line.		If previous column was marked (Y), provide date	Galvanized (G)		IF customer refused access to property, date waiver obtained	1
	number starting with "LP" or " LA". / If address is not a lead and	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line	customer side service line	Service Line Identified? EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). /		Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron of Transite (O) Plastic - PVC, HDPE	Lead (L) Cast/Ductile Iron or	Lead (L) Cast/Ductile Iron or		If Yes, that section of service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
		Voc (V) or No (N)					PEX (P) Unknown (U)	Transite (O) Plastic - PVC, HDPE, PEX (I	Transite (O) Plastic - PVC, HDPE PEX (P)	,	Requiring Replacement in the appropriate immediately preceding				Leave blank if no Lead		refused access.	
	Y	Yes (Y) or No (N)					Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)		column(s).				Service Line was replaced.			
								Unknown Not Lead (UNL	Unknown Not Lead (UNL)									
4145 ELMWOOD AVENUE 6712 41ST STREET	N/A N/A	N N	N N	1958 1919	1958 1919		U	U	U	U			N N					104357 104358
4401 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					104359
3929 GROVE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					104360
7026 41ST STREET	N/A	N	N	1930	1930		U	U	U	U			N					104361
4119 GUNDERSON AVENUE 4018 CLARENCE AVENUE	N/A N/A	N N	N N	1956 1953	1956 1953		U	U	U	U			N N					104362 104363
4034 EAST AVENUE	N/A	N	N	1949	1949		U	U	U	U			N					104364
3931 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					104366
7028 40TH PLACE 4300 MAPLE AVENUE	N/A N/A	N N	N N	1976 1960	1976 1960		U	U	U	U			N N					104367 104368
6718 41ST STREET	N/A N/A	N N	N N	1960	1960		U	U	U	U			N N					104368
4429 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U			N					104372
4202 RIDGELAND AVENUE	N/A	N	N	1915	1915		U	U	U	U			N					104375
4147 GUNDERSON AVENUE 4019 OAK PARK AVENUE	N/A N/A	N N	N N	1957 1935	1957		U	U	U	U			N N					104376 104377
3919 CLINTON AVENUE	N/A	N N	N N	1950	1935 1950		U	U	U	U			N					104377
4104 OAK PARK AVENUE	N/A	N	N	1911	1911		U	U	U	U			N					104381
4123 WENONAH AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					104382
3912 HOME AVENUE 3925 CLARENCE AVENUE	N/A N/A	N N	N N	1948 1960	1948 1960		U	U	U	U			N N					104383 104384
4030 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					104386
4212 GROVE AVENUE	LP1C072	N	N	1953	1953		U	U	U	U			N					104387
7034 41ST STREET	N/A	N	N	1941	1941		U	U	U	U			N					104388
43RD & RIDGELAND 4012 OAK PARK AVENUE	N/A N/A	N N	N N	1928	1928		U	U	U	U			N N					104390 104391
6730 41ST STREET	N/A	N	N	1943	1943		U	U	U	U			N					104392
4130 OAK PARK AVENUE	N/A	N	N	1939	1939		U	U	U	U			N					104393
4001 WESLEY AVENUE	N/A	N	N	1953	1953		U	U	U	U			N N					104395
4219 HOME AVENUE 4001 HOME AVENUE	N/A N/A	N N	N N	1940 1942	1940 1942		U	U	U	U			N N					104396 104397
6501 41ST STREET	N/A	N	N	1955	1955		U	U	U	U			N					104399
7041 40TH STREET	N/A	N	N	1914	1914		U	U	U	U			N					104400
4403 HOME AVENUE	N/A	N N	N N	1927	1927		U	U	U	U			N N					104401
4140 MAPLE AVENUE 4215 WISCONSIN AVENUE	N/A N/A	N N	N N	1925 1955	1925 1955		U	U	U	U			N N					104403 104404

	Lead Service Line Inventory Template																	
	1			T			Lead Ser	vice Line Inve	ntory Temp	late	l							
*Please enter information in the empty box next to each section	Water	System Nai	me		Stickne	2y	System	ID Number:		13000	Current Inventory Date:							
*Please enter totals in the empty box next to each category	t Total Servic	Total Service lines: 1904 Total Lead: 71 Total Non-Lead:		111	Total Gal Requiring re				1722 Website link to Mate Inventory:			https://lead-service-line-inventory-1-novotny.hub.arcgis.com/						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					Copper - No Lead Solder (C)	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Lead (L)					EXAMPLES:			
		Group Homes, Parks, Playgrounds					Copper - Lead Solde		Copper - Lead Solds	r Galvanized Requiring Replacemnt (GRR)	If any galvanized service line material was ever downstream of a Lead				Copper - No Lead Solder (C)		IF customer refused	
	Lead and Copper Sample site number is the 7 digit	Special Care Facilities, Hospitals	,			How was the Material of this	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	section, mark Yes (Y). If the galvanized service line material was never	Enter date		If previous column was marked (Y), provide date	Galvanized (G)		access to property, date waiver obtained	1
	number starting with "LP" or " LA". / If address is not a lead and	Clinics, Child Care Facilities	Yes (Y) or No (N	What year was the PWS-Owned service line	customer side service line	Service Line Identified? EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). /	customer was notified of Lead Service Line.	Yes (Y) or No (N)	the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron of Transite (O)	Lead (L)	Lead (L)		If Yes, that section of service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
			(N)				Plastic - PVC, HDPE PEX (P) Unknown (U)	, Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (F	Cast/Ductile Iron of Transite (O) Plastic - PVC, HDPE		Requiring Replacement in the appropriate immediately preceding				Lancia blank if an Land		refused access.	
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	PEX (P) Unknown (U)		column(s).				Leave blank if no Lead Service Line was replaced.			
								Unknown Not Lead (UNL	Unknown Not Lead (UNL)									
4001 CLARENCE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					104405
4221 MAPLE AVENUE 3925 GROVE AVENUE	N/A N/A	N N	N N	1957 1953	1957 1953		U	U	U	U			N N					104406 104407
3927 ELMWOOD AVENUE	N/A	N	N	1898	1898		U	U	U	U			N					104408
4013 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					104409
4219 WISCONSIN AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					104410
4345 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					104411
4030 ELMWOOD AVENUE 4338 CLINTON AVENUE	LP1C039 N/A	N N	N N	1924 1954	1924 1954		U	U	U	U			N N					104412 104414
4451 KENILWORTH AVENUE	N/A N/A	N N	N N	1954	1954		U	U	U	U			N N					104414
3911 GUNDERSON AVENUE	N/A	N	N	1962	1962	Visual Inspection	U	U	С	U			N					104416
4139 GUNDERSON AVENUE	N/A	N	N	1956	1956	·	U	U	U	U			N					104417
4408 GROVE AVENUE	N/A	N	N	1956	1956		U	U	U	U			N					104419
4231 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					104421
4105 WENONAH AVENUE 4324 WISCONSIN AVENUE	N/A N/A	N N	N N	1954 1959	1954 1959		U	U	U	U			N N					104422 104423
4324 WISCONSIN AVENUE 4221 ELMWOOD AVENUE	N/A N/A	N N	N N	1959	1959		U	U	U	U			N N					104423
4019 GUNDERSON AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					104426
3931 EUCLID AVENUE	N/A	N	N	1925	1925		U	U	U	U			N					104427
3926 CLARENCE AVENUE	N/A	N	N	1914	1914		U	U	U	U			N					104428
6725 PERSHING ROAD 4409 HOME AVENUE	N/A N/A	N N	N N	1954	1954		U	U	U	U			N N					104429 104430
3916 EUCLID AVENUE	N/A N/A	N N	N N	1954	1954		U	U	U	U			N N					104430
3923 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					104432
4036 WESLEY AVENUE	N/A	N	N	1960	1960		U	U	U	U	_		N				_	104433
6726 41ST STREET	N/A	N	N	1953	1953		U	U	U	U			N					104434
4432 KENILWORTH AVENUE	N/A	N N	N N	1947	1947		U	U	U	U			N N					104435
6829 PERSHING ROAD 7012 43RD STREET	N/A N/A	N N	N N	1950	1950		U	U	U	U			N N					104438 104439
4135 ELMWOOD AVENUE	N/A	N	N	1964	1964		U	U	U	U			N					104440
4417 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U			N					104442
7015 40TH PLACE	N/A	N	N	1961	1961		U	U	U	U			N					104444
6409 41ST STREET	N/A	N	N	1953	1953		U	U	U	U			N					104445
4218 ELMWOOD AVENUE	N/A	N N	N N	1953	1953		U	U	U	U			N N					104447
3932 HOME AVENUE 3933 WESLEY AVENUE	N/A N/A	N N	N N	1947 1955	1947 1955		U	U	U	U			N N					104448 104449

				T			Lead Ser	Lead Service Line Inventory Template										
*Please enter information in the empty box next to each section	Water	System Na	me		Stickne	ey .	System	ID Number:		13000	Current Inventory Date:							
*Please enter totals in the empty box next to each category	^t Total Servic	Total Service lines: 1904 Total Lead: 71 Total Non-Lead:				111	Total Gal Requiring re		0	Total Unknown:	1722		k to Material ntory:	https://lead-service				
Service Address	Lead and Copper Sample site number.	: Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Copper - No Lead Solder (C)	EXAMPLES: Lead (L)					EXAMPLES:			
		Group Homes,					Copper - Lead Solde		Copper - Lead Solds	r Galvanized Requiring Replacemnt (GRR)	If any galvanized service line material was ever downstream of a Lead				Copper - No Lead Solder (C)			
	Lead and Copper Sample site number is the 7 digit	Parks, Playgrounds Special Care Facilities, Hospitals	;, ;,			How was the Material of this		Galvanized (G)	Galvanized (G)	Unknown (U)	section, mark Yes (Y). If the galvanized service line material was never	Enter date customer was notified of Lead Service Line.		If previous column was	Galvanized (G)		IF customer refused access to property, date waiver obtained	
or " L If add	number starting with "LP" or " LA". /	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line	customer side service line	Service Line Identified? EXAMPLES: Construction Records, Visual Inspections,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). /		Yes (Y) or No (N)	marked (Y), provide date the Lead Service Line was replaced.	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver.	
	copper sample site mark "N/A"			installed, if known?	installed, if known?	Survey Response, Maintenance Records, etc	Cast/Ductile Iron of Transite (O) Plastic - PVC, HDPE	Lead (L) Cast/Ductile Iron or	Lead (L) Cast/Ductile Iron or		If Yes, that section of service line should be marked as Galvanized	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite (O)		/ Leave blank if customer has not	
		Yes (Y) or No (N)	'N)				PEX (P) Unknown (U)	Transite (O) Plastic - PVC, HDPE, PEX (I	Transite (O) Plastic - PVC, HDPE PEX (P)		Requiring Replacement in the appropriate immediately preceding				Leave blank if no Lead		refused access.	
		res (1) of NO (N)					Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)		column(s).				Service Line was replaced.			
								Unknown Not Lead (UNL	Unknown Not Lead (UNL)								B	
3938 EUCLID AVENUE 4435 KENILWORTH AVENUE	N/A N/A	N N	N N	1931 1946	1931 1946		U	U	U	U			N N					104450 104451
4134 WISCONSIN AVENUE	N/A	N	N N	1953	1953		U	U	U	U			N					104454
7116 40TH STREET	N/A	N	N	1958	1958		U	U	U	U			N					104455
4012 GUNDERSON AVENUE	N/A	N	N	1958	1958		U	U	U	U			N					104456
4448 CLINTON AVENUE 4206 S SCOVILLE AVENUE	N/A N/A	N N	N N	1951 1916	1951 1916		U	U	U	U			N N					104457 104458
4401 GROVE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					104459
4301 S KENILWORTH AVENUE	N/A	N	N	1967	1967		U	U	U	U			N					104460
3944 OAK PARK AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					104461
3916 GUNDERSON AVENUE 7115 40TH PLACE	N/A N/A	N N	N N	1955 1917	1955 1917		U	U	U	U			N N					104464 104465
4117 ELMWOOD AVENUE	N/A	N	N	1955	1955		U	U	U	U			N					104466
4115 WISCONSIN AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					104468
4407 KENILWORTH AVENUE	N/A	N	N	1946	1946		U	U	U	U			N					104471
4015 EAST AVENUE 4137 GUNDERSON AVENUE	N/A N/A	N N	N N	1941 1956	1941 1956		U	U	U	U			N N					104472 104473
3926 EAST AVENUE	N/A	N	N	1968	1956		U	U	U	U			N					104474
4109 HARLEM AVENUE	N/A	N	N				U	U	U	U			N					104476
7123 40TH STREET	N/A	N	N	1966	1966		U	U	U	U			N					104477
4132 CLINTON AVENUE 4228 GUNDERSON AVENUE	N/A N/A	N N	N N	1952 1963	1952 1963		U	U	U	U			N N					104478 104479
4128 S OAK PARK AVENUE	N/A	N	N	1303	1555		U	U	U	U			N					104479
4239 SCOVILLE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					104482
3800 CICERO AVENUE	N/A	N	N	2022	2022		U	U	U	U			N					104484
4220 WISCONSIN AVENUE 4206 OAK PARK AVENUE	N/A N/A	N N	N N	1954 1926	1954 1926		U	U	U	U			N N					104486 104487
4324 MAPLE AVENUE	N/A	N	N	1961	1961		U	U	U	U			N					104488
4005 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U			N					104491
4234 SCOVILLE AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					104492
4132 WISCONSIN AVENUE 4433 HARLEM AVENUE	N/A N/A	N N	N N	1955	1955		U	U	U	U			N N					104493 104494
6625 PERSHING ROAD	N/A	N	N N	1968	1968		U	U	U	U			N					104495
4021 SCOVILLE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					104496
3927 GROVE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					104497
6404 41ST STREET	N/A	N	N	1953	1953		U	U	U	U	<u> </u>	<u> </u>	N		<u> </u>		<u> </u>	104498

	Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section	Water	System Nar	me	Stickney				ID Number:		13000	Current Inver	ntory Date:	4/15/2025						
*Please enter totals in the empty box next to each category Total Service lines: 1904		1904	Total Lead:	71	Total Non-Lead:	111	Total Galvanized Requiring replacement:		0	Total Unknown:	1722	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/					
						•													
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification		PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number	
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:				
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service line material was ever				Copper - No Lead Solder (C)				
	Lead and Copper Sample	Group Homes, Parks, Playgrounds, Special Care	s,				Copper - Lead Solde (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solde (CLS)	r Galvanized Requiring Replacemnt (GRR)	downstream of a Lead section, mark Yes (Y). If the galvanized service line	e Entard-t-	Enter date customer was notified of Lead Service Line. / Service Line is not Lead put N/R				IF customer refused access to property,		
	site number is the 7 digit number starting with "LP"	Facilities, Hospitals, Clinics, Child Care		What year was the	What year was the	How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never downstream of any Lead	customer was		If previous column was marked (Y), provide date	Galvanized (G)	Yes (Y) or No (N)	date waiver obtained by PWS or date PWS		
	or " LA". / If address is not a lead and	Facilities	Yes (Y) or No (N)	PWS-Owned service line installed, if known	customer side service line installed, if known	EXAMPLES: Construction Records, Visual Inspections, Survey Response,	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	section, mark No (N). / If Yes, that section of	Service Line. /		the Lead Service Line was replaced. / Leave blank if previous column was (N).	Plastic - PVC, HDPE, PEX (P)		notified IDPH of refusal to sign waiver.		
	copper sample site mark "N/A"			,		Maintenance Records, etc	Cast/Ductile Iron o Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized				Cast/Ductile Iron or Transite (O)		Leave blank if customer has not		
								Plastic - PVC, HDPE PEX (P)	Transite (O)	Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE,		Requiring Replacement in the appropriate						refused access.	
		Yes (Y) or No (N)					Unknown (U) Unknown Not Lead	Plastic - PVC, HDPE, PEX (P) Unknown (U)	PEX (P) Unknown (U)	<u></u>	immediately preceding column(s).				Leave blank if no Lead Service Line was replaced.				
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead		-								
4312 MAPLE AVENUE	N/A	N	N	1962	1962		U	U	(UNL) U	U			N					104499	
4122 CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U			N					104501	
6817 PERSHING ROAD	N/A	N	N				U	U	U	U			N					104502	
6821 PERSHING ROAD 4203 GUNDERSON AVENUE	N/A N/A	N N	N N				U	U	U	U			N N					104503 104504	
4012 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U			N N					104505	
7035 43RD STREET	N/A	N	N	1955	1955		U	U	U	U			N					104507	
4203 SCOVILLE AVENUE	N/A	N	N	1961	1961		U	U	U	U			N					104508	
4222 GUNDERSON AVENUE	N/A	N	N	1946	1946		U	U	U	U			N					104509	
4325 MAPLE AVENUE 4148 GUNDERSON AVENUE	N/A N/A	N N	N N	1960 1955	1960 1955		U	U	U	U			N N					104510 104511	
4136 GROVE AVENUE	N/A N/A	N	N N	1955	1955		U	U	U	U			N N					104511	
6809-B PERSHING ROAD	N/A	N	N				U	U	U	U			N					104513	
6807 PERSHING ROAD	N/A	N	N				U	U	U	U			N					104514	
6809-C PERSHING ROAD	N/A	N	N				U	U	U	U			N					104515	
6809-A PERSHING ROAD	N/A	N	N				U	U	U	U			N 					104516	
6805 PERSHING ROAD 7018 40TH PLACE	N/A N/A	N N	N N	1953	1953		U	U	U	U			N N					104517 104518	
4016 CLINTON AVENUE	N/A	N	N	1930	1930		U	U	U	U			N					104519	
4314 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U			N					104520	
4310 MAPLE AVENUE	N/A	N	N	1962	1962		U	U	U	U			N					104521	
4127 SCOVILLE AVENUE	N/A	N	N	1922	1922		U	U	U	U			N					104522	
3941 ELMWOOD AVENUE	N/A	N N	N	1953	1953		U	U	U	U			N N					104523	
4013 EUCLID AVENUE 4028 WESLEY AVENUE	N/A N/A	N N	N N	1924 1957	1924 1957		U	U	U	U			N N					104524 104525	
4406 MAPLE AVENUE	N/A	N	N	1937	1988		U	U	U	U			N					104526	
6428 41ST STREET	N/A	N	N	1918	1918		U	U	U	U			N					104527	
4138 MAPLE AVENUE	N/A	N	N	1953	1953		U	U	U	U			N					104528	
4448 KENILWORTH AVENUE	N/A	N	N	1954	1954		U	U	U	U			N					104529	
6431 41ST STREET	N/A	N	N	1953	1953		U	U	U	U			N					104530	
4221 S WISCONSIN AVENUE 4335 HOME AVENUE	N/A N/A	N N	N N	1956 1925	1956 1925		U	U	U	U			N N					104531 104533	